



Aviation Investigation Final Report

Location: DIXON, Illinois Accident Number: CHI82DA310

Date & Time: August 6, 1982, 15:00 Local Registration: N195SB

Aircraft: CESSNA 195A Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT LANDED DOWNWIND ON RUNWAY 26 AND THE AIRCRAFT GROUNDLOOPED DURING THE LANDING ROLL. THE MAIN LANDING GEAR AND LEFT WING TIP WERE DAMAGED DURING THE SWERVE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - TAILWIND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Private	Age:	45,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 27, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	597 hours (Total, all aircraft), 31 hours (Total, this make and model), 545 hours (Pilot In Command, all aircraft), 48 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N195SB
Model/Series:	195A 195A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	7374
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	45 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2419 Hrs	Engine Manufacturer:	JACOBS
ELT:	Installed	Engine Model/Series:	R-755-B2
Registered Owner:	ROBERT L. FINLEY	Rated Power:	350 Horsepower
Operator:	ROBERT L. FINLEY	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 CHI82DA310

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	3 miles
Lowest Ceiling:	Overcast / 2500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	OSHKOSH	Type of Flight Plan Filed:	None
Destination:	DIXON	Type of Clearance:	None
Departure Time:	13:40 Local	Type of Airspace:	

Airport Information

Airport:	DIXON MUNICIPAL 1L6	Runway Surface Type:	Macadam
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	26	IFR Approach:	
Runway Length/Width:	3100 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Page 3 of 4 CHI82DA310

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 6, 1983

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=70486

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CHI82DA310