



Aviation Investigation Final Report

Location: FORT ATKINSON, Wisconsin **Accident Number:** CHI82DA192

Date & Time: May 29, 1982, 17:30 Local **Registration:** N93616

Aircraft: ERCOUPE 415-C Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE SAFETY BOLT ON THE PROPELLER HUB FAILED ALLOWING THE PROPELLER TO SEPARATE FROM THE AIRCRAFT. THE PILOT LANDED IN A PLOWED FIELD.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) PROPELLER SYSTEM/ACCESSORIES, HUB - DISCONNECTED

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

- 2. (F) TERRAIN CONDITION SOFT3. (F) TERRAIN CONDITION OPEN FIELD

Page 2 of 6 CHI82DA192

Factual Information

Pilot Information

Certificate:	Commercial	Age:	60,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	June 17, 1980
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1983 hours (Total, all aircraft), 327 hours (Total, this make and model), 1758 hours (Pilot In Command, all aircraft), 2 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI82DA192

Aircraft and Owner/Operator Information

Aircraft Make:	ERCOUPE	Registration:	N93616
Model/Series:	415-C 415-C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	939
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	134 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2000 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	C-85
Registered Owner:	WILLIAM H. SEYBOLD	Rated Power:	85 Horsepower
Operator:	WILLIAM H. SEYBOLD	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	3 miles
Lowest Ceiling:	Overcast / 1500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	65°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	FORT ATKINSON, WI	Type of Flight Plan Filed:	None
Destination:	FORT ATKINSON, WI	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Page 4 of 6 CHI82DA192

Airport Information

Airport:	SEYBOLD	Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Soft
Runway Used:	0	IFR Approach:	
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	43.000057,-88.800697(est)

Page 5 of 6 CHI82DA192

Administrative Information

Investigator In Charge (IIC):

Additional Participating

Persons:

Original Publish Date: May 29, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=70704

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI82DA192