



Aviation Investigation Final Report

Location: HELENA, Montana Accident Number: DEN82DA179

Date & Time: August 30, 1982, 13:45 Local Registration: CFSPV

Aircraft: BEECH A23-19 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

ACCORDING TO A WITNESS, THE PILOT WAS ATTEMPTING TO LAND ON A DIRT ROAD THAT IS ALSO USED AS A LANDING STRIP. THE AIRCRAFT TOUCHED DOWN APPROXIMATELY 1500 FEET AT THE DOWNHILL END OF THE RUNWAY, BALLOONED BY A WIND GUST AND MOVED TO THE EAST EXTREME OF THE RUNWAY. THE PILOT ADDED POWER AND TOUCHED DOWN AGAIN AND BALLOONED. THE PILOT STATED THAT HE DID NOT HAVE ENOUGH DISTANCE TO STOP BEFORE THE END OF THE RUNWAY. HE APPLIED POWER TO AVOID A DITCH AND LANDED IN A FIELD. THE PILOT ESTIMATED THAT THE WIND WAS FROM 300 DEG AT 8 GUSTING 20 KTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN

Phase of Operation: LANDING - ROLL

Findings

- 1. (F) WEATHER CONDITION CROSSWIND
- 2. (F) WEATHER CONDITION GUSTS
- 3. (C) COMPENSATION FOR WIND CONDITIONS IMPROPER PILOT IN COMMAND
- 4. (C) DISTANCE MISJUDGED PILOT IN COMMAND

5. (C) AIRSPEED - MISJUDGED - PILOT IN COMMAND

6. (C) GO-AROUND - NOT PERFORMED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

Findings

7. (F) TERRAIN CONDITION - DITCH

- 8. (F) TERRAIN CONDITION ROUGH/UNEVEN
- 9. MANEUVER PERFORMED PILOT IN COMMAND

Page 2 of 5 DEN82DA179

Factual Information

Pilot Information

Certificate:	Commercial	Age:	44,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 8, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1825 hours (Total, all aircraft), 953 hours (Total, this make and model), 1825 hours (Pilot In Command, all aircraft), 69 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	CFSPV
Model/Series:	A23-19 A23-19	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	MB74
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	69 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2403 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-320-E2C
Registered Owner:	BEN MASK	Rated Power:	150 Horsepower
Operator:	CLIFF MASK	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN82DA179

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HLN	Distance from Accident Site:	8 Nautical Miles
Observation Time:	18:54 Local	Direction from Accident Site:	140°
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	40 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	69°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	HELENA , MT (HLN)	Type of Flight Plan Filed:	None
Destination:	WILHELM RANCH, MT	Type of Clearance:	None
Departure Time:	13:35 Local	Type of Airspace:	

Airport Information

Airport:	WILHELM RANCH	Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	
Runway Length/Width:	4000 ft / 0 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	46.530456,-112.210441(est)

Page 4 of 5 DEN82DA179

Administrative Information

Investigation Docket:

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 30, 1983

Last Revision Date:
Investigation Class: Class
Note:

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

https://data.ntsb.gov/Docket?ProjectID=71005

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN82DA179