

Aviation Investigation Final Report

Location:	LOS LUMAS, New Me	exico	Accident Number:	FTW82DA309
Date & Time:	August 1, 1982, 16:0	0 Local	Registration:	N36709
Aircraft:	STINSON	10A	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

WHILE LANDING, THE PLANE TOUCHED DOWN IN A CROSSWIND FROM THE RIGHT AT 15 KNOTS. THE PILOT REPORTED THAT THE PLANE WEATHERCOCKED TO THE RIGHT AND WENT INTO A DITCH. REPORTEDLY, THE PILOT WAS UNABLE TO CONTROL THE HEADING OF THE AIRCRAFT IN THE CROSSWIND.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

2. (F) LACK OF FAMILIARITY WITH AIRCRAFT - PILOT IN COMMAND

3. (F) WEATHER CONDITION - CROSSWIND

4. DIRECTIONAL CONTROL - NOT POSSIBLE - PILOT IN COMMAND

5. GROUND LOOP/SWERVE - UNCONTROLLED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL Findings 6. (F) TERRAIN CONDITION - DITCH

Factual Information

Pilot Information

Certificate:	Private	Age:	30.Male
ocrimence.	Thrute	Age.	50,Maic
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 28, 1980
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	170 hours (Total, all aircraft), 3 hours (Total, this make and model), 93 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	STINSON	Registration:	N36709
All Clait Make.	3110300	Registration.	N30709
Model/Series:	10A 10A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	8109
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	FRANKLIN
ELT:	Installed	Engine Model/Series:	90
Registered Owner:	LAWRENCE RYDBERG	Rated Power:	90 Horsepower
Operator:	LAWRENCE RYDBERG	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	85°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ALBUQUERQUE , NM (ABQ)	Type of Flight Plan Filed:	None
Destination:	FLYING L. RANCH, TX (T33)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	MID VALLEY E98	Runway Surface Type:	Macadam
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	
Runway Length/Width:	4400 ft / 0 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	34.810794,-106.729728(est)

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	August 1, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=71487

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.