



Aviation Investigation Final Report

Location: MONTGOMERY, Alabama Incident Number: ATL82IA281

Date & Time: September 15, 1982, 09:20 Local Registration: N220HB

Aircraft: PIPER PA-34-220T Aircraft Damage: Minor

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PILOT STATED THAT A NORMAL RUNUP WAS COMPLETED BEFORE TAKEOFF. DURING THE TAKEOFF ROLL, THE AIRCRAFT ACCELE- RATED THROUGH 75 KNOTS WHEN A LOUD BANG WAS HEARD FROM THE LEFT SIDE. THE TAKEOFF WAS ABORTED AND A ROLLOUT ACCOMPLISHED. EXAMINATION OF THE LEFT ENGINE REVEALED THAT ONE OF THREE LEFT PROPELLER COUNTERWEIGHTS WERE MISSING. EACH COUNTERWEIGHT IS SECURED BY A SINGLE BOLT AND LOCKING NUT. EXAMINATION OF THE BOLT TUB REVEALED EVIDENCE OF PRE-LOAD STRESS. A SERVICE BULLETIN WAS ISSUED ON MARCH 03 1982, STATING THAT TO REDUCE PRE-LOAD STRESS ON THE COUNTERWEIGHT BOLT, THE TORQUE SPECIFICATION HAS BEEN REDUCED FROM 105-100 FOOT POUNDS TO 65-60 TORQUE POUNDS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (C) PROPELLER SYSTEM/ACCESSORIES, COUNTERWEIGHT - OVERTORQUE

- 2. (C) PROPELLER SYSTEM/ACCESSORIES, COUNTERWEIGHT SEPARATION 3. (C) PROCEDURES/DIRECTIVES NOT CORRECTED MANUFACTURER

Page 2 of 6 ATL82IA281

Factual Information

Pilot Information

Certificate:	Commercial	Age:	65,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	16000 hours (Total, all aircraft), 100 hours (Total, this make and model), 14 hours (Pilot In Command, all aircraft), 54 hours (Last 90 days, all aircraft)		

Page 3 of 6 ATL82IA281

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N220HB
Model/Series:	PA-34-220T PA-34-220T	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	34-8133270
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4750 lbs
Time Since Last Inspection:	28 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	289 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	TSIO-360-KB
Registered Owner:	MONTGOMERY AVIATION CORP.	Rated Power:	220 Horsepower
Operator:	MONTGOMERY AVIATION CORP.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	MONTGOMERY , AL	Type of Flight Plan Filed:	None
Destination:	MONTGOMERY , AL	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Page 4 of 6 ATL82IA281

Airport Information

Airport:	DANNELLY FIELD	Runway Surface Type:	Concrete
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	9000 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Minor
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 5 of 6 ATL82IA281

Administrative Information

Investigator In Charge (IIC):

Additional Participating

Persons:

Original Publish Date: September 15, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=71756

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL82IA281