

Aviation Investigation Final Report

Location:	MONTICELLO, New Yo	ork	Incident Number:	NYC83IA040
Date & Time:	December 7, 1982, 14	:10 Local	Registration:	N3809E
Aircraft:	AERONCA	11AC	Aircraft Damage:	Minor
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal			

Analysis

AS THE FLIGHT MADE A THREE POINT LANDING IN STRONG, GUSTING, LEFT CROSSWINDS, A GUST OF WIND LIFTED THE AIRCRAFT'S LEFT WING. DIRECTIONAL CONTROL WAS LOST AND THE AIRCRAFT DEPARTED THE RIGHT SIDE OF THE RUNWAY. IT CAME TO REST AT THE BOTTOM OF A GRASSY SLOPE NEXT TO THE RUNWAY, INCURRING MINOR DAMAGE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

- 1. (F) WEATHER CONDITION CROSSWIND
- 2. (C) COMPENSATION FOR WIND CONDITIONS IMPROPER PILOT IN COMMAND
- 3. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND
- 4. (F) TERRAIN CONDITION DOWNHILL

Factual Information

Pilot Information

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 1, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	120 hours (Total, all aircraft), 17 hours (Total, this make and model), 70 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	AERONCA	Registration:	N3809E
Model/Series:	11AC 11AC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	11AC-S28
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1250 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2113 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	C-85-8FJ
Registered Owner:	DAVID PEARSALL	Rated Power:	85 Horsepower
Operator:	DAVID PEARSALL	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	14 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	58°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	NEW MILFORD ,CT (11N)	Type of Flight Plan Filed:	None
Destination:	GLENDALE , AZ (C)	Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	

Airport Information

Airport:	SULLIVAN COUNTY MSV	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	6300 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	41.649921,-74.680969(est)

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	December 7, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=71760

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.