



# **Aviation Investigation Final Report**

Location: WINSLOW, Arizona Accident Number: LAX82DA115

Date & Time: March 22, 1982, 14:15 Local Registration: N25782

Aircraft: CESSNA 152 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE PILOT STATED THAT HE DID A TOUCH AND GO ON RUNWAY 29, THEN PULLED THE POWER OFF AT APPROXIMATELY 300 FT AGL OVER THE INTERSECTION OF RUNWAYS 29 AND 22. HE REPORTED THAT FROM THERE, HE ATTEMPTED TO LAND ON RUNWAY 22 WITH NO POWER, FAILED TO MAINTAIN AIRSPEED IN THE TURN, AND ENTERED A HIGH SINK RATE. THE AIRCRAFT LANDED HARD BEFORE REACHING RUNWAY 22.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: UNDERSHOOT

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

#### **Findings**

- 1. (C) JUDGMENT POOR PILOT IN COMMAND
- 2. (F) OVERCONFIDENCE IN PERSONAL ABILITY PILOT IN COMMAND
- 3. (F) OVERCONFIDENCE IN AIRCRAFT'S ABILITY PILOT IN COMMAND
- 4. (C) ALTITUDE MISJUDGED PILOT IN COMMAND
- 5. (C) DISTANCE MISJUDGED PILOT IN COMMAND
- 6. (C) AIRSPEED MISJUDGED PILOT IN COMMAND

-----

Occurrence #2: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
7. (C) LEVEL OFF - IMPROPER - PILOT IN COMMAND

Page 2 of 5 LAX82DA115

# **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 24, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	231 hours (Total, all aircraft), 19 hours (Total, this make and model), 187 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N25782
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	15280782
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	60 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2249 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-235-L2C
Registered Owner:	GALLAWAY, DOLORES	Rated Power:	110 Horsepower
Operator:	WWINSLOW AVIATION	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX82DA115

## **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Unknown	Visibility	50 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	50°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	59°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	WINSLOW , AZ (INW)	Type of Flight Plan Filed:	None
Destination:	WINSLOW , AZ (INW)	Type of Clearance:	None
Departure Time:	21:20 Local	Type of Airspace:	

# **Airport Information**

Airport:	WINSLOW MUNI INW	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	22	IFR Approach:	Practice
Runway Length/Width:	7498 ft / 150 ft	VFR Approach/Landing:	

# **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.100761,-110.640197(est)

Page 4 of 5 LAX82DA115

#### **Administrative Information**

Investigator In Charge (IIC):
Additional Participating

Persons:

Original Publish Date: March 22, 1983

**Last Revision Date:** 

Investigation Class: Class

Note:

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=73070">https://data.ntsb.gov/Docket?ProjectID=73070</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX82DA115