

Aviation Investigation Final Report

Location: Soldotna, Alaska Accident Number: ANC09CA020

Date & Time: February 16, 2009, 16:00 Local Registration: N418SP

Aircraft: Beech 65-A90-1 Aircraft Damage: Substantial

Defining Event: Loss of visual reference **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The airline transport pilot was making a personal cross-country flight under Title 14, CFR Part 91. The pilot said when he arrived at the destination airport there was 3-4 inches of new snow, and that the overcast and low light condition made everything look gray. He said the visual approach slope indicator (VASI) lights were inoperative, and the appropriate notice to airman (NOTAM) was issued. He said he turned on the runway lights, identified what he thought was the runway surface, and lined up the runway edge lights on his left. After the airplane touched down he said he realized that he landed to the right of the runway surface, with the right side runway edge lights on his left. The pilot said the airplane settled into deep snow, and impacted a snowbank, collapsing the landing gear. In a written statement the pilot wrote that given the snow and light conditions, using the wide area augmentation system (WAAS) instrument flight rules (IFR) approach would have aligned the airplane with the runway surface. The pilot said there were no known mechanical problems with the airplane prior to the accident. The airplane sustained structural fuselage damage during the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's misidentification of the runway surface during landing. Contributing to the accident were the snow-covered terrain, and low-light conditions.

Findings

Personnel issues Identification/recognition - Pilot

Personnel issues Visual illusion/disorientation - Pilot

Environmental issues Snow/slush/ice covered surface - Not specified

Environmental issues Low light - Effect on personnel

Page 2 of 6 ANC09CA020

Factual Information

History of Flight

Landing	Loss of visual reference (Defining event)	
Landing-flare/touchdown	Landing gear collapse	

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	52,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	November 27, 2007
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 14, 2008
Flight Time:	14000 hours (Total, all aircraft), 1730 hours (Total, this make and model), 13500 hours (Pilot In Command, all aircraft), 100 hours (Last 90 days, all aircraft), 28 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC09CA020

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N418SP
Model/Series:	65-A90-1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	LM-138
Landing Gear Type:	Retractable - Tricycle	Seats:	9
Date/Type of Last Inspection:	November 10, 2008 Continuous airworthiness	Certified Max Gross Wt.:	10200 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	11807 Hrs at time of accident	Engine Manufacturer:	Pratt & Whitney
ELT:	Installed, not activated	Engine Model/Series:	PT6A-20
Registered Owner:	MISSIONARY AVIATION REPAIR CENTER	Rated Power:	550 Horsepower
Operator:	MISSIONARY AVIATION REPAIR CENTER	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site: Visual (VMC) Condition of Light: Day Observation Facility, Elevation: PASX Distance from Accident Site: Observation Time: 15:16 Local Direction from Accident Site: Lowest Cloud Condition: Scattered / 8000 ft AGL Visibility 10 miles Lowest Ceiling: Broken / 9000 ft AGL Visibility (RVR): Wind Speed/Gusts: / Turbulence Type Forecast/Actual: Wind Direction: Turbulence Severity Forecast/Actual: / Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C / -1°C Precipitation and Obscuration: Type of Flight Plan Filed: Company VFR Destination: Soldetne AK (PASS) Type of Flight Plan Filed: None				
Observation Time: 15:16 Local Direction from Accident Site: Lowest Cloud Condition: Scattered / 8000 ft AGL Visibility 10 miles Lowest Ceiling: Broken / 9000 ft AGL Visibility (RVR): Wind Speed/Gusts: / Turbulence Type Forecast/Actual: Wind Direction: Turbulence Severity Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C / -1°C Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Lowest Cloud Condition: Scattered / 8000 ft AGL Visibility I 0 miles Lowest Ceiling: Wind Speed/Gusts: / Wind Direction: Zurbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Observation Facility, Elevation:	PASX	Distance from Accident Site:	
Lowest Ceiling: Broken / 9000 ft AGL Visibility (RVR): Wind Speed/Gusts: / Turbulence Type Forecast/Actual: Wind Direction: Turbulence Severity Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C / -1°C Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Observation Time:	15:16 Local	Direction from Accident Site:	
Wind Speed/Gusts: Wind Direction: Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C /-1°C Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Lowest Cloud Condition:	Scattered / 8000 ft AGL	Visibility	10 miles
Wind Direction: Turbulence Severity Forecast/Actual: Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C / -1°C Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Lowest Ceiling:	Broken / 9000 ft AGL	Visibility (RVR):	
Altimeter Setting: 29.5 inches Hg Temperature/Dew Point: 1°C / -1°C Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Wind Speed/Gusts:	/	- -	/
Precipitation and Obscuration: Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Wind Direction:			/
Departure Point: Wasilla, AK (PAWS) Type of Flight Plan Filed: Company VFR	Altimeter Setting:	29.5 inches Hg	Temperature/Dew Point:	1°C / -1°C
	Precipitation and Obscuration:			
Postination: Soldstra AV (DASV) Type of Clearance: None	Departure Point:	Wasilla, AK (PAWS)	Type of Flight Plan Filed:	Company VFR
Destination. Soldottia, Ar (FASA) Type of Clearance. Notice	Destination:	Soldotna, AK (PASX)	Type of Clearance:	None
Departure Time: 15:15 Local Type of Airspace:	Departure Time:	15:15 Local	Type of Airspace:	

Page 4 of 6 ANC09CA020

Airport Information

Airport:	Soldotna PASX	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Snow
Runway Used:	07	IFR Approach:	None
Runway Length/Width:	5000 ft / 130 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	60.474998,-151.038055

Page 5 of 6 ANC09CA020

Administrative Information

Investigator In Charge (IIC):	Lewis, Lawrence
Additional Participating Persons:	Silvia Villa; FAA; Anchorage, AK
Original Publish Date:	May 12, 2009
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73354

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC09CA020