



Aviation Investigation Final Report

Location:	Gaithersburg, Maryland	Accident Number:	ERA09LA200
Date & Time:	March 15, 2009, 13:43 Local	Registration:	N213CP
Aircraft:	CIRRUS DESIGN CORP SR22	Aircraft Damage:	Substantial
Defining Event:	Loss of control in flight	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

During the initial climb after takeoff on an instrument-flight-rules flight, as the airplane entered clouds about 700 to 1,000 feet above mean sea level, the passenger door opened about 2 to 3 inches, which allowed rain, cold air, and increased noise to enter the cockpit. The pilot said that he became spatially disoriented and that the airplane subsequently "stalled and started to spin." The pilot activated the Cirrus Airplane Parachute System and the airplane descended toward the ground. The left wing struck a parked vehicle and the airplane came to rest on a road about 1/2 mile west of the airport. The airplane's left wing was fractured and the empennage was separated just forward of the horizontal stabilizer. Examination of the airplane, which included the passenger door locking mechanism, did not reveal any mechanical anomalies. The pilot reported 327 hours of total flight experience, which included 161 hours in the same make and model as the accident airplane, and about 7 and 63 hours of actual and simulated instrument flight experience, respectively. A weather observation taken at the departure airport about the time of the accident included a visibility of 2 miles and overcast clouds at 400 feet.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's spatial disorientation after the passenger door opened during flight in instrument meteorological conditions. Contributing to the accident was the pilot's failure to properly secure the door latch.

Findings

Personnel issues

Personnel issues

Lack of action - Pilot Spatial disorientation - Pilot

Factual Information

History of Flight		
Initial climb	Miscellaneous/other	
Maneuvering	Loss of control in flight (Defining event)	

On March 15, 2009, about 1343 eastern daylight time, a Cirrus Design Corp. SR22, N213CP, owned and operated by a private pilot, was substantially damaged after it deployed its Cirrus Airplane Parachute System (CAPS), shortly after takeoff from the Montgomery County Airpark (GAI), Gaithersburg, Maryland. The certificated private pilot was not injured. Instrument meteorological conditions prevailed and an instrument flight rules flight plan had been filed for the flight destined for the Battle Creek International Airport (AZO), Kalamazoo, Michigan. The personal flight was conducted under the provisions of Title 14 Code of Federal Regulations Part 91.

The airplane departed from runway 32, a 4,202-foot-long, asphalt runway.

The pilot reported that during the initial climb, as the airplane first entered clouds, about 700 to 1,000 feet mean sea level, the passenger side door "popped open" about 2 to 3 inches, which allowed rain, cold air, and increased noise to enter the cockpit. The pilot said he became spatially disoriented and the airplane's attitude varied; however, he was able to stabilize the airplane and intended to return to GAI. While maneuvering, with the airplane "in and out of clouds," the airplane "stalled and started to spin." The pilot was not able to recall the airplane's airspeed or altitude. He recalled pressing the "level button" and then elected to deploy the CAPS.

The airplane subsequently descended toward the ground. The left wing struck a parked vehicle and the airplane came to rest on a road, about 1/2 mile west of the airport. The airplane's the left wing was fractured and the empennage separated just forward of the horizontal stabilizer.

Examination of the airplane, which included the passenger door locking mechanism, by a Federal Aviation Administration (FAA) inspector, did not reveal any mechanical malfunctions. The pilot stated he did not experience any mechanical malfunctions during the flight.

The airplane was equipped with a "Garmin Perspective" cockpit instrumentation system, and a remote data module (RDM). The RDM, which was intended to record engine and flight parameters, was removed and forwarded to the NTSB Vehicle Recorders Laboratory, Washington, DC, where it was subsequently downloaded.

According to the Safety Board Specialist's Factual Report, significant events recorded during the accident flight included the takeoff at 1339:35, roll excursions which began at 1340:00,

pitch excursions which began at 1341:50, engagement of the autopilot in Level Mode for both lateral and vertical directions at 1342:06, stall warning at 1342:08, and CAPS deployment at 13:42:18. The autopilot and flight director disengaged, as designed when the stall warning system activated.

The pilot, age 64, held a private pilot certificate, with ratings for airplane single-engine land and instrument airplane. His most recent FAA third-class medical certificate was issued on September 12, 2008. The pilot reported 327 hours of total flight experience, which included 161 hours in the same make and model as the accident airplane, and about 7 and 63 hours of "actual" and "simulated" instrument flight experience, respectively.

The airplane, serial number 3142, was issued a standard airworthiness certificate on July 18, 2008, and was purchased new by the pilot through a corporation during August 2008. At the time of the accident, the airplane had been operated for about 120 hours. The pilot reported that he had previously owned another SR22, which was equipped with an Avidyne cockpit instrumentation system.

The Garmin Perspective Avionics suite included a feature designed to engage the autopilot to command an attitude for level flight. The Cirrus Perspective Pilot's Guide, stated, in part:

"Level Mode is coupled pitch and roll modes and is annunciated as both the vertical and lateral modes when active. Pressing the LVL Key engages the autopilot (if not engaged), rolls the wings level, and maintains an aircraft attitude that provides level flight. Level Mode does not track altitude or heading. Pressing the LVL Key always engages the autopilot. When the LVL Key is pressed all armed and active modes are cancelled and the autopilot and flight director revert to LVL Mode for pitch and roll."

According to a Cirrus representative, the LVL button will not engage, or will disengage, if the Stall Warning System is activated. At the time of the accident, the SR22 Pilot's Operating Handbook Supplement pertaining to Level Button on the Garmin Perspective System indicated:

"LVL – Level Button: The LVL button engages the autopilot (if not already engaged) and commands roll to zero bank angle and pitch to zero vertical speed."

On August 26, 2009, the section was revised to:

"LVL – Level Button: The LVL button engages the autopilot (within the Autopilot Engagement Limits if not already engaged) and commands roll to zero bank angle and pitch to zero vertical speed. The LVL button will not engage, or will disengage, if the Stall Warning System is activated."

A weather observation taken at GAI, at 1335, reported calm winds; visibility 2 miles, overcast clouds at 400 feet; temperature 4 degrees Celsius (C), dew point 3 degrees C; altimeter 30.21 inches of mercury. The pilot recalled that the cloud layer was "slightly higher" than about 800

feet.

Pilot Information

Certificate:	Private	Age:	64,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	September 12, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 3, 2008
Flight Time:	327 hours (Total, all aircraft), 161 hours (Total, this make and model), 261 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CIRRUS DESIGN CORP	Registration:	N213CP
Model/Series:	SR22	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3142
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	January 23, 2009 100 hour	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:	17 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	117 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, activated	Engine Model/Series:	IO-550N
Registered Owner:	N2877B LLC	Rated Power:	310 Horsepower
Operator:	N2877B LLC	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Day
Observation Facility, Elevation:	GAI,539 ft msl	Distance from Accident Site:	
Observation Time:	13:35 Local	Direction from Accident Site:	200°
Lowest Cloud Condition:		Visibility	2 miles
Lowest Ceiling:	Overcast / 400 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	4°C / 3°C
Precipitation and Obscuration:			
Departure Point:	Gaithersburg, MD (GAI)	Type of Flight Plan Filed:	IFR
Destination:	Kalamazoo, MI (AZO)	Type of Clearance:	IFR
Departure Time:	13:40 Local	Type of Airspace:	

Airport Information

Airport:	Montgomery County GAI	Runway Surface Type:	Asphalt
Airport Elevation:	539 ft msl	Runway Surface Condition:	Unknown
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	4202 ft / 75 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.164722,-77.171943(est)

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	Sandra McClure; FAA/FSDO; Baltimore, MD Brad T Miller; Cirrus Aircraft; Duluth, MN
Original Publish Date:	October 21, 2010
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73493

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.