



Aviation Investigation Final Report

Location:	Cartersville, Georgia	Accident Number:	ERA09LA203
Date & Time:	March 19, 2009, 11:08 Local	Registration:	N312RW
Aircraft:	Wayne O Robinson S6S Rans	Aircraft Damage:	Substantial
Defining Event:	Aerodynamic stall/spin	Injuries:	2 Serious
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot was departing in an experimental, amateur-built airplane, equipped with a non-certificated 65-horsepower engine. Shortly after takeoff, the airplane lost partial engine power, banked 90 degrees left, nosed down and collided with the ground while attempting to return to the runway. Examination of the engine ignition system found that it was equipped with two coil packs. Chafing was observed on two wires from the aft coil pack. If the chafed wire running to the ignition made contact with the adjacent ground wire, or the engine block, the aft cylinder would have stopped producing power, and the remaining cylinder would have had difficulty continuing normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain airspeed following a partial loss of engine power during initial climb, which resulted in an aerodynamic stall. Contributing to the accident was chafed wires in the ignition system.

Findings

Personnel issues	Incorrect action performance - Pilot
Aircraft	Airspeed - Not attained/maintained
Aircraft	Electrical pwr sys wiring - Damaged/degraded

Factual Information

History of Flight

Initial climb	Loss of engine power (partial)
Emergency descent	Aerodynamic stall/spin (Defining event)

On March 19, 2009, at 1108 eastern daylight time, an experimental, amateur-built S6S Rans, N312RW, received substantial damage when it collided with the ground following a loss of engine power after takeoff from the Cartersville Airport (VPC), Cartersville, Georgia. The certificated private pilot and passenger received serious injuries. Visual meteorological conditions prevailed and no flight plan was filed for the local flight. The airplane was registered to a private individual and operated by the private pilot under the provision of 14 Code of Federal Regulations Part 91.

Witnesses stated that shortly after takeoff, the engine lost power and the pilot attempted to return to the runway. While turning at a steep bank angle, approximately 90 degrees left bank, the airplane nosed down and collided with the ground. Witnesses called local authorities and proceeded to the accident site to lend assistance.

Examination of the airplane found that it had impacted the ground in about a 30-degree nose down attitude. The engine was displaced back into the firewall and the firewall was displaced into the cockpit. Both wings sustained leading edge impact damage, and both main landing gear were observed bowed outward. The cargo area, empennage, rudder, and horizontal stabilizers were undamaged. Flight control continuity was established throughout the airplane. Examination of the airframe and flight controls revealed no anomalies.

Examination of the engine revealed it was equipped with two coil packs, one for each cylinder. Both coil packs were removed and the wiring harness to the ignitions switch was also removed. Chafing was observed on two wires in the rear coil packs wiring. One wire, light brown in color, was connected to the coil pack and to a ground nut on the alternator. It was observed chafed near a plastic wire connector, traversing along the rear of the engine. A second wire was observed chafed at the same location, but was black and yellow in color and was connected at the ignition switch and the aft coil pack.

The two-seat, high-wing, fixed tricycle gear airplane, serial number 11041619S, was issued a Federal Aviation Administration experimental airworthiness certificate on January 25, 2008. It was powered by a non-certificated Rotax 582 DCDI, 65-horsepower engine. According to the aircraft flight logbook, the last conditional inspection was performed on August 7, 2008. At that time, the airplane had accumulated 40 hours of operation. At the time of the accident, the airplane had accumulated 103 hours of operation.

Pilot Information

Certificate:	Private	Age:	49, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	February 7, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 1500 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Wayne O Robinson	Registration:	N312RW
Model/Series:	S6S Rans	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	11041619S
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	August 7, 2008 Condition	Certified Max Gross Wt.:	1200 lbs
Time Since Last Inspection:	63 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	103 Hrs at time of accident	Engine Manufacturer:	Rotax
ELT:	C91 installed, activated, did not aid in locating accident	Engine Model/Series:	582 DCDI
Registered Owner:	On file	Rated Power:	65 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VPC,759 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	11:53 Local	Direction from Accident Site:	19°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Broken / 6000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.17 inches Hg	Temperature/Dew Point:	19°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Cartersville, GA (VPC)	Type of Flight Plan Filed:	None
Destination:	Cartersville, GA (VPC)	Type of Clearance:	None
Departure Time:	11:08 Local	Type of Airspace:	

Airport Information

Airport:	Cartersville Airport VPC	Runway Surface Type:	Asphalt
Airport Elevation:	759 ft msl	Runway Surface Condition:	Dry
Runway Used:	19	IFR Approach:	None
Runway Length/Width:	5760 ft / 100 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious	Latitude, Longitude:	34.123054,-84.848609

Administrative Information

Investigator In Charge (IIC):	Wilson, Ralph
Additional Participating Persons:	Kathy Tibbs; FAA/FSDO; College Park, GA
Original Publish Date:	June 17, 2010
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=73513

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).