



# Aviation Investigation Final Report

---

<b>Location:</b>	Baker, California	<b>Accident Number:</b>	WPR09LA177
<b>Date &amp; Time:</b>	April 2, 2009, 16:30 Local	<b>Registration:</b>	N222G
<b>Aircraft:</b>	Cessna 337G	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	2 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot was in cruise flight when both engines began to sputter and lose power. He attempted a restart of each engine but was unsuccessful. He estimated that the wind was out of the southeast at 40 knots and he wanted to turn into the wind for the landing, but could only get to a gravel road, which had a crosswind. He lowered the landing gear at the last instant in an attempt to cushion the landing, and kept the left wing low into the wind. The left wing contacted a gravel berm along the left side of the road, and the airplane spun around on the road. The landing gear fractured and separated and the airplane came to rest with the right wing on the ground. Recovery personnel drained 27 gallons of fuel from the left tank and 1.5 gallons from the right tank; the fuel selector valves were positioned for normal cruise flight. During a followup examination of the airplane no anomalies were noted. Fuel supplies were plumbed into the aircraft fuel system at both the left and right wing fuel tanks and both engines were started and run at various power settings. The investigation could not determine the reason for the power loss.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A total loss of engine power for undetermined reasons.

## Findings

<b>Environmental issues</b>	Rough terrain - Contributed to outcome
<b>Environmental issues</b>	Crosswind - Not specified
<b>Not determined</b>	(general) - Unknown/Not determined

## Factual Information

### History of Flight

<b>Enroute-cruise</b>	Loss of engine power (total) (Defining event)
<b>Emergency descent</b>	Off-field or emergency landing
<b>Landing-landing roll</b>	Collision with terr/obj (non-CFIT)

On April 2, 2009, about 1630 Pacific daylight time, a Cessna 337G, N222G, encountered uneven terrain during a forced landing near Baker, California. The pilot/owner was operating the airplane under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The certificated airline transport pilot and one passenger sustained minor injuries; the airplane sustained substantial damage to the airframe and wings. The cross-country personal flight departed Corona, California, at 1545, with a planned destination of Henderson, Nevada. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot reported that he was in cruise flight when both engines began to sputter and lose power. He attempted a restart, but was unsuccessful. He stated that the airplane was losing altitude rapidly. He headed toward Interstate 15 thinking that he would be found quicker. He estimated that the wind was out of the southeast at 40 knots. He wanted to turn into the wind for the landing, but could only get to a gravel road, which had a crosswind. He lowered the landing gear at the last instant in an attempt to cushion the landing, and kept the left wing low into the wind. The left wing contacted a gravel berm along the left side of the road, and the airplane spun around on the road. The landing gear fractured and separated; the airplane came to rest with the right wing on the ground.

Recovery personnel reported that they drained 27 gallons of fuel from the left tank, and 1.5 gallons from the right tank.

The Safety Board investigator-in-charge (IIC) examined the airplane and engines.

The IIC removed the top spark plugs from the front engine. All spark plugs were clean and oval shaped with no mechanical deformation. The spark plug electrodes were gray in color, which corresponded to normal operation according to the Champion Aviation Check-A-Plug AV-27 Chart.

The IIC manually rotated the crankshaft with the propeller. The crankshaft rotated freely, and the valves moved approximately the same amount of lift in firing order. The gears in the accessory case turned freely, and he obtained thumb compression on all cylinders in firing order. He connected the spark plugs to the respective ignition harness leads, rotated the propeller, and produced spark at all plug electrodes.

The IIC removed the top spark plugs from the rear engine. All spark plugs were clean and oval shaped with no mechanical deformation. The spark plug electrodes were gray, which corresponded to normal operation according to the Champion Aviation Check-A-Plug AV-27 Chart.

The IIC manually rotated the crankshaft with the propeller. The crankshaft rotated freely, and the valves moved approximately the same amount of lift in firing order. The gears in the accessory case turned freely, and he obtained thumb compression on all cylinders in firing order. He connected the spark plugs to the respective ignition harness leads, rotated the propeller, and produced spark at all plug electrodes.

Recovery personnel plumbed a fuel supply to the left wing inlet line, and installed a propeller that was not certified for this airplane. The front engine was started without difficulty; there were no fuel flow indications due to impact damage. After the engine temperature stabilized, they applied full throttle and obtained 26 inches of manifold pressure and a maximum of 1,400 engine revolutions per minute (rpm). Initially black smoke came from the exhaust, but then it cleared. Movement of the mixture control had no effect until the last inch of travel toward the idle cutoff position. The engine idled smoothly at 700 rpm, and was shut off smoothly with the mixture control.

Recovery personnel plumbed a fuel supply to the right wing inlet line. The rear engine was started without difficulty; there were no fuel flow indications due to impact damage. After the engine temperature stabilized, they applied full throttle and the manifold pressure went to the top of the green arc. The engine rpm increased and was climbing through 2,500 rpm. They did not go higher as the rear propeller was deformed, and the engine started to vibrate. They set the rpm at 1,800 and completed a magneto check; the rpm dropped 100 rpm on the left magneto and 50 rpm on the right magneto. Aft movement of the mixture control smoothed out engine operation. The engine idled smoothly at 750 rpm, and was shut off smoothly by the mixture control with a 50-rpm rise.

## Pilot Information

<b>Certificate:</b>	Airline transport; Commercial	<b>Age:</b>	71, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane; Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	March 17, 2009
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	March 17, 2009
<b>Flight Time:</b>	19000 hours (Total, all aircraft), 3000 hours (Total, this make and model), 15000 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N222G
<b>Model/Series:</b>	337G	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	33701783
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	April 17, 2008 Annual	<b>Certified Max Gross Wt.:</b>	4630 lbs
<b>Time Since Last Inspection:</b>	30 Hrs	<b>Engines:</b>	2 Reciprocating
<b>Airframe Total Time:</b>	1698 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Teledyne Continental Motors
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	IO-360-G
<b>Registered Owner:</b>	Roger L Levander	<b>Rated Power:</b>	210 Horsepower
<b>Operator:</b>	Roger L Levander	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KDAG,1927 ft msl	<b>Distance from Accident Site:</b>	40 Nautical Miles
<b>Observation Time:</b>	16:51 Local	<b>Direction from Accident Site:</b>	220°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	28 knots / 36 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	260°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	27°C / -7°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Corona, CA (AJO )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Henderson, NV (HND )	<b>Type of Clearance:</b>	VFR flight following
<b>Departure Time:</b>	15:45 Local	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Minor	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Minor	<b>Latitude, Longitude:</b>	35.25,-116.083335(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Plagens, Howard
<b>Additional Participating Persons:</b>	Ron Allen; FAA Riverside FSDO; Riverside, CA
<b>Original Publish Date:</b>	April 22, 2010
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=73589">https://data.ntsb.gov/Docket?ProjectID=73589</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).