



Aviation Investigation Final Report

Location:	Corvallis, Oregon	Accident Number:	WPR09LA184
Date & Time:	April 7, 2009, 15:30 Local	Registration:	N719HT
Aircraft:	Sikorsky CH-54B	Aircraft Damage:	Substantial
Defining Event:	Miscellaneous/other	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

The pilot and certified flight instructor departed for a local area instructional flight during which the pilot practiced a series of takeoffs and landings. During ground operations, the crew stated that they felt an unusual vibration, which was partially mitigated by keeping the collective pitch raised about 2 inches from the full down position. The pilot reported that he decided to adjust his seat position so he landed and handed off the controls to the certified flight instructor (CFI). The CFI lowered the collective to the full down position in preparation for the seat adjustment operation. At this time he noticed a vibration, which was followed by a loud "bang." The subsequent helicopter examination revealed that two of the six main rotor blades had diverged from their normal plane of rotation and impacted the tail rotor drive system, resulting in the number 5 and 6 tail rotor drive shaft sections separating from the helicopter. The investigation and examination of the helicopter found that during maintenance performed at an undetermined date by the operator's mechanics, the bell cranks that connect to the main rotor blades' control rods had been incorrectly installed in a reversed manner. This allowed the swash plate to travel outside of its designed range.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The improper assembly of main rotor blade control components by the operator's maintenance personnel, which resulted in the main rotor blade's divergent path and their contact with the tail rotor drive shaft during ground operation following landing.

Findings

Personnel issues	Incorrect action performance - Maintenance personnel
Aircraft	(general) - Incorrect service/maintenance
Aircraft	(general) - Incorrect service/maintenance

Factual Information

History of Flight

Prior to flight	Aircraft maintenance event
Standing-engine(s) operating	Miscellaneous/other (Defining event)

On April 7, 2009, about 1530 Pacific daylight time, a Sikorsky CH-54B (Skycrane), N719HT, was substantially damaged following touchdown at the Corvallis Municipal Airport, Corvallis, Oregon, when the main rotor blades diverted from their normal rotation plane and severed the tail rotor drive shaft. The helicopter was operated by Helicopter Transport Services, Corvallis. Visual meteorological conditions prevailed at the time, and no flight plan had been filed. Neither the airline transport certificated pilot, who held a certified flight instructor (CFI) certificate, nor the second crewmember-pilot was injured during the instructional/proficiency flight. The flight was performed under the provisions of 14 Code of Federal Regulations Part 91 and originated from Corvallis about 1500.

The CFI reported to the National Transportation Safety Board investigator that the helicopter had operated normally prior to the mishap, although a vibration was felt during ground operation. Therefore, the collective position was kept up about 2 inches, which seemed to reduce the ground vibrations.

After practicing four or five landings from a hover, the pilot, who was receiving instruction, landed to adjust his seat position. He handed off the controls to the CFI. The CFI lowered the collective to the full down position, in preparation for the seat adjustment. The terrain on which he landed was sloped. The CFI reported that as he "lowered the collective to the full down position, a vibration was noticed, followed by a loud 'bang', followed by severe vibrations. An emergency shut down followed, with immediate application of the rotor brake." After exiting the helicopter, it was determined that the number 5 & 6 tail rotor drive shaft sections had departed the helicopter, with damage to 2 of the 6 main rotor blades.

During the subsequent examination of the helicopter, the CFI verbally reported to the Safety Board investigator that the accident occurred when the main rotor blades diverged from their normal plane of rotation and contacted the tail rotor drive shaft.

The operator's director of maintenance verbally reported to the Safety Board investigator that maintenance of the helicopter was by the company's mechanics. During maintenance, the bellcranks that connect to the control rods had been incorrectly installed (in a reversed manner) thereby allowing the swashplate to travel outside of its designed range.

Federal Aviation Administration (FAA) personnel, who examined the wreckage and interviewed the operator's mechanics, stated they were unable to ascertain the date on which the subject

bellcranks had been installed, but it appeared to have been several years prior to the accident date. To reduce the likelihood for recurrence of this type of accident, the operator modified its maintenance procedure regarding bellcrank installation.

Flight instructor Information

Certificate:	Airline transport; Flight instructor	Age:	58, Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Helicopter; Instrument airplane; Instrument helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	November 5, 2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	September 17, 2008
Flight Time:	19000 hours (Total, all aircraft), 1100 hours (Total, this make and model), 18700 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Co-pilot Information

Certificate:	Commercial; Flight instructor	Age:	37, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	Yes
Instructor Rating(s):	Helicopter; Instrument helicopter	Toxicology Performed:	No
Medical Certification:	Class 1 None	Last FAA Medical Exam:	November 28, 2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 17, 2008
Flight Time:	2982 hours (Total, all aircraft), 1100 hours (Total, this make and model), 2356 hours (Pilot In Command, all aircraft), 180 hours (Last 90 days, all aircraft), 60 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Sikorsky	Registration:	N719HT
Model/Series:	CH-54B	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Experimental (Special); Restricted (Special)	Serial Number:	69-18469
Landing Gear Type:	Tricycle	Seats:	3
Date/Type of Last Inspection:	March 1, 2009 AAIP	Certified Max Gross Wt.:	47000 lbs
Time Since Last Inspection:	12 Hrs	Engines:	2 Turbo shaft
Airframe Total Time:	5365 Hrs at time of accident	Engine Manufacturer:	P & W
ELT:	Installed, not activated	Engine Model/Series:	JFTD12A-5A
Registered Owner:	U S LEASECO INC	Rated Power:	4800 Horsepower
Operator:	Helicopter Transport Services, Inc.	Operating Certificate(s) Held:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CVO,250 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	14:55 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.76 inches Hg	Temperature/Dew Point:	19°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Corvallis, OR	Type of Flight Plan Filed:	None
Destination:	Corvallis, OR	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	

Airport Information

Airport:	Corvallis Municipal CVO	Runway Surface Type:	
Airport Elevation:	250 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	44.497222,-123.289443(est)

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne
Additional Participating Persons:	Tim Moon; Federal Aviation Administration; Portland, OR
Original Publish Date:	April 22, 2010
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73618

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).