



Aviation Investigation Final Report

Location:	Salem, Indiana	Accident Number:	CEN09CA244
Date & Time:	April 1, 2009, 18:50 Local	Registration:	N115MS
Aircraft:	Mooney M20J	Aircraft Damage:	Substantial
Defining Event:	Collision with terr/obj (non-CFIT)	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot was practicing takeoff and landings when he extended the landing gear and heard the landing gear motor start while the airplane was on the downwind leg to the runway. The pilot noticed that the landing gear was not down during the landing flare. The airplane touched down on the runway with the landing gear retracted, and the airplane skidded about 500 feet before coming to a stop. The airplane received substantial damage when the airplane's firewall and underside skin were damaged. During the airplane's recovery, the landing gear control handle was placed into the down position and the landing gear extended when the master switch was placed into the on position. Postaccident inspection of the airplane revealed no anomalies.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to follow the landing checklist and extended the landing gear.

Findings

Personnel issues	Use of checklist - Pilot
Personnel issues	Forgotten action/omission - Pilot
Aircraft	Gear extension and retract sys - Not used/operated

Factual Information

History of Flight

Landing	Landing gear not configured
Landing-flare/touchdown	Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Private	Age:	58, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	August 1, 2007
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3000 hours (Total, all aircraft), 550 hours (Total, this make and model), 3 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N115MS
Model/Series:	M20J	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-0031
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 20, 2009 Annual	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3366 Hrs as of last inspection	Engine Manufacturer:	Textron Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360-A3B6D
Registered Owner:	Caren Schamel	Rated Power:	
Operator:	Pilot	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Salem, IN (I83)	Type of Flight Plan Filed:	None
Destination:	Salem, IN (I83)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Salem Municipal Airport I83	Runway Surface Type:	Asphalt
Airport Elevation:	822 ft msl	Runway Surface Condition:	Dry
Runway Used:	10	IFR Approach:	None
Runway Length/Width:	2738 ft / 50 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.601943,-86.139999(est)

Administrative Information

Investigator In Charge (IIC): Gallo, Mitchell

Additional Participating Persons:

Original Publish Date: June 11, 2009

Last Revision Date:

Investigation Class: [Class](#)

Note: This accident report documents the factual circumstances of this accident as described to the NTSB.

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=73631>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).