

Aviation Investigation Final Report

Location: Georgetown, South Carolina Accident Number: ERA09CA275

Date & Time: April 29, 2009, 11:45 Local Registration: N3036M

Aircraft: Piper PA-12 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Other work use

Analysis

The recently hired, tailwheel-endorsed commercial pilot was acting as pilot-in-command and was accompanied by the chief pilot of a banner tow company. He was practicing touch and go landings in a tailwheel airplane. During the second landing, the airplane turned to the right soon after the tailwheel contacted the runway. The pilot attempted to maintain directional control, but was unable to prevent the airplane departing the runway. The airplane ground looped, the left main landing gear collapsed, and the left wing was bent upward. Examination of the airplane by a Federal Aviation Administration inspector did not reveal any preimpact mechanical malfunctions. The recorded wind, about the time of the accident, was oriented with the runway heading at 5 knots. The pilot reported 319 hours of total flight experience, of which 3 hours were in the tailwheel-type airplane.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during landing roll. Contributing to the accident was the pilot's lack of experience in the make and model airplane.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Total experience w/ equipment - Pilot

Personnel issues Aircraft control - Pilot

Page 2 of 6 ERA09CA275

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)

Pilot Information

Certificate:	Commercial	Age:	29,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	March 18, 2009
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 22, 2008
Flight Time:	319 hours (Total, all aircraft), 3 hours (Total, this make and model), 187 hours (Pilot In Command, all aircraft), 8 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Other flight crew Information

Certificate:	Commercial	Age:	43,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	June 25, 2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 5, 2009
Flight Time:	4500 hours (Total, all aircraft), 3800 hours (Total, this make and model)		

Page 3 of 6 ERA09CA275

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N3036M
Model/Series:	PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	12-1581
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 8, 2009 100 hour	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	18 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	9944 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	O-320-A2B
Registered Owner:	Barnstormers Flite Signs	Rated Power:	150 Horsepower
Operator:	Barnstormers Flite Signs	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GGE,36 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	11:55 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.35 inches Hg	Temperature/Dew Point:	26°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	N. Myrtle Beach, SC (CRE)	Type of Flight Plan Filed:	None
Destination:	Georgetown, SC (GGE)	Type of Clearance:	None
Departure Time:	11:40 Local	Type of Airspace:	

Page 4 of 6 ERA09CA275

Airport Information

Airport:	Georgetown County Airport GGE	Runway Surface Type:	Asphalt
Airport Elevation:	36 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	33.311668,-79.319725(est)

Page 5 of 6 ERA09CA275

Administrative Information

Investigator In Charge (IIC):	Alleyne, Eric
Additional Participating Persons:	Todd Clamp; FAA/ FSDO; West Columbia, SC
Original Publish Date:	August 13, 2009
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73754

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA09CA275