



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Alpine, Texas	<b>Accident Number:</b>	CEN09LA284
<b>Date &amp; Time:</b>	May 8, 2009, 10:30 Local	<b>Registration:</b>	N60HG
<b>Aircraft:</b>	Cessna 421B	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (partial)	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Positioning		

## Analysis

Shortly after departure, when the airplane was about 400 feet in the air, the right engine stopped producing power. The pilot conducted a forced landing in a nearby field. An on-site inspection revealed that the airplane fuel tanks contained plenty of fuel. A post accident examination of the engines was conducted. An engine monitor was downloaded; a sudden decrease in cylinder head (CHT) and exhaust gas (EGT) temperature readings were observed for the right engine. A visual inspection of the engine revealed that the idler gear support pin, located on the rear of the engine, had backed out. The idler pin's retaining hardware (two nuts and lock-washers) were missing. The idler pin's movement allowed the idler gear to drop and become disconnected from the magnetos drive gear, resulting in a loss of engine ignition. Additionally, due to the mis-located idler gear, the accessory drive gears on the cam and crankshafts were either ground down or broken. Disassembly of the engine, found numerous metal pieces in the engine's oil sump.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of engine power due to disengagement of the magneto idler gear support pin.

## Findings

<b>Aircraft</b>	(general) - Malfunction
<b>Aircraft</b>	(general) - Not specified
<b>Aircraft</b>	Magneto/distributor - Malfunction

# Factual Information

## History of Flight

Initial climb	Loss of engine power (partial) (Defining event)
Initial climb	Off-field or emergency landing
Initial climb	Collision with terr/obj (non-CFIT)

On May 8, 2009, approximately 1030 central daylight time, a twin-engine Cessna 421B, N60HG, was substantially damaged during a forced landing following the loss of engine power shortly after takeoff, near Alpine, Texas. The commercial pilot, sole occupant, received minor injuries during the forced landing. The airplane was registered and operated by O'Hara Flying Service, Amarillo, Texas. Visual meteorological conditions prevailed and a flight plan was not filed for the Title 14 Code of Federal Regulations Part (CFR) 91 positioning flight destined for the Rick Husband Amarillo International Airport (AMA), Amarillo, Texas.

The pilot reported that, shortly after takeoff when the airplane was about 400 feet in the air, the right engine stopped producing power. As the pilot reached up to feather the right engine, the left engine "surged and sounded like it was going to quit." The pilot moved the engine controls forward, and looked for a place for a forced landing. The pilot added that he felt he did not have full power on the left engine. The airplane impacted several small bushes during the off-airfield landing.

A Federal Aviation Administration (FAA) inspector who responded to the site reported that the airplane had plenty of fuel and that it appeared consistent with 100LL aviation grade fuel.

An examination of the aircraft wreckage was conducted by the NTSB Investigator-in-Charge (IIC), along with technical representatives from the airframe and engine manufacturers, at Air Salvage of Dallas (ASOD) on 28 May, 2009.

A JPI engine monitor was downloaded; a sudden decrease in cylinder head (CHT) and exhaust gas (EGT) temperature readings were observed for the right engine. A visual inspection of the engine revealed that the idler gear support pin, located on the rear of the motor, had backed out. The idler pin's retaining hardware (two nuts and lock-washers) were missing. The idler pin's movement allowed the idler gear to drop, and become disconnected from the magneto drive gears, resulting in a loss of engine ignition. The idler gear teeth were severely worn. Additionally, the accessory drive gears on the cam and crankshafts were either ground down or broken. Disassembly of the engine, found numerous metal pieces in the engine's oil sump.

Examination of the left engine and engine monitor readings, revealed no apparent abnormalities. The engine was rotated to obtain thumb compression and drive train continuity. Each cylinder was borescoped; the sparkplugs were light gray in color and appeared "normal."

The magnetos were removed and rotated by hand, producing spark at each terminal. The engine's oil filter was cut open, inspected, and was found to be clear of any metal.

### Pilot Information

<b>Certificate:</b>	Airline transport	<b>Age:</b>	49,Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 5, 2008
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	February 9, 2009
<b>Flight Time:</b>	8818 hours (Total, all aircraft), 95 hours (Total, this make and model), 8060 hours (Pilot In Command, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N60HG
<b>Model/Series:</b>	421B	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	421B0534
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	8
<b>Date/Type of Last Inspection:</b>	April 1, 2009 100 hour	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	2 Reciprocating
<b>Airframe Total Time:</b>	7543 Hrs as of last inspection	<b>Engine Manufacturer:</b>	CONT MOTOR
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	GTSIO-520-C
<b>Registered Owner:</b>	O'HARA FLYING SERVICE II LP	<b>Rated Power:</b>	340 Horsepower
<b>Operator:</b>	O'HARA FLYING SERVICE II LP	<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KE38	<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>	10:26 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	5 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	230°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.94 inches Hg	<b>Temperature/Dew Point:</b>	31°C / 2°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Alpine, TX	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Amarillo, TX (AMA )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Alpine-Casparis Municipal Apt E38	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	30.429063,-103.32933(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Hatch, Craig
<b>Additional Participating Persons:</b>	Dan Vengen; FAA FSDO; Lubbock, TX Tom Moody; Cessna Aircraft Company; Wichita, KS John Kent; Continental Aircraft Engines; Mobile, AL
<b>Original Publish Date:</b>	April 22, 2010
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=73805">https://data.nts.gov/Docket?ProjectID=73805</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).