



Aviation Investigation Final Report

Location:	Jacksonville, Florida	Accident Number:	ERA09TA440
Date & Time:	August 4, 2009, 16:28 Local	Registration:	N186AE
Aircraft:	Eurocopter AS 350B3	Aircraft Damage:	Substantial
Defining Event:	Loss of control in flight	Injuries:	1 Minor, 1 None
Flight Conducted Under:	Public aircraft		

Analysis

The certified flight instructor and a commercial pilot receiving instruction were practicing maneuvers in the helicopter with the hydraulic system turned off, to simulate a hydraulic system failure. The commercial pilot was conducting a practice approach to a runway, with a transition to a hover. As the helicopter approached 5 feet above the ground, the commercial pilot began to lose directional control of the helicopter. The flight instructor assumed control; however, the helicopter entered multiple revolutions, climbs, and descents before it contacted the ground, spun, and rolled over. The fuselage, tail rotor and main rotor drive systems were substantially damaged. Examination of the helicopter did not reveal any preimpact mechanical malfunctions; nor did either pilot report any mechanical abnormalities. According to the helicopter manufacturer's flight manual training supplement, hovering without hydraulic power was not an approved procedure and would result in "excessive pilot workload, poor aircraft control, and possible loss of control."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The flight instructor's improper decision to attempt hover flight without hydraulic power and his subsequent loss of control.

Findings

Personnel issues	Decision making/judgment - Instructor/check pilot
Aircraft	(general) - Simulated malf/failure
Personnel issues	Aircraft control - Instructor/check pilot
Aircraft	(general) - Not attained/maintained

Factual Information

History of Flight

Maneuvering-hover	Loss of control in flight (Defining event)
Uncontrolled descent	Collision with terr/obj (non-CFIT)

On August 4, 2009, about 1628 eastern daylight time, a Eurocopter AS 350B3 helicopter, N186AE, was substantially damaged while maneuvering at Herlong Airport (HEG), Jacksonville, Florida. The certified flight instructor (CFI) sustained minor injuries and the certificated commercial pilot receiving instruction was not injured. Visual meteorological conditions prevailed, and no flight plan was filed for the instructional flight that originated at Jacksonville Naval Air Station (NIP), Jacksonville, Florida. The helicopter was owned by the US Department of Homeland Security and operated by Customs and Border Protection (CBP) as a public use flight.

According to a CBP representative and the pilots, the pilots were practicing maneuvers with the hydraulic system turned off, to simulate a hydraulic system failure. The commercial pilot was conducting a practice approach to runway 25, with a transition to a hover. As the helicopter approached 5 feet above the ground, the commercial pilot began to lose directional control, and requested that the flight instructor take control of the helicopter. The flight instructor assumed control; however, the helicopter entered multiple revolutions, climbs, and descents, before it contacted the ground, spun, and rolled over.

The helicopter came to rest about 290 feet south of runway 25, on a magnetic heading about 080 degrees. The fuselage, tail rotor and main rotor drive systems were substantially damaged.

Examination of the helicopter by a Federal Aviation Administration (FAA) inspector did not reveal any preimpact mechanical malfunctions; nor did either pilot report any mechanical abnormalities.

The CFI reported 2,782 hours of total helicopter flight experience, which included 580 hours in the same make and model as the accident helicopter.

The commercial pilot reported 1,154 hours of total helicopter flight experience, which included 12 hours in the same make and model as the accident helicopter.

Review of the AS 350B3 flight manual training supplement revealed that practice hovering without hydraulic power was not an approved procedure. The manual stated, in part:

"Caution: Do not attempt to carry out hover flight or any low speed maneuver without hydraulic

pressure assistance. The intensity and direction of the control feedback forces will change rapidly. This will result in excessive pilot workload, poor aircraft control, and possible loss of control."

Winds, reported at an airport located about 5 miles southwest of HEG, at 1550, were variable at 6 knots.

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	42, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	Helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	March 12, 2009
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	July 17, 2009
Flight Time:	3422 hours (Total, all aircraft), 580 hours (Total, this make and model), 1264 hours (Pilot In Command, all aircraft), 62 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Commercial	Age:	36, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	January 27, 2009
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	July 11, 2009
Flight Time:	2620 hours (Total, all aircraft), 12 hours (Total, this make and model), 1200 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Eurocopter	Registration:	N186AE
Model/Series:	AS 350B3	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3872
Landing Gear Type:	Skid	Seats:	6
Date/Type of Last Inspection:	May 21, 2009 100 hour	Certified Max Gross Wt.:	4961 lbs
Time Since Last Inspection:	52 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	1149 Hrs at time of accident	Engine Manufacturer:	Turbomeca
ELT:	Installed, not activated	Engine Model/Series:	Arriel 2B/2B1
Registered Owner:	U S DEPARTMENT OF HOMELAND SECURITY	Rated Power:	847 Horsepower
Operator:	U S Customs and Border Protection	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VQQ,81 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	15:50 Local	Direction from Accident Site:	225°
Lowest Cloud Condition:	Few / 3500 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 4500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	33°C / 24°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Jacksonville, FL (NIP)	Type of Flight Plan Filed:	Company VFR
Destination:	Jacksonville, FL (HEG)	Type of Clearance:	VFR
Departure Time:	15:58 Local	Type of Airspace:	

Airport Information

Airport:	Herlong HEG	Runway Surface Type:	Asphalt
Airport Elevation:	87 ft msl	Runway Surface Condition:	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	4000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor, 1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	30.274166,-81.803054(est)

Administrative Information

Investigator In Charge (IIC):	Schiada, Luke
Additional Participating Persons:	Joe Gramzinski; FAA/FSDO; Orlando, FL
Original Publish Date:	January 7, 2011
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=74447

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).