



Aviation Investigation Final Report

Location: Torrance, California Accident Number: WPR10CA079

Date & Time: November 29, 2009, 13:45 Local Registration: N8700

Aircraft: Curtiss Wright TRAVEL AIR 4000 Aircraft Damage: None

Defining Event: Ground collision **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Positioning

Analysis

The Travel Air pilot was taxiing down the 58-foot-wide asphalt lane that stretched between rows of hangar buildings toward a taxiway. Prior to beginning the taxi the pilot had visually checked the lane and had not observed any other aircraft in the lane between his position and the taxiway. The Travel Air is a tailwheel-type configuration, and the pilot was making continuous S-turns to look for obstructions ahead of his position. As he reached the end of the buildings, his propeller collided with the empennage of a stationary Lancair that had been pulled out of the end hangar. The pilot of the Lancair had started his engine and was contacting the Air Traffic Control Tower for a clearance onto the taxiway when the collision occurred. The point of the collision is in a non-movement ramp area not subject to air traffic control separation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The Travel Air pilot's failure to maintain an adequate visual lookout during taxi.

Findings

Personnel issues	Monitoring other aircraft - Pilot
Personnel issues	Task monitoring/vigilance - Pilot

Factual Information

History of Flight

Taxi	Ground collision (Defining event)

Pilot Information

Certificate:	Private	Age:	76,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	November 26, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 3000 hours (Total, all ai	rcraft), 2000 hours (Total, this make a	and model)

Aircraft and Owner/Operator Information

Curtiss Wright	Registration:	N8700
TRAVEL AIR 4000	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	976
	Seats:	3
	Certified Max Gross Wt.:	
	Engines:	1 Reciprocating
	Engine Manufacturer:	CONT MOTOR
	Engine Model/Series:	W670 SERIES
SMITH RICHARD CHARLES	Rated Power:	250 Horsepower
SMITH RICHARD CHARLES	Operating Certificate(s) Held:	None
	TRAVEL AIR 4000 Normal SMITH RICHARD CHARLES	TRAVEL AIR 4000 Aircraft Category: Amateur Built: Normal Serial Number: Seats: Certified Max Gross Wt.: Engines: Engine Manufacturer: Engine Model/Series: SMITH RICHARD CHARLES Rated Power: SMITH RICHARD CHARLES Operating Certificate(s)

Page 2 of 8 WPR10CA079

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipi	tation	
Departure Point:	Torrance, CA (TOA)	Type of Flight Plan Filed:	None
Destination:	Torrance, CA (TOA)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Zamperini Field Airport TOA	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	None
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	1 None	Latitude, Longitude:	33.803333,-118.339447(est)

Page 3 of 8 WPR10CA079

Administrative Information

Keliher, Zoe
Bill McGowen; Federal Aviation Administration; Los Angeles, CA
March 23, 2010
<u>Class</u>
This accident report documents the factual circumstances of this accident as described to the NTSB.
https://data.ntsb.gov/Docket?ProjectID=75157

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 8 WPR10CA079





Aviation Investigation Final Report

Location: Torrance, California Accident Number: WPR10CA079

Date & Time: November 29, 2009, 13:45 Local Registration: N880RS

Aircraft: SUTHERLAND RON LANCAIR 235 Aircraft Damage: Substantial

Defining Event: Ground collision **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The Travel Air pilot was taxiing down the 58-foot-wide asphalt lane that stretched between rows of hangar buildings toward a taxiway. Prior to beginning the taxi the pilot had visually checked the lane and had not observed any other aircraft in the lane between his position and the taxiway. The Travel Air is a tailwheel-type configuration, and the pilot was making continuous S-turns to look for obstructions ahead of his position. As he reached the end of the buildings, his propeller collided with the empennage of a stationary Lancair that had been pulled out of the end hangar. The pilot of the Lancair had started his engine and was contacting the Air Traffic Control Tower for a clearance onto the taxiway when the collision occurred. The point of the collision is in a non-movement ramp area not subject to air traffic control separation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The Travel Air pilot's failure to maintain an adequate visual lookout during taxi.

Findings

Personnel issues Monitoring other aircraft - Pilot of other aircraft

Factual Information

History of Flight

Taxi Ground collision

Pilot Information

Certificate:	Airline transport; Commercial	Age:	51
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	October 20, 2008
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	3400 hours (Total, all aircraft), 530 h Command, all aircraft)	nours (Total, this make and model), 25	000 hours (Pilot In

Aircraft and Owner/Operator Information

Aircraft Make:	SUTHERLAND RON	Registration:	N880RS
Model/Series:	LANCAIR 235	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	88
Landing Gear Type:		Seats:	2
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	0-320 SERIES
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 6 of 8 WPR10CA079

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Torrance, CA (TOA)	Type of Flight Plan Filed:	Unknown
Destination:	Torrance, CA (TOA)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Zamperini Field Airport TOA	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	1 None	Latitude, Longitude:	33.803333,-118.339447(est)

Page 7 of 8 WPR10CA079

Administrative Information

Keliher, Zoe	
Bill McGowen; Federal Aviation Administration; Los Angeles, CA	
March 23, 2010	
<u>Class</u>	
This accident report documents the factual circumstances of this accident as described to the NTSB.	
https://data.ntsb.gov/Docket?ProjectID=75157	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 8 of 8 WPR10CA079