



Aviation Investigation Final Report

Location: LaGrange, Georgia Accident Number: ERA10LA107

Date & Time: December 6, 2009, 12:15 Local Registration: N51620

Aircraft: Maule M5 Aircraft Damage: Substantial

Defining Event: Aircraft structural failure **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

A Federal Aviation Administration (FAA) inspector was conducting a ramp check when he noticed a damaged airplane with substantial damage to the right wing and right main landing gear. According to the pilot, after landing he turned left off of the runway onto the first taxiway. He stated that, as he began the turn, the right landing gear collapsed and the right wing tip and propeller struck the ground.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the right main landing gear for undetermined reasons.

Findings

Aircraft Main landing gear - Not specified

Factual Information

History of Flight

Landing-landing roll Aircraft structural failure (Defining event)

Landing roll Landing gear collapse

On December 6, 2009, about 1215 eastern standard time, a Maule M-5-220C, N51620, was substantially damaged following a collapse of the right main landing gear, at LaGrange-Callaway Airport (LGC), LaGrange, Georgia. The certificated private pilot/owner and his passenger were not injured. The personal flight was operated under the provisions of Title 14 Code of Federal Regulations Part 91. Visual meteorological conditions prevailed, and no flight plan was filed.

An inspector from the Federal Aviation Administration (FAA) Flight Standards District Office in Atlanta, Georgia, was conducting a ramp check at LGC several weeks after the accident when he noticed the damaged airplane, which was tied down in its usual location. The inspector determined that the pilot had not reported the damage, or the event that caused it, either to the FAA or to the National Transportation Safety Board (NTSB).

Follow-up activity by the inspector revealed that the right wing and right main landing gear were substantially damaged. Each main landing gear consisted of two upper struts and one lower strut. The upper ends of the three struts attached to the fuselage, and the lower ends attached to the respective main wheel fitting. The lower strut of the right main gear was buckled, which permitted the right main landing gear to collapse, and the right wing to contact the ground.

According to the pilot, after landing on runway 13, he turned left onto the first taxiway. He stated that as he began the turn, "the right landing gear collapsed" and the "right wing tip and propeller struck the ground."

FAA records indicated that the airplane was manufactured in 1974, and that it was equipped with a Franklin 6A-350 series piston engine. The airplane was first registered to the pilot in 1981. Further information regarding the airplane's condition and maintenance history were never provided to the NTSB, despite several requests to both the FAA and the airplane's owner. Review of FAA Airworthiness Directives and Maule Service Bulletins revealed that no additional mandatory or recommended maintenance or inspection procedures regarding the M-5 main landing gear were issued.

FAA records indicated that the pilot held a private pilot certificate with ratings for airplane single-engine land and instrument airplane. His most recent FAA third-class medical certificate was issued in July, 2008. He reported a total flight time of 723 hours, with 479 hours in the

Page 2 of 6 ERA10LA107

accident airplane.

FAA records indicated that LGC was equipped with a single asphalt runway, designated 13-31, that measured 5,599 feet by 150 feet. Airport elevation was listed as 693 feet above mean sea level. The airport was not equipped with a control tower. The first taxiway that intersected runway 13 was located approximately 1,500 feet from the threshold, and was oriented perpendicular to the runway centerline.

The 1215 recorded weather observation at LGC included winds from 130 degrees at 7 knots, 10 miles visibility, temperature 5 degrees C, dew point 2 degrees C, and an altimeter setting of 30.27 inches of mercury.

Pilot Information

| Certificate: | Private | Age: | 52,Male |
|---------------------------|---|-----------------------------------|---------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | July 15, 2008 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | July 26, 2009 |
| Flight Time: | (Estimated) 723 hours (Total, all aircraft), 479 hours (Total, this make and model), 5 hours (Last 90 days, all aircraft) | | |

Page 3 of 6 ERA10LA107

Aircraft and Owner/Operator Information

| Aircraft Make: | Maule | Registration: | N51620 |
|-------------------------------|-----------------------------|-----------------------------------|-----------------|
| Model/Series: | M5 220C | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 5012C |
| Landing Gear Type: | Tailwheel | Seats: | 4 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 2500 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 922 Hrs at time of accident | Engine Manufacturer: | FRANKLIN |
| ELT: | | Engine Model/Series: | 6A350 |
| Registered Owner: | On file | Rated Power: | 220 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |
| | | | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|-----------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | LGC,693 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 12:15 Local | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 7 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 130° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.27 inches Hg | Temperature/Dew Point: | 5°C / 2°C |
| Precipitation and Obscuration: | No Obscuration; No Precipit | ation | |
| Departure Point: | Lagrange, GA (LGC) | Type of Flight Plan Filed: | Unknown |
| Destination: | Lagrange, GA (LGC) | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | |
| | | | |

Page 4 of 6 ERA10LA107

Airport Information

| Airport: | LaGrange-callaway Airport LGC | Runway Surface Type: | Asphalt |
|----------------------|-------------------------------|----------------------------------|---------|
| Airport Elevation: | 693 ft msl | Runway Surface Condition: | Unknown |
| Runway Used: | 13 | IFR Approach: | Unknown |
| Runway Length/Width: | 5600 ft / 150 ft | VFR Approach/Landing: | Unknown |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 33.009514,-85.070078(est) |

Page 5 of 6 ERA10LA107

Administrative Information

| Investigator In Charge (IIC): | Huhn, Michael | |
|--------------------------------------|--|--|
| Additional Participating Persons: | William Hougenhout; FAA/FSDO; Atlanta, GA | |
| Original Publish Date: | November 29, 2011 | |
| Last Revision Date: | | |
| Investigation Class: | <u>Class</u> | |
| Note: | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=75223 | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA10LA107