



Aviation Investigation Final Report

Location:	Hot Springs, Arkansas	Accident Number:	CEN10CA332
Date & Time:	June 14, 2010, 14:00 Local	Registration:	N70906
Aircraft:	Piper J3C-65	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot/owner and a commercial-rated pilot departed in a tandem, two-seat, tailwheelequipped airplane on a local flight. On the return leg to the airport the commercial pilot was flying the airplane. The commercial pilot, who was seated in the rear seat, did his beforelanding checks to set up for the landing; however, during the approach to the runway the engine lost power. Unable to regain engine power, they elected to conduct a forced landing in a vacant lot. During the forced landing the airplane sustained damage to the left wing and fuselage. After the accident the pilot/owner and commercial pilot discovered that the engine's fuel shut-off valve was in the (pulled) off position. The commercial pilot reported that he flew a Cub Special (PA-11), but never the accident airplane (J3), and that the fuel shut-off valve in the J3 was in the same place as the carburetor heat in the PA-11. The commercial pilot added that the shut-off valve was not color coded or marked, and that he pulled the fuel shut-off knob mistaking it for the carburetor heat.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A total loss of engine power due to fuel starvation as a result of the pilot's inadvertent closure of the fuel valve. Contributing to the accident were the unmarked fuel shutoff valve and the pilot's inexperience in the accident airplane.

Findings

Aircraft	Fuel selector/shutoff valve - Unintentional use/operation
Personnel issues	Incorrect action performance - Pilot
Personnel issues	Total experience w/ equipment - Pilot
Aircraft	Fuel selector/shutoff valve - Related operating info

Factual Information

History of Flight

Approach-VFR pattern final	Fuel starvation
Approach-VFR pattern final	Loss of engine power (total) (Defining event)
Emergency descent	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	23,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Unknown	Last FAA Medical Exam:	June 14, 2010
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	November 25, 2009
Flight Time:	(Estimated) 1700 hours (Total, all aircraft), 0 hours (Total, this make and model), 1500 hours (Pilot In Command, all aircraft), 100 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Airline transport; Flight engineer	Age:	64,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Unknown	Last FAA Medical Exam:	February 18, 2010
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	(Estimated)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N70906
Model/Series:	J3C-65	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17927
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	July 20, 2009 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3325 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91A installed, activated, did not aid in locating accident	Engine Model/Series:	C85 Series
Registered Owner:	On file	Rated Power:	85 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	КНОТ	Distance from Accident Site:	1 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Few / 3900 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.06 inches Hg	Temperature/Dew Point:	31°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	Hot Springs, AR (KHOT)	Type of Flight Plan Filed:	Unknown
Destination:	Hot Springs, AR (KHOT)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Hot Springs Memorial Field KHOT	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Unknown
Runway Used:	13	IFR Approach:	Visual
Runway Length/Width:	4099 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	34.478054,-93.096107(est)

Administrative Information

Investigator In Charge (IIC):	Hatch, Craig
Additional Participating Persons:	Tommy J Arnold; FAA FSDO; Little Rock, AR
Original Publish Date:	October 21, 2010
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=76380

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.