

Aviation Investigation Final Report

Location: Lake Charles, Louisiana Accident Number: CEN10CA352

Date & Time: June 26, 2010, 10:15 Local Registration: N191EH

Aircraft: Aerospatiale AS350 Aircraft Damage: Substantial

Defining Event: Hard landing **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor was preparing the commercial-rated pilot for a check ride in the helicopter equipped with skid-type landing gear. During one of three running landings to a touchdown, the flight instructor was demonstrating a practice hydraulic failure running landing and the helicopter started to get into ground resonance as he initially touched down. The flight instructor increased power to become briefly airborne and continued the maneuver to a normal practice hydraulic failure running landing. After the ground resonance experience, the flight instructor continued the flight training session for an additional 45 minutes and conducted another hydraulic failure running landing, several slope landings, and five hovering autorotations. Two of the hovering autorotations were described as rough, with an undesired drift to the front left. The flight instructor then left the airport where they had been practicing and returned to their home base airport where they conducted two straight-in autorotations and three 180-degree autorotations, all to a power recovery. After shut-down procedures were completed the two pilots were surprised when they discovered substantial damage, with buckling around the full circumference of the forward part of the tail boom and a crack in the skin at the 6 o'clock position. The flight instructor stated that he thought the damage occurred when they were conducting hovering autorotations. The two pilots reported that they were not injured.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The flight instructor's inadvertent entry into ground resonance when demonstrating a hydraulic failure running landing, which resulted in substantial damage to the helicopter. Contributing to the accident was the pilot's and instructor pilot's failure to control the drift and rate of descent during the practice maneuvers.

Findings

Aircraft Descent rate - Not attained/maintained

Aircraft Directional control - Not attained/maintained

Personnel issues Incorrect action performance - Instructor/check pilot

Personnel issues Lack of action - Pilot

Personnel issues Lack of action - Instructor/check pilot

Page 2 of 6 CEN10CA352

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact	
Landing-flare/touchdown	Ground resonance	
Other	Aircraft inspection event	
Autorotation	Hard landing (Defining event)	
Landing-landing roll	Abnormal runway contact	

Flight instructor Information

Certificate:	Commercial	Age:	30,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	Helicopter; Instrument helicopter	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	January 13, 2010
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 4, 2009
Flight Time:	2383 hours (Total, all aircraft), 655 hours (Total, this make and model), 2258 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Commercial	Age:	48,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	May 12, 2010
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	4185 hours (Total, all aircraft), 6 hours (Total, this make and model)		

Page 3 of 6 CEN10CA352

Aircraft and Owner/Operator Information

Aircraft Make:	Aerospatiale	Registration:	N191EH
Model/Series:	AS350 B2	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2505
Landing Gear Type:	Skid	Seats:	6
Date/Type of Last Inspection:	June 8, 2010 AAIP	Certified Max Gross Wt.:	4961 lbs
Time Since Last Inspection:	90 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	8980 Hrs as of last inspection	Engine Manufacturer:	TURBOMECA
ELT:	C126 installed, not activated	Engine Model/Series:	Arriel 1
Registered Owner:	ERA Helicopters LLC	Rated Power:	732 Horsepower
Operator:	ERA Helicopters LLC	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:	ERA Helicopters	Operator Designator Code:	U0GA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CWF,17 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	09:50 Local	Direction from Accident Site:	360°
Lowest Cloud Condition:	Scattered / 2000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.02 inches Hg	Temperature/Dew Point:	32°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lake Charles, LA (LCH)	Type of Flight Plan Filed:	Company VFR
Destination:	Lake Charles, LA (LCH)	Type of Clearance:	VFR
Departure Time:	09:36 Local	Type of Airspace:	

Page 4 of 6 CEN10CA352

Airport Information

Airport:	Chennault International Airpor CWF	Runway Surface Type:	Concrete
Airport Elevation:	17 ft msl	Runway Surface Condition:	Dry
Runway Used:	15	IFR Approach:	None
Runway Length/Width:	10701 ft / 200 ft	VFR Approach/Landing:	Full stop;Simulated forced landing;Stop and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	30.206388,-93.139167(est)

Page 5 of 6 CEN10CA352

Administrative Information

Investigator In Charge (IIC):	Latson, Thomas
Additional Participating Persons:	Richard S Gordon; FAA Baton Rouge FSDO; Baton Rouge, LA
Original Publish Date:	December 20, 2010
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=76459

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN10CA352