



Aviation Investigation Final Report

Location:	Fowlerville, Michigan	Accident Number:	CEN11LA014
Date & Time:	October 11, 2010, 15:16 Local	Registration:	N53DB
Aircraft:	Drake Ronald A Acro Sport 1	Aircraft Damage:	Substantial
Defining Event:	Loss of control in flight	Injuries:	1 Serious
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

A witness reported that during landing the airplane touched down hard and bounced. He heard the sound of the engine increase, but not to a level consistent with takeoff power. He noted that the nose of the airplane was high. The airplane appeared to become unsteady and turned to the left, low over the trees. He commented that the airplane was rolling as he lost sight of it. He then heard the sound of the crash. A postaccident examination of the airframe and engine did not reveal any anomalies consistent with a preimpact failure or malfunction. The pilot had logged 3 flights in the amateur-built airplane prior to the accident flight, with a total of 3 landings.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's loss of control during a go-around maneuver following a bounced landing. Contributing to the accident was the pilot's limited experience in the make and model airplane.

Findings

Personnel issues Personnel issues Aircraft control - Pilot Total experience w/ equipment - Pilot

Factual Information

History	of F	Flight
---------	------	--------

Approach-VFR go-around

Loss of control in flight (Defining event) Collision with terr/obj (non-CFIT)

On October 11, 2010, about 1516 eastern daylight time, an amateur-built Drake Acro Sport 1 biplane, N53DB, impacted trees and terrain at the Maple Grove Airport (65G), Fowlerville, Michigan. The pilot had been conducting takeoffs and landings on runway 27 (3,050 feet by 110 feet, turf) and was attempting a go-around at the time of the accident. The pilot was seriously injured. The airplane sustained substantial damage to the wings and fuselage. The aircraft was registered to and operated by the pilot under the provisions of 14 Code of Federal Regulations Part 91. Visual meteorological conditions prevailed for the flight, which was not operated on a flight plan. The local flight departed from 65G at an undetermined time.

A witness reported that the pilot had overshot the runway and executed a go-around prior to the accident. On the accident approach, the airplane touched down hard and bounced. He heard the sound of the engine increase, but not to a level consistent with takeoff power. He noted that the nose of the airplane was high. The airplane began to "waffle" and turn to the left, low over the trees. He commented that the airplane was rolling as he lost sight of it. He then heard the sound of the crash.

The pilot did not have any recollection of the events leading up to the accident.

The airplane impacted a wooded area south of the airport. Sections of the wings were separated from the fuselage. They were located adjacent to the fuselage. The ailerons were dislocated from the wings and were located with the wreckage. The aft fuselage was deformed. The elevators and rudders remained attached to the horizontal and vertical stabilizers, respectively. Control continuity was confirmed from the elevators and rudder to the cockpit controls. A postaccident examination of the airframe did not reveal any anomalies consistent with a preimpact failure. A detailed examination of the engine did not reveal any anomalies which would have precluded the production of full power. The airplane recording hour meter indicated 10.7 hours.

The accident airplane was issued an amateur-built, experimental airworthiness certificate on April 9, 2010. Maintenance records included an entry noting the issuance of the airworthiness certificate. One additional entry, dated April 23, 2010, indicated the successful completion of the transponder and altitude reporting equipment testing. There were no subsequent entries in the maintenance records provided.

A review of pilot's logbook indicated a total flight time of 695.5 hours, with 20.6 hours in

tailwheel equipped aircraft. The available logbook information included 3 entries related to the accident airplane. The first was dated June 4, 2010, and noted a local flight of 0.7 hours, with 1 landing. The entry also included the comment, "Prop strike on landing." The second entry was dated October 1, 2010, and indicated a flight duration of 1.6 hours, with 1 landing. This entry included the notation, "First successful flight by R. D." The third entry was dated October 6, 2010, and indicated a flight duration of 1.1 hours, with 1 landing. This was the final entry in the available records. A logbook endorsement indicated the satisfactory completion of a flight review on May 25, 2010.

Weather conditions recorded at the Livingston County Airport (OZW), located about 7 miles southeast of 65G, at 1515, included clear skies and northwest winds at 6 knots.

Thethethethethethethethethethethethetheth			
Certificate:	Private	Age:	63,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Sport pilot None	Last FAA Medical Exam:	June 1, 2006
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 25, 2010
Flight Time:	696 hours (Total, all aircraft), 4 hours (Total, this make and model), 6 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Drake Ronald A	Registration:	N53DB
Model/Series:	Acro Sport 1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	90401
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	April 9, 2010 Condition	Certified Max Gross Wt.:	1350 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	11 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	0-320-H2AD
Registered Owner:	On file	Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	OZW,962 ft msl	Distance from Accident Site:	6 Nautical Miles
Observation Time:	15:35 Local	Direction from Accident Site:	146°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	24°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Fowlerville, MI (65G)	Type of Flight Plan Filed:	None
Destination:	Fowlerville, MI (65G)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Maple Grove 65G	Runway Surface Type:	Grass/turf
Airport Elevation:	908 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3050 ft / 110 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	42.717224,-84.0625(est)

Administrative Information

Investigator In Charge (IIC):	Sorensen, Timothy	
Additional Participating Persons:	Lewis Wright; FAA-Detroit FSDO; Belleville, MI	
Original Publish Date:	June 8, 2011	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=77544	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.