



# **Aviation Investigation Final Report**

Location: Riverton, Wyoming Accident Number: WPR11CA468

Date & Time: September 24, 2011, 10:00 Local Registration: N7549N

Aircraft: Beech 36 Aircraft Damage: Substantial

**Defining Event:** Landing gear collapse **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot said that after landing he inadvertently moved the main landing gear lever rather than the flap lever to the retract position, which resulted in the collapse of all three landing gear and substantial damage to the undercarriage of the airplane. The pilot reported no anomalies with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadvertent retraction of the landing gear during the landing roll.

#### **Findings**

Personnel issues Incorrect action performance - Pilot

Aircraft Landing gear selector - Unintentional use/operation

### **Factual Information**

### **History of Flight**

Landing-landing roll	Landing gear collapse (Defining event)	
----------------------	--	--

#### **Pilot Information**

Certificate:	Private	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 13, 2010
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 31, 2010
Flight Time:	219 hours (Total, all aircraft), 130 hours (Total, this make and model)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Beech	Registration:	N7549N
Model/Series:	36 NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	E-66
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	April 8, 2011 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	38 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4689 Hrs	Engine Manufacturer:	Teledyne Continental
ELT:	Installed, not activated	Engine Model/Series:	10-520
Registered Owner:	On file	Rated Power:	285 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 WPR11CA468

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RiW,5528 ft msl	Distance from Accident Site:	
Observation Time:	09:53 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.31 inches Hg	Temperature/Dew Point:	18°C / -3°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Riverton, WY (RIW )	Type of Flight Plan Filed:	Unknown
Destination:	Riverton, WY (RIW )	Type of Clearance:	None
Departure Time:	09:15 Local	Type of Airspace:	

### **Airport Information**

Airport:	Riverton Regional Airport RIW	Runway Surface Type:	Asphalt
Airport Elevation:	5528 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	28	IFR Approach:	None
Runway Length/Width:	8203 ft / 150 ft	VFR Approach/Landing:	Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.064167,-108.459724

Page 3 of 4 WPR11CA468

#### **Administrative Information**

Investigator In Charge (IIC):	Little, Thomas
Additional Participating Persons:	Michael Maglione; Federal Aviation Administration; Casper, WY
Original Publish Date:	December 1, 2011
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=81904

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 WPR11CA468