



Aviation Investigation Final Report

Location:	Grinnell, Iowa	Accident Number:	CEN12LA247
Date & Time:	April 17, 2012, 11:16 Local	Registration:	N69HJ
Aircraft:	Hughes 269A	Aircraft Damage:	Substantial
Defining Event:	Ground resonance	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The helicopter began to vibrate as the pilot raised the collective for liftoff. The pilot lowered the collective and closed the throttle when the vibration began; however, he was too late in recognizing the onset of ground resonance, which resulted in a violent, uncontrollable oscillation and separation of the tail boom from the fuselage. Examination of the helicopter revealed no anomalies that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper liftoff technique, which resulted in ground resonance, and the pilot's delayed recognition of the ground resonance.

Findings

Personnel issues	Incorrect action performance - Pilot
Aircraft	(general) - Not specified
Personnel issues	Identification/recognition - Pilot

Factual Information

History of Flight

Takeoff	Ground resonance (Defining event)
Takeoff	Attempted remediation/recovery
Takeoff-rejected takeoff	Aircraft structural failure

On April 17, 2012, about 1116 central daylight time, a Hughes 269A, N69HJ, experienced ground resonance during takeoff at Grinnell Regional Airport (GGI), Grinnell, Iowa. The pilot subsequently aborted the takeoff. The commercial pilot and a passenger were uninjured. The helicopter sustained substantial damage to the fuselage. The helicopter was registered to Lowry Flying Service Inc and operated by the pilot under the provisions of 14 Code of Federal Regulations Part 91 as a personal flight. Visual meteorological conditions prevailed and a flight plan had not been filed for the local flight that was originating at the time of the accident.

The pilot stated that when he raised the collective for liftoff, the helicopter started to vibrate. He "rolled the collective down" and "throttle off," but it was too late, and the helicopter shook apart "immediately." The transmission broke severing the tail. The rotor blades hit the ground.

According to the Federal Aviation Administration inspector, the helicopter never lifted off the ground during the accident flight. The pilot experienced ground resonance on three previous flights, the first of which was during takeoff and the other two occurred during landing. During the previous three occurrences of ground resonance, the pilot was able to identify and initiate a successful recovery. During the accident flight, the pilot was too late in recognizing the onset of ground resonance. There were no mechanical anomalies that would have precluded normal operation.

Pilot Information

Certificate:	Airline transport; Commercial	Age:	59, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	October 3, 2011
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 19, 2011
Flight Time:	8692 hours (Total, all aircraft), 30 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N69HJ
Model/Series:	269A UNDESIGNAT	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	580869
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	April 6, 2012 Annual	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3085 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	HIO-360-B1A
Registered Owner:	Lowry Flying Service Inc	Rated Power:	180 Horsepower
Operator:	Pilot	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GGI,1008 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	11:15 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.35 inches Hg	Temperature/Dew Point:	13°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Grinnell, IA (GGI)	Type of Flight Plan Filed:	None
Destination:	Grinnell, IA (GGI)	Type of Clearance:	None
Departure Time:	11:16 Local	Type of Airspace:	

Airport Information

Airport:	Grinnell Regional Airport GGI	Runway Surface Type:	
Airport Elevation:	1008 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	41.709999,-92.736114(est)

Administrative Information

Investigator In Charge (IIC):	Gallo, Mitchell
Additional Participating Persons:	Tony Will; Federal Aviation Administration; Des Moines, IA
Original Publish Date:	August 13, 2013
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=83415

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).