



Aviation Investigation Final Report

Location: CONWAY, South Carolina Accident Number: ATL91LA112

Date & Time: June 15, 1991, 13:36 Local Registration: N2GV

Aircraft: PIPER PA-12 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE BANNER TOW PILOT WAS CRUISING ADJACENT TO A LOCAL GOLF COURSE AT 1000 AGL WHEN HE EXPERIENCED A GRADUAL LOSS OF ENGINE POWER FOLLOWED BY A COMPLETE LOSS OF ENGINE POWER. ATTEMPTS TO REGAIN FULL POWER AND RESTART THE ENGINE FAILED. THE PILOT MANEUVERED THE AIRPLANE INTO POSITION FOR AN APPROACH TO A FAIRWAY AND RELEASED THE BANNER. THE AIRPLANE CAME TO REST 15 FEET OFF THE DEPARTURE END OF THE FAIRWAY IN A WOODED AREA. SUBSEQUENT EXAMINATIONS OF THE AIRPLANE REVEALED THAT THE #2 EXHAUST VALVE HAD FAILED. THE ENGINE WAS LAST OVERHAULED 2556 HOURS PRIOR TO THIS ACCIDENT. THE EXHAUST VALVE'S TIME IN SERVICE WAS NOT DETERMINED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE OF THE NUMBER TWO EXHAUST VALVE, WHICH RESULTED IN LOSS OF ENGINE POWER.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: CRUISE

Findings

1. (C) ENGINE ASSEMBLY, VALVE, EXHAUST - FAILURE, TOTAL

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

2. OBJECT - TREE(S)

Page 2 of 6 ATL91LA112

Factual Information

Pilot Information

| Certificate: | Commercial | Age: | 54,Male |
|---------------------------|---|-----------------------------------|---------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medicalw/ waivers/lim | Last FAA Medical Exam: | April 5, 1991 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 4293 hours (Total, all aircraft), 1581 hours (Total, this make and model), 4058 hours (Pilot In Command, all aircraft), 260 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft) | | |

Page 3 of 6 ATL91LA112

Aircraft and Owner/Operator Information

| Aircraft Make: | PIPER | Registration: | N2GV |
|-------------------------------|------------------------|-----------------------------------|-----------------|
| Model/Series: | PA-12 PA-12 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Restricted (Special) | Serial Number: | 12-824 |
| Landing Gear Type: | Tailwheel | Seats: | 3 |
| Date/Type of Last Inspection: | August 23, 1990 Annual | Certified Max Gross Wt.: | 1750 lbs |
| Time Since Last Inspection: | 180 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 2556 Hrs | Engine Manufacturer: | LYCOMING |
| ELT: | | Engine Model/Series: | O-320-A2B |
| Registered Owner: | SKY SIGNS, INC. | Rated Power: | 150 Horsepower |
| Operator: | SKY SIGNS, INC. | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | CRE ,33 ft msl | Distance from Accident Site: | 25 Nautical Miles |
| Observation Time: | 16:47 Local | Direction from Accident Site: | 270° |
| Lowest Cloud Condition: | Unknown | Visibility | 5 miles |
| Lowest Ceiling: | Broken | Visibility (RVR): | |
| Wind Speed/Gusts: | 9 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 190° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 31°C / 23°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | CONWAY , SC | Type of Flight Plan Filed: | None |
| Destination: | N MYRTLE BEACH, SC | Type of Clearance: | None |
| Departure Time: | 13:26 Local | Type of Airspace: | Class G |

Page 4 of 6 ATL91LA112

Airport Information

| Airport: | | Runway Surface Type: | |
|----------------------|---|----------------------------------|----------------|
| Airport Elevation: | | Runway Surface Condition: | |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 33.789993,-79.150657(est) |

Page 5 of 6 ATL91LA112

Administrative Information

| Investigator In Charge (IIC): | Powell, Phillip | |
|--------------------------------------|---|--|
| Additional Participating Persons: | DAVID ANDERSON; COLUMBIA , SC | |
| Original Publish Date: | December 15, 1992 | |
| Last Revision Date: | | |
| Investigation Class: | <u>Class</u> | |
| Note: | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=8420 | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL91LA112