



Aviation Investigation Final Report

Location: Gilmer, Texas Accident Number: CEN12LA566

Date & Time: August 21, 2012, 17:40 Local Registration: N2443

Aircraft: Thorp T-18 Aircraft Damage: Substantial

Defining Event: Fuel starvation **Injuries:** 2 Serious

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

Shortly after takeoff, the engine lost power, and the pilot performed a forced landing to wooded terrain. Examination of the engine revealed the fuel line from the fuel pump to the metering unit was disconnected at the metering unit. This disconnection would result in a loss of engine power. No additional anomalies were noted during the airframe and engine examination.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The disconnected metering unit fuel line, which resulted in a loss of engine power.

Findings

Aircraft Fuel distribution - Incorrect service/maintenance

Aircraft Fuel distribution - Malfunction

Personnel issues Installation - Maintenance personnel

Factual Information

History of Flight

Initial climb	Fuel starvation (Defining event)
Emergency descent	Collision with terr/obj (non-CFIT)

On August 21, 2012, approximately 1740 central daylight time, a Thorp T-18 experimental amateur-built airplane, N2443, sustained substantial damage when it impacted terrain during an attempted takeoff from Gilmer Municipal Airport (JXI), Gilmer, Texas. The airline transport pilot sustained minor injuries, and the pilot-rated passenger sustained serious injuries. The airplane was registered to McClendon Associates and operated by the pilot under the provisions of the 14 Code of Federal Regulations Part 91 as a personal flight. Visual meteorological conditions prevailed for the flight, which was not operated on a flight plan. The flight was destined for Denton, Texas.

According to the pilot, the fuel tanks were 3/4 full. Prior to takeoff, the pilot completed an engine run up with no problems noted. Shortly after takeoff, the engine rpm rolled back from 2,300 to 1,500 rpm. The pilot attempted to restore engine power; however, he was unsuccessful. The pilot executed a forced landing to tree-covered terrain. The airplane impacted several trees and came to rest upright.

A review of the engine maintenance records showed the engine underwent a conditional inspection on September 1, 2011, at a tachometer time of 930.9 hours. The engine was overhauled on March 23, 2003, at a tachometer time of 593.4 hours.

On September 21, 2012, at the facilities of Air Salvage of Dallas, Lancaster, Texas, the engine was examined under the supervision of a Federal Aviation Administration inspector. Examination of the engine revealed that the fuel line from the fuel pump to the metering unit was disconnected at the metering unit. No other anomalies were noted with the engine during the examination.

Page 2 of 5 CEN12LA566

Pilot Information

Certificate:	Airline transport; Commercial	Age:	58,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 9, 2011
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	September 10, 2011
Flight Time:	11000 hours (Total, all aircraft), 60 hours (Total, this make and model), 8000 hours (Pilot In Command, all aircraft), 12 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Thorp	Registration:	N2443
Model/Series:	T-18	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	536
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	September 1, 2011 Condition	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	780 Hrs at time of accident	Engine Manufacturer:	Continental Motors, Inc.
ELT:	Installed, not activated	Engine Model/Series:	IO-346-A
Registered Owner:	On file	Rated Power:	165 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN12LA566

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	28°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Gilmer, TX (JXI)	Type of Flight Plan Filed:	None
Destination:	Denton, TX (DTO)	Type of Clearance:	None
Departure Time:	17:40 Local	Type of Airspace:	

Airport Information

Airport:	Gilmer Municipal Airport JXI	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious	Latitude, Longitude:	32.697776,-94.948608(est)

Page 4 of 5 CEN12LA566

Administrative Information

Investigator In Charge (IIC): Sauer, Aaron

Additional Participating Persons: Chris Doherty; Federal Aviation Administration; Dallas, TX John Kent; Continental Motors; Mobile, AL

Original Publish Date: January 31, 2013

Last Revision Date: Investigation Class: Class

Note: Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=84768

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN12LA566