



# Aviation Investigation Final Report

---

<b>Location:</b>	Mc Cool Junction, Nebraska	<b>Accident Number:</b>	CEN12LA648
<b>Date &amp; Time:</b>	September 19, 2012, 12:30 Local	<b>Registration:</b>	N37754
<b>Aircraft:</b>	Hughes 269A	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

---

## Analysis

After takeoff, about 400 feet above ground level and about 50 knots airspeed, the flight instructor reduced the throttle to idle so the student pilot could demonstrate an autorotation. The student dropped the collective to enter the autorotation, and the engine stopped producing power; the helicopter descended rapidly and landed hard. A postaccident examination of the helicopter revealed an obstructed air filter. It is likely that the student lowered the collective too quickly, which, combined with the obstructed air filter, created a rich fuel mixture and loss of engine power. The student pilot mismanaged the autorotation and the instructor did not intervene in a timely manner to prevent the hard landing.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The flight instructor's inadequate supervision of the student pilot's entry into the autorotation, which resulted in a hard landing. Contributing to the accident was the loss of engine power as a result of the student pilot rapidly lowering the helicopter's collective and the partly obstructed air filter.

## Findings

---

<b>Personnel issues</b>	Monitoring other person - Instructor/check pilot
<b>Personnel issues</b>	Aircraft control - Student/instructed pilot
<b>Aircraft</b>	(general) - Incorrect service/maintenance

## Factual Information

### History of Flight

<b>Takeoff</b>	Loss of engine power (total) (Defining event)
<b>Autorotation</b>	Off-field or emergency landing
<b>Autorotation</b>	Hard landing

On September 19, 2012, about 1230 central daylight time, a Hughes 269A, helicopter, N37754, performed a hard landing, following an autorotation near Mc Cool Junction, Nebraska. The certificated flight instructor (CFI) and student pilot were not injured. The helicopter sustained substantial damage to the fuselage and tail boom. The helicopter was registered to and operated by the Star City Flying Club, Lincoln, Nebraska, under the provisions of 14 Code of Federal Regulations Part 91 as an instructional flight. Visual meteorological conditions prevailed for the flight, which operated without a flight plan. The flight originated from a private airfield.

According to statements taken by the responding Federal Aviation Administration inspectors, the purpose of the flight was to prepare the student pilot for an upcoming check ride. After takeoff, about 400 feet above ground level and at an airspeed on 50 knots, the CFI brought the engine back to idle to simulate a loss of engine power. The student dropped the collective and the engine quit producing power. An autorotation was initiated; however, the helicopter rapidly descended and landed hard. The tail boom was severed and the helicopter rolled over on its side. An inspection of the airframe and engine by inspectors from the FAA inspectors revealed that the air filter was approximately 80% obstructed by debris. A ground run was performed on the engine and the engine was found to have an excessively rich mixture.

## Flight instructor Information

<b>Certificate:</b>	Airline transport; Commercial; Flight instructor	<b>Age:</b>	75, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Helicopter; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	November 1, 2011
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Information

<b>Certificate:</b>	Private	<b>Age:</b>	72, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	July 31, 2012
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Hughes	<b>Registration:</b>	N37754
<b>Model/Series:</b>	269A	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	67-16774
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	May 1, 2013 Annual	<b>Certified Max Gross Wt.:</b>	1550 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	4706 Hrs at time of accident	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	HIO-360-B1A
<b>Registered Owner:</b>	STAR CITY FLYING CLUB LLC	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	STAR CITY FLYING CLUB LLC	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KJYR	<b>Distance from Accident Site:</b>	13 Nautical Miles
<b>Observation Time:</b>	12:35 Local	<b>Direction from Accident Site:</b>	320°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	12 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	250°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.85 inches Hg	<b>Temperature/Dew Point:</b>	32°C / 5°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	McCool Junction, NE	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	McCool Junction, NE	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	12:30 Local	<b>Type of Airspace:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	40.740997,-97.590934(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Aguilera, Jason
<b>Additional Participating Persons:</b>	Jim Sazama; FAA FSDO; Lincoln, NE
<b>Original Publish Date:</b>	June 4, 2013
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=85100">https://data.ntsb.gov/Docket?ProjectID=85100</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).