



Aviation Investigation Final Report

Location:	London, Ohio	Accident Number:	CEN13CA145
Date & Time:	January 29, 2013, 09:30 Local	Registration:	N193M
Aircraft:	Hughes 369HS	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The private pilot said the helicopter's turbine engine lost power after flying through an area of moderate to heavy snow. The pilot entered an autorotation and applied excessive aft cyclic during the touchdown in a field, which caused the main rotor blades to flex down and sever the tailboom. Weather reported in the area included snow and freezing fog, with a temperature of 16 degrees F. The helicopter was equipped with an automatic engine re-ignition and engine failure warning system, which was required per the rotorcraft flight manual (RFM) for operation in falling or blowing snow. The pilot said this system was armed at the time of the engine failure and the engine-out warning light illuminated and an audible tone sounded before the power loss. The RFM also stated that flight into known icing conditions was prohibited and fuel had to meet anti-icing capability of JP-4 when operating at 40 degrees or less. A review of fueling records revealed that no anti-icing additive was added to the fuel. The pilot was aware of the icing conditions, but he continued the flight. Examination of the engine found no mechanical anomalies that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to comply with established cold weather operating procedures, which resulted in a total loss of engine power. Contributing to the accident was the pilot's excessive aft cyclic input during the landing flare, which resulted in main rotor blade contact with the tail boom.

Findings

Personnel issues	Decision making/judgment - Pilot
Personnel issues	Incorrect action performance - Pilot
Environmental issues	Snow - Effect on equipment

Factual Information

History of Flight

Enroute	Loss of engine power (total) (Defining event)
----------------	---

Pilot Information

Certificate:	Private	Age:	53, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 14, 2011
Occupational Pilot:	No	Last Flight Review or Equivalent:	January 14, 2013
Flight Time:	500 hours (Total, all aircraft), 400 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N193M
Model/Series:	369HS	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1190219S
Landing Gear Type:	Skid	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Turbo shaft
Airframe Total Time:	6309 Hrs	Engine Manufacturer:	Allison
ELT:	Not installed	Engine Model/Series:	A250-C18
Registered Owner:	Daniel Mills	Rated Power:	250 Horsepower
Operator:	Daniel Mills	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Day
Observation Facility, Elevation:	OSU,906 ft msl	Distance from Accident Site:	21 Nautical Miles
Observation Time:	09:53 Local	Direction from Accident Site:	242°
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:	Indefinite (V V) / 800 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.19 inches Hg	Temperature/Dew Point:	-9°C / -10°C
Precipitation and Obscuration:			
Departure Point:	Canton, OH	Type of Flight Plan Filed:	VFR
Destination:	Dayton, OH (DAY)	Type of Clearance:	VFR;VFR flight following
Departure Time:		Type of Airspace:	

Airport Information

Airport:	None	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	2 None	Latitude, Longitude:	40.050834,-83.386665(est)

Administrative Information

Investigator In Charge (IIC):	Yeager, Leah
Additional Participating Persons:	David Tarrant; FAA/FSDO; Columbus, OH
Original Publish Date:	June 19, 2013
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=86104

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).