



# Aviation Investigation Final Report

---

<b>Location:</b>	Beaumont, Texas	<b>Accident Number:</b>	CEN13LA305
<b>Date &amp; Time:</b>	May 23, 2013, 12:00 Local	<b>Registration:</b>	N121CM
<b>Aircraft:</b>	Stinson 108-3	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (partial)	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation		

---

## Analysis

The pilot reported that the airplane's engine lost partial power shortly after takeoff. The airplane was unable to maintain altitude, so he executed a forced landing to a field, and the airplane nosed over. Postaccident examination revealed that the rubber boot between the carburetor heat box and cowl was missing its forward clamp, which was not found in the wreckage. The clamp was likely missing because an improper clamp was used or a clamp was not installed properly, which allowed the boot to come loose and to be ingested into the inlet of the carburetor heat box, restricting the airflow and resulting in a rich fuel mixture and the subsequent partial loss of engine power. No other anomalies were found with the engine or its systems.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The lack of a forward clamp on the carburetor heat box rubber boot, which allowed the boot to be ingested into the inlet of the carburetor heat box, restricting the airflow and leading to a subsequent partial loss of engine power.

## Findings

---

<b>Aircraft</b>	Air intake - Damaged/degraded
<b>Aircraft</b>	Air intake - Incorrect service/maintenance
<b>Personnel issues</b>	Installation - Maintenance personnel

## Factual Information

### History of Flight

<b>Enroute-climb to cruise</b>	Loss of engine power (partial) (Defining event)
<b>Landing</b>	Collision with terr/obj (non-CFIT)
<b>Landing</b>	Nose over/nose down

On May 23, 2013, about 1200 central daylight time, a Stinson 108-3, N121CM, sustained substantial damage when it nosed over during a forced landing following a loss of engine power near Beaumont, Texas. The pilot received minor injuries. The airplane sustained damage to the vertical tail surfaces, wings, wing struts, and fuselage. The aircraft was registered to and operated by Aircapital Nevada, Inc., under the provisions of 14 Code of Federal Regulations Part 91 as a business flight. Visual meteorological conditions prevailed for the flight, which was not operated on a flight plan. The flight was originating from the Beaumont Municipal Airport, Beaumont, Texas, and was bound for College Station, Texas.

The pilot reported that he had performed a pre-takeoff run-up and all engine indications were normal. He proceeded to take off and made two 90-degree turns prior to the loss of engine power. The pilot said that the engine was still producing some power, but he was not able to maintain altitude. He attempted to land in a field and the airplane nosed over.

Examination of the engine confirmed compression on all cylinders, valve system continuity, and magneto operation. The carburetor appeared new and the fuel strainer was clean with no debris. The fuel within the gascolator did not appear to have any water or sediment. The upper spark plugs were of three different electrode configurations. All of the plugs exhibited a wet-black appearance. The rubber boot that was located between the carburetor heat box and the cowl was very pliable and had cracks on the exterior surfaces. The rear of the boot was attached to the carburetor heat box with a clamp and sealant. The front of the boot did not have a clamp installed and one was not found in the wreckage.

Discussions with a member of the International Stinson Club (ISC) revealed that the front of the boot between the carburetor heat box and the cowl should have had a 2-piece clamp installed. The ISC member said that without the clamp installed it is possible for the boot to be sucked into the inlet of the carburetor heat box thereby restricting airflow, resulting in a rich mixture and reduction of engine power.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	81
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	January 10, 2013
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Stinson	<b>Registration:</b>	N121CM
<b>Model/Series:</b>	108-3	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	108-4284
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	Annual	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	FRANKLIN
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	6A4165 SERIES
<b>Registered Owner:</b>	AIRCAPITAL NEVADA INC	<b>Rated Power:</b>	165 Horsepower
<b>Operator:</b>	AIRCAPITAL NEVADA INC	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	BMT,32 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	11:35 Local	<b>Direction from Accident Site:</b>	0°
<b>Lowest Cloud Condition:</b>	Scattered / 2400 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 3000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	8 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	190°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.03 inches Hg	<b>Temperature/Dew Point:</b>	29°C / 23°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Beaumont, TX (BMT )	<b>Type of Flight Plan Filed:</b>	Unknown
<b>Destination:</b>	College Station, TX (CLL )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	12:00 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Beaumont Municipal Airport BMT	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	32 ft msl	<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	30.070278,-94.214996

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Brannen, John
<b>Additional Participating Persons:</b>	Raymond L McCall; FAA-Houston FSDO; Houston, TX
<b>Original Publish Date:</b>	February 10, 2014
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=87017">https://data.nts.gov/Docket?ProjectID=87017</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).