



# Aviation Investigation Final Report

<b>Location:</b>	Eagle, Colorado	<b>Accident Number:</b>	CEN13LA362
<b>Date &amp; Time:</b>	June 28, 2013, 14:55 Local	<b>Registration:</b>	N856CC
<b>Aircraft:</b>	Piper PA-24-260	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel starvation	<b>Injuries:</b>	2 Serious
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

During the flight, the airplane's engine experienced a loss of power, and the copilot took control of the airplane from the pilot, who had been flying, and directed the pilot to attempt to restart the engine. The airplane descended and impacted terrain short of the runway. The fuel tank selector was found in the left main tank position, but no visible fuel was found in the left main tank. After battery power was applied to the airplane, the engine data monitoring system indicated that the left main tank had 11 gallons of fuel and the right main tank had 8 gallons of fuel. After the fuel floats were moved, the monitoring system indicated that the left main tank had 2 gallons of fuel and that the right main tank had 9.5 gallons of fuel. Regardless of the fuel quantity indications, the pilots should have known how much fuel was in each tank and, based on fuel calculations, known when each tank was going to become empty. Further, the pilot should have switched fuel tanks as part of the engine restart procedures; however, he did not report doing so. Each of the four fuel tank senders were examined and wear and corrosion were found on all of them. When tested with a voltmeter, none of the fuel floats provided consistent electrical signals, which would alter the amount of fuel indicated on the engine monitoring system. Because the selector was positioned to the left main tank, the engine lost power due to fuel starvation.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilots' improper fuel management, which resulted in the loss of engine power due to fuel starvation. Contributing to the accident was worn and corroded fuel senders, which transmitted inaccurate fuel readings to the fuel monitoring system.

## Findings

---

<b>Aircraft</b>	Fuel - Fluid management
<b>Aircraft</b>	Fuel quantity sensor - Fatigue/wear/corrosion
<b>Personnel issues</b>	Forgotten action/omission - Pilot

## Factual Information

### History of Flight

<b>Approach</b>	Fuel starvation (Defining event)
<b>Landing</b>	Loss of engine power (total)

On June 28, 2013, about 1455 mountain daylight time, a Piper PA-24-260 airplane, N856CC, impacted terrain near the Eagle County Regional Airport (KEGE), Eagle, Colorado. The pilots were both seriously injured. The airplane was substantially damaged. The airplane was registered to and operated by a private individual under the provisions of 14 Code of Federal Regulations Part 91 as a personal flight. Visual meteorological conditions prevailed for the flight which operated on a visual flight rules flight plan. The flight originated from McClellan-Palomar Airport (KCRQ), Carlsbad, California, about 0915 pacific daylight time and was destined for KEGE.

The responding Federal Aviation Administration inspector conducted an on-scene examination of the airplane. The fuel selector was found by first responders in the left main position. Battery power was applied to the airplane and the engine data monitoring (EDM) unit displayed.

Left Auxiliary Tank: 0 gallons  
Left Main Tank: 11 gallons  
Right Main Tank: 8 gallons  
Right Auxiliary Tank: 3 gallons

Each tank contained a float that was moved and allowed to settle. The EDM displayed lower quantities. During recovery, the tanks were drained. The left auxiliary tank was empty and the left main tank contained 2 gallons. The right main tank contained 9.5 gallons and the right auxiliary tank contained 2.5 gallons.

The pilot reported that the co-pilot had borrowed the airplane in order to make the trip. The pilot flew the airplane while the co-pilot monitored their fuel status. While approaching runway 25 at EGE, the engine stopped producing power. The co-pilot took control of the airplane and directed the pilot to attempt a restart of the engine. The airplane descended and impacted terrain.

The airplane was moved to a salvage facility and the airplane's fuel tank senders were examined. All four senders displayed signs of age, wear, and corrosion. When tested with a voltmeter, none of the floats registered a consistent electrical signal when actuated through its range of motion.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	54
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Unknown
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 14, 2013
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	May 14, 2013
<b>Flight Time:</b>	220.6 hours (Total, all aircraft), 2.2 hours (Last 90 days, all aircraft), 2.2 hours (Last 30 days, all aircraft)		

## Co-pilot Information

<b>Certificate:</b>	Airline transport; Commercial; Flight engineer; Private	<b>Age:</b>	70
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	June 5, 2012
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Piper	<b>Registration:</b>	N856CC
<b>Model/Series:</b>	PA-24-260	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	24-4020
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	Unknown	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	C91A installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	TIO-540 SER
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	310 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KEGE,6547 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	14:50 Local	<b>Direction from Accident Site:</b>	70°
<b>Lowest Cloud Condition:</b>	Clear / 12000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	260°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.28 inches Hg	<b>Temperature/Dew Point:</b>	32°C / 1°C
<b>Precipitation and Obscuration:</b>	In the vicinity - Showers - Rain		
<b>Departure Point:</b>	CARLSBAD, CA (CRQ )	<b>Type of Flight Plan Filed:</b>	VFR
<b>Destination:</b>	Eagle, CO (EGE )	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	09:15 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	EAGLE COUNTY RGNL EGE	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	6547 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	25	<b>IFR Approach:</b>	Visual
<b>Runway Length/Width:</b>	9000 ft / 150 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Serious	<b>Latitude, Longitude:</b>	39.641109,-106.935554(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Aguilera, Jason
<b>Additional Participating Persons:</b>	Richard F Hosker; FAA; Denver, CO
<b>Original Publish Date:</b>	March 24, 2014
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=87251">https://data.ntsb.gov/Docket?ProjectID=87251</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).