

Aviation Investigation Final Report

Location: Everett, Washington Accident Number: WPR13CA327

Date & Time: July 12, 2013, 12:20 Local Registration: N6101H

Aircraft: STEARMAN AIRCRAFT C3-B Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that while en route, the airplane's engine began to make an abnormal noise and was running rough. He opted to make a precautionary landing at a nearby airport. The touchdown for the wheel-landing was normal and as the tailwheel settled onto the runway surface, the pilot held aft pressure on the control stick. During the landing roll, the airplane veered to the left and, despite the pilot's efforts to regain directional control with right rudder application, the airplane ground looped. The right main landing gear collapsed and the airplane incurred substantial damage to the interconnect strut.

The pilot initially reported no mechanical malfunctions or failures with the airplane that would have precluded normal operation, aside from the rough running engine. Later he submitted a statement that indicated he thought there was a possible failure of the landing gear. A postaccident examination of the landing gear revealed no evidence of mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during landing, which resulted in a ground loop.

Findings

Personnel issues	Aircraft control - Pilot
Aircraft	Directional control - Not attained/maintained

Page 2 of 5 WPR13CA327

Factual Information

History of Flight

Enroute-cruise	Loss of engine power (partial)
Landing-landing roll	Loss of control on ground (Defining event)

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	56
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	December 20, 2012
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 18, 2013
Flight Time:	2440 hours (Total, all aircraft), 10 ho Command, all aircraft)	ours (Total, this make and model), 220	00 hours (Pilot In

Aircraft and Owner/Operator Information

STEARMAN AIRCRAFT	Registration:	N6101H
СЗ-В	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	135
Tailwheel	Seats:	2
June 13, 2013 Annual	Certified Max Gross Wt.:	
	Engines:	1 Reciprocating
	Engine Manufacturer:	WRIGHT
Installed, not activated	Engine Model/Series:	J-5
On file	Rated Power:	220 Horsepower
On file	Operating Certificate(s) Held:	None
	C3-B Normal Tailwheel June 13, 2013 Annual Installed, not activated On file	C3-B Aircraft Category: Amateur Built: Normal Serial Number: Tailwheel Seats: June 13, 2013 Annual Certified Max Gross Wt.: Engines: Engine Manufacturer: Installed, not activated Engine Model/Series: On file Operating Certificate(s)

Page 3 of 5 WPR13CA327

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Ephrata, WA (EPH)	Type of Flight Plan Filed:	None
Destination:	Arlington, WA (AWO)	Type of Clearance:	None
Departure Time:	10:00 Local	Type of Airspace:	

Airport Information

Airport:	Snohomish County - Paine Field PAE	Runway Surface Type:	Asphalt
Airport Elevation:	610 ft msl	Runway Surface Condition:	Dry
Runway Used:	34L	IFR Approach:	None
Runway Length/Width:	9010 ft / 150 ft	VFR Approach/Landing:	Full stop;Precautionary landing;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.906944,-122.281387(est)

Page 4 of 5 WPR13CA327

Administrative Information

Investigator In Charge (IIC):	Keliher, Zoe
Additional Participating Persons:	Dale Watkins; Federal Aviation Administration; Seattle, WA
Original Publish Date:	December 19, 2013
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=87479

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 WPR13CA327