



# Aviation Investigation Final Report

<b>Location:</b>	CULPEPER, Virginia	<b>Accident Number:</b>	BF093LA104
<b>Date &amp; Time:</b>	July 3, 1993, 14:00 Local	<b>Registration:</b>	N9014K
<b>Aircraft:</b>	STINSON 108-1	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

THE PILOT REPORTED THAT THE AIRPLANE VEERED OFF THE RIGHT SIDE OF THE RUWNAY DURING LANDING ROLLOUT AND COLLIDED WITH A DITCH. HE STATED THAT HE APPLIED LEFT RUDDER AND BRAKE 'TO NO AVAIL'. AN INSPECTION OF THE AIRPLANE DID NOT REVEAL ANY MECHANICAL MALFUNCTIONS.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL DURING LANDING ROLLOUT. A FACTOR RELATED TO THE ACCIDENT INCLUDE A DITCH.

## Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER  
Phase of Operation: LANDING - ROLL

### Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND  
-----

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER  
Phase of Operation: LANDING - ROLL

Findings

2. (F) TERRAIN CONDITION - DITCH

## Factual Information

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	58, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	December 30, 1993
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	144 hours (Total, all aircraft), 48 hours (Total, this make and model), 80 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	STINSON	<b>Registration:</b>	N9014K
<b>Model/Series:</b>	108-1 108-1	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal; Utility	<b>Serial Number:</b>	1082014
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	February 1, 1993 Annual	<b>Certified Max Gross Wt.:</b>	2303 lbs
<b>Time Since Last Inspection:</b>	21 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2180 Hrs	<b>Engine Manufacturer:</b>	FRANKLIN
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	150
<b>Registered Owner:</b>	KATHY T. SANTIAGO	<b>Rated Power:</b>	150 Horsepower
<b>Operator:</b>	KATHY T. SANTIAGO	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	IAD ,313 ft msl	<b>Distance from Accident Site:</b>	30 Nautical Miles
<b>Observation Time:</b>	13:52 Local	<b>Direction from Accident Site:</b>	45°
<b>Lowest Cloud Condition:</b>	Scattered / 2500 ft AGL	<b>Visibility</b>	6 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	7 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	260°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29 inches Hg	<b>Temperature/Dew Point:</b>	31°C / 22°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	(W49)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:15 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	CULPEPER COUNTY W49	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	313 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	22	<b>IFR Approach:</b>	
<b>Runway Length/Width:</b>	4002 ft / 75 ft	<b>VFR Approach/Landing:</b>	Full stop

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	38.470664,-78.000907(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Guzzetti, Jeffrey
<b>Additional Participating Persons:</b>	DAVID KIRCHGESSNER; WASHINGTON , DC DALE ALLEN; WASHINGTON , DC
<b>Original Publish Date:</b>	September 26, 1994
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=8779">https://data.nts.gov/Docket?ProjectID=8779</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).