



Aviation Investigation Final Report

Location:	Lund, Nevada	Accident Number:	WPR13LA407
Date & Time:	September 15, 2013, 08:15 Local	Registration:	N1079K
Aircraft:	Mooney M20J	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	3 None
Flight Conducted Under:	Part 91: General aviation - Aerial observation		

Analysis

The pilot reported that he was maneuvering the airplane about 1,000 feet above ground level when the engine experienced a loss of power. The pilot initiated a forced landing to a road; however, the engine regained power before the airplane landed. As the airplane began to climb out, it collided with power lines. The pilot chose to continue the flight and landed at an airport 150 miles south of the accident site where it was discovered that the airplane sustained substantial damage due to the power line strike. Postaccident examination of the airframe and engine did not reveal any mechanical malfunctions or failures that would have precluded normal operation. The cause of the engine power loss could not be determined.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to monitor the environment, which led to a collision with power lines during climbout. Contributing to the accident was the loss of engine power during low-altitude flight for reasons that could not be determined because postaccident examination of the airframe and engine did not reveal any mechanical malfunctions or failures that would have precluded normal operation, which led to a forced landing that the pilot subsequently aborted when the engine regained full power.

Findings

Personnel issues	Monitoring environment - Pilot
Not determined	(general) - Unknown/Not determined
Environmental issues	Wire - Contributed to outcome
Personnel issues	Use of equip/system - Pilot

Factual Information

History of Flight

Maneuvering-low-alt flying	Loss of engine power (total) (Defining event)
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)

On September 15, 2013, about 0815 Pacific daylight time, a Mooney M20J, N1079K, sustained substantial damage when it collided with power lines 15 miles south of Lund, Nevada. The airplane was registered to Smith Plane LLC, and operated under the provisions of 14 Code of Federal Regulations Part 91 as a business flight. Visual meteorological conditions prevailed, and no flight plan was filed. The commercial pilot and two passengers were not injured. The flight originated from Ely Airport, Ely, Nevada, at 0730 and had a destination of North Las Vegas Airport(VGT), Las Vegas, Nevada.

The pilot stated to the National Transportation Safety Board (NTSB) investigator-in-charge (IIC) that the purpose of the flight was to monitor a race course at the Silver State Classic Challenge Road Race. When he was about 1,000 feet above ground level the engine experienced a loss of power. While attempting to make an emergency landing, the engine regained power; shortly thereafter the airplane collided with power lines. The power lines subsequently separated from the airplane and the pilot continued his climbout. The pilot reported that he decided to depart the area and fly south to VGT, which was about 150 miles south, rather than fly over the mountains near Ely, Nevada.

One of the passengers reported in a written statement to a Federal Aviation Administration inspector, that as he was looking out of the window the pilot was manipulating the controls. The pilot stated that he was going to land on a road as he pulled and then pushed the throttle lever back in. After colliding with the wires, the passenger stated that all of the alarms were going off. The passenger further stated that the cylinder head temperature was high, and that he pointed this to the pilot.

The postaccident examination of the airplane revealed that the airplane had impact marks and damage on both wings, cowling and propeller assembly. The left wing tip fairing section was bent rearward and the left aileron was ripped from the trailing edge to its leading edge. The postaccident examination of the airframe and engine revealed no evidence of mechanical malfunctions or failures that would have precluded normal operation.

Pilot Information

Certificate:	Commercial	Age:	74
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	August 1, 2013
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 5, 2013
Flight Time:	4222 hours (Total, all aircraft), 4000 hours (Total, this make and model)		

Passenger Information

Certificate:		Age:	
Airplane Rating(s):		Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Passenger Information

Certificate:		Age:	
Airplane Rating(s):		Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N1079K
Model/Series:	M20J NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	1990	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-3159
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	September 4, 2013 Annual	Certified Max Gross Wt.:	2899 lbs
Time Since Last Inspection:	8 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3529 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO360 SER A&C
Registered Owner:	SMITH PLANE LLC	Rated Power:	200 Horsepower
Operator:	SMITH PLANE LLC	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KELY,6262 ft msl	Distance from Accident Site:	36 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	20°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots / None	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	7°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Ely, NV (ELY)	Type of Flight Plan Filed:	
Destination:	LAS VEGAS, NV (VGT)	Type of Clearance:	None
Departure Time:	07:30 Local	Type of Airspace:	

Airport Information

Airport:	ELY ARPT /YELLAND FLD/ ELY	Runway Surface Type:	
Airport Elevation:	6259 ft msl	Runway Surface Condition:	Unknown
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	38.771945,-115.01361

Administrative Information

Investigator In Charge (IIC): Swick, Andrew

Additional Participating Persons: Paul Alukonis; Federal Aviation Administration; Las Vegas, NV

Original Publish Date: August 14, 2014

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.ntsb.gov/Docket?ProjectID=88038>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).