

Aviation Investigation Final Report

| Location: | Kotzebue, Alaska | Accident Number: | ANC13LA100 |
|-------------------------|--------------------------------------|------------------|-------------|
| Date & Time: | September 13, 2013, 13:15 Local | Registration: | N8316Q |
| Aircraft: | Cessna U206F | Aircraft Damage: | Substantial |
| Defining Event: | VFR encounter with IMC | Injuries: | 2 Serious |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

Before departing from a remote hunting site on a short cross-country flight, the accident pilot obtained a pilot report from another pilot who had just flown the route. The pilot report indicated 25 miles visibility, clouds at 1,400 feet, and a cloud ceiling at 1,800 feet. The airplane departed uneventfully, and, about 15 minutes into the 30-minute flight, the airplane approached the last ridge before the destination airport. The top of the ridge was about 1,950 feet mean sea level. The pilot stated that the destination airport peninsula was visible in the distance with an estimated 500 feet of clearance between the top of the ridge and the base of the cloud ceiling. He added that, as the airplane neared the ridge, the airplane encountered a severe downdraft and an abrupt entry into instrument meteorological conditions and then subsequently collided with the ridge about 30 to 50 feet below the ridgeline. However, review of handheld GPS data revealed that the airplane was in a constant climb during the minutes leading up to the collision with the ridge except for a 6-foot descent just before the collision. Additionally, the nearest reporting weather station reported a cloud ceiling about 50 feet below the ridgeline. The pilot noted no preimpact mechanical malfunctions with the airplane that would have precluded normal operation. Thus, it is likely that the pilot was flying the airplane low to stay below the clouds and then began to climb the airplane to clear the ridge when he entered instrument meteorological conditions as the airplane approached the ridge.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper decision to continue visual flight rules flight into instrument meteorological conditions, which resulted in controlled flight into terrain.

Findings

Personnel issues

Aircraft

Decision making/judgment - Pilot Altitude - Not attained/maintained

Factual Information

| History of Flight | |
|-------------------|-----------------------------------------|
| Enroute-cruise | VFR encounter with IMC (Defining event) |
| Enroute-cruise | Controlled flight into terr/obj (CFIT) |
| | |

On September 13, 2013, about 1315 Alaska daylight time, a Cessna U206F airplane, N8316Q, operated by a private individual, was substantially damaged when it collided with mountainous and hilly terrain about 25 miles northeast of Kotzebue, Alaska. The commercial pilot and passenger were seriously injured. The personal flight was conducted under the provisions of 14 Code of Federal Regulations Part 91. Visual meteorological conditions prevailed for the planned flight to Ralph Wien Memorial Airport, Kotzebue, Alaska. No flight plan was filed for the flight that departed from a remote hunting camp near Kiana, Alaska, about 1300.

The pilot stated that the purpose of the accident flight was to get supplies at Kotzebue and return to the hunting camp. Prior to departure, he obtained a pilot report from another pilot that had just flown the route. The pilot report included visibility 25 miles, clouds at 1,400 feet, and a ceiling at 1,800 feet. The accident airplane departed uneventfully and was in cruise flight as it approached the last ridge before Kotzebue. The pilot further stated that the Kotzebue peninsula was visible in the distance with an estimated 500 feet of clearance, between the top of the ridge and the base of the cloud layer. The pilot added that as the airplane neared the ridge, a severe downdraft was encountered along with abrupt entry into instrument meteorological conditions. He stabilized the airplane using cockpit instrumentation; however, the airplane collided with the ridge about 30 to 50 feet below the ridgeline. The pilot also noted that there were no preimpact mechanical malfunctions with the airplane.

A handheld GPS was recovered from the airplane and forwarded to the NTSB Vehicle Recorders Laboratory, Washington, DC, for data download. Review of the downloaded data revealed that during the last 6 minutes of flight, the airplane climbed from a GPS altitude of 709 feet to a GPS altitude of 1,955 feet. During the last 1 minute of flight, as the airplane approached the ridge, it climbed from a GPS altitude of 1,562 feet, to a GPS altitude of 1,955 feet. One second later, the airplane descended 6 feet to a GPS altitude of 1,949 feet, followed by a 10-foot descent to 1,939 feet 8 seconds after; however, the groundspeed between those two records decayed from 53 knots to 12 knots, consistent with collision occurring during that time.

After learning about reports of a weak emergency locator transmitter signal north of Kotzebue, search and rescue personnel aboard an Army National Guard UH-60L helicopter were dispatched from Nome, Alaska. The two seriously injured occupants remained at the accident site, while pinned in the wreckage, for approximately 28 hours before rescue personnel could reach the accident site.

The closest weather reporting facility was at Kotzebue, about 25 miles southwest of the accident site. At 1253, a weather observation was reporting, in part: Wind from 230 degrees at 17 knots; visibility 9 miles in light rain, broken ceiling at 1,900 feet, overcast ceiling at 2,500 feet; temperature 6 degrees C; dew

point 3 degrees C; altimeter 29.81 inches Hg. At 1353, a weather observation was reporting, in part: Overcast ceiling at 1,700 feet.

| Certificate: | Commercial; Flight instructor | Age: | 61 |
|---------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|----------------------------------------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | Airplane multi-engine; Airplane single-engine; Instrument airplane | Toxicology Performed: | No |
| Medical Certification: | Class 2 Without waivers/limitations | Last FAA Medical Exam: | June 26, 2013 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | June 24, 2013 |
| Flight Time: | 9275 hours (Total, all aircraft), 27 ho Command, all aircraft), 85 hours (Las 2 hours (Last 24 hours, all aircraft) | urs (Total, this make and model), 913 st 90 days, all aircraft), 35 hours (Last | 7 hours (Pilot In 30 days, all aircraft), |

Pilot Information

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N8316Q |
|----------------------------------|------------------------------------------------------|-----------------------------------|-----------------|
| Model/Series: | U206F | Aircraft Category: | Airplane |
| Year of Manufacture: | 1976 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | U20603177 |
| Landing Gear Type: | Tricycle | Seats: | 6 |
| Date/Type of Last Inspection: | May 22, 2013 Annual | Certified Max Gross Wt.: | 3600 lbs |
| Time Since Last Inspection: | 15 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 11165 Hrs at time of accident | Engine Manufacturer: | Continental |
| ELT: | C91 installed, activated, aided in locating accident | Engine Model/Series: | 10-520 |
| Registered Owner: | On file | Rated Power: | 300 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|-----------------------------------------|----------------------|-----------------------------------------|-------------------|
| Observation Facility, Elevation: | OTZ,14 ft msl | Distance from Accident Site: | 25 Nautical Miles |
| Observation Time: | 12:53 Local | Direction from Accident Site: | 225° |
| Lowest Cloud Condition: | | Visibility | 9 miles |
| Lowest Ceiling: | Broken / 1900 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | 17 knots / | Turbulence Type Forecast/Actual: | / Terrain-Induced |
| Wind Direction: | 230° | Turbulence Severity Forecast/Actual: | / Severe |
| Altimeter Setting: | 29.8 inches Hg | Temperature/Dew Point: | 6°C / 3°C |
| Precipitation and Obscuration: | Light - None - Rain | | |
| Departure Point: | Kiana, AK | Type of Flight Plan Filed: | None |
| Destination: | Kotzebue, AK | Type of Clearance: | None |
| Departure Time: | 13:00 Local | Type of Airspace: | |

Wreckage and Impact Information

| Crew Injuries: | 1 Serious | Aircraft Damage: | Substantial |
|------------------------|-----------|-------------------------|----------------------|
| Passenger Injuries: | 1 Serious | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 Serious | Latitude, Longitude: | 67.17778,-161.863052 |

Administrative Information

| Investigator In Charge (IIC): | Gretz, Robert |
|--------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|
| Additional Participating Persons: | Clark Miller; FAA - Fairbanks Flight Standards District Office; Fairbanks , AK Jan Smith; Cessna Aircraft Company; Wichita, KS |
| Original Publish Date: | August 14, 2014 |
| Last Revision Date: | |
| Investigation Class: | <u>Class</u> |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=88042 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.