



Aviation Investigation Final Report

Location:	Santa Teresa, New Mexico	Accident Number:	CEN13LA571
Date & Time:	September 29, 2013, 15:30 Local	Registration:	N3078F
Aircraft:	Cessna 182J	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Skydiving		

Analysis

The pilot reported that he was making a circling descent to the airport after dropping parachutists and that he used carburetor heat during the descent. As the pilot was on the base leg of the landing pattern, close to the turn onto the final leg, the engine lost power. The pilot landed the airplane short of the runway, and the firewall buckled and the nose landing gear bent forward. The operator later functionally tested the engine and it operated normally.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A loss of engine power for reasons that could not be determined because no anomalies were found during the postaccident engine examination.

Findings

Aircraft	(general) - Not specified
Not determined	(general) - Unknown/Not determined

Factual Information

History of Flight

Approach-VFR pattern downwind	Loss of engine power (total) (Defining event)
Emergency descent	Controlled flight into terr/obj (CFIT)

On September 29, 2013, about 1530 mountain daylight time, a Cessna 182J, N3078F, landed short of the runway at Dona Ana County Airport (5T6), Santa Teresa, New Mexico, after the engine lost power. The pilot, the sole occupant on board, was not injured. The airplane was substantially damaged. The airplane was registered to and operated by a private individual under the provisions of 14 Code of Federal Regulations Part 91 as a skydiving flight. Visual meteorological conditions prevailed at the time of the accident, and no flight plan had been filed. The local flight originated from 5T6 about 1505.

The pilot told a Federal Aviation Administration inspector that he was returning to the airport after parachutists had exited the airplane. During the descent, he momentarily opened throttle several times to "clear" the engine. Carburetor heat was on throughout the descent. When he went to advance the throttle to level off in the traffic pattern, the engine failed to respond. The pilot immediately turned towards runway 28. The airplane landed short of the runway. Post-accident inspection revealed the firewall was buckled and the nose landing gear was bent forward.

According to the operator, the engine was functionally tested and it operated normally. It was his opinion that when the pilot advanced the throttle to level off, the engine "loaded up" and failed to respond.

Pilot Information

Certificate:	Commercial	Age:	30
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	January 19, 2012
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 16, 2013
Flight Time:	310 hours (Total, all aircraft), 6 hours (Total, this make and model), 150 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N3078F
Model/Series:	182J	Aircraft Category:	Airplane
Year of Manufacture:	1968	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18257178
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	May 30, 2013 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	20 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2333 Hrs at time of accident	Engine Manufacturer:	Continental Motors
ELT:	Installed, not activated	Engine Model/Series:	O-470-R
Registered Owner:	Robert H. Kearns	Rated Power:	230 Horsepower
Operator:	Robert H. Kearns	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KELP,3958 ft msl	Distance from Accident Site:	28 Nautical Miles
Observation Time:	15:51 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	27°C / 1°C
Precipitation and Obscuration:			
Departure Point:	Santa Teresa, NM (5T6)	Type of Flight Plan Filed:	None
Destination:	Santa Teresa, NM (5T6)	Type of Clearance:	None
Departure Time:	15:05 Local	Type of Airspace:	Class G

Airport Information

Airport:	Dona Ana County 5T6	Runway Surface Type:	Asphalt
Airport Elevation:	4112 ft msl	Runway Surface Condition:	Dry
Runway Used:	28	IFR Approach:	None
Runway Length/Width:	8500 ft / 100 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	31.839729,-106.680145(est)

Administrative Information

Investigator In Charge (IIC): Scott, Arnold

Additional Participating Persons:

Original Publish Date: February 3, 2014

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.ntsb.gov/Docket?ProjectID=88227>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).