

Aviation Investigation Final Report

Location:	Homer, Alaska	Accident Number:	DCA14FA002
Date & Time:	October 23, 2013, 15:30 Local	Registration:	N575U
Aircraft:	Beech 1900C	Aircraft Damage:	Substantial
Defining Event:	Landing gear collapse	Injuries:	15 None
Flight Conducted Under:	Part 121: Air carrier - Scheduled		

Analysis

The captain was the pilot flying and conducted a visual approach to runway 22. The aircraft was configured on final approach with the landing gear down and the flaps selected to landing. The first officer indicated that, after touchdown on the runway, while intending to retract the flaps, he inadvertently selected the landing gear handle up. The nose landing gear and both main landing gear retracted and the airplane slid to a stop on the runway resting on the lower fuselage, wings, and engine nacelles.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The first officer inadvertently selecting the landing gear handle up after touchdown during the landing rollout. Contributing to the accident was the first officer's decision to reconfigure the airplane while still on the active runway.

Findings

Personnel issues	Incorrect action performance - Flight crew
Personnel issues	Use of equip/system - Flight crew
Personnel issues	Incorrect action selection - Flight crew
Personnel issues	Identification/recognition - Flight crew

Factual Information

History of Flight	
Landing-landing roll	Landing gear not configured
Landing-landing roll	Landing gear collapse (Defining event)

HISTORY OF FLIGHT

On October 23, 2013, at about 1530 Alaska daylight time (AKDT), ERA Alaska flight 878, a Beechcraft 1900C, N575U, experienced a nose and main landing gear collapse during landing on runway 22 at Homer Airport (HOM), Homer, Alaska. The 2 flight crew members and 13 passengers were not injured and the airplane sustained substantial damage. The scheduled domestic passenger flight was operating under the provisions of 14 Code of Federal Regulations Part 121 from Ted Stevens Anchorage International Airport (ANC), Anchorage, Alaska.

The captain was the pilot flying and conducted a visual approach to runway 22. The aircraft was configured on final approach with the landing gear down and the flaps selected to landing. After touchdown on the runway, the first officer selected the landing gear handle up. The nose landing gear and both main landing gear retracted and the airplane slid to a stop on the runway resting on the lower fuselage, wings, and engine nacelles.

INJURIES TO PERSONS

There were no injuries to the 13 passengers or 2 crewmembers on board.

DAMAGE TO AIRCRAFT

The airplane was substantially damaged sustaining deformation and wear due to runway contact. The lower fuselage dragged along the runway resulting in structural damage to the fuselage skin, stringers, and frames. Both propellers sustained damage due to contact with the runway surface

PERSONNEL INFORMATION

The flight crew consisted of two pilots and the accident occurred on their first flight of the day.

The captain, age 34, reported 7,609 hours total flight time, including 6,639 hours as pilot in command and 739 hours in the BE-1900. The captain held a valid Federal Aviation Administration (FAA) Airline Transport Pilot (ATP) certificate with type ratings for BE-1900, and DHC-8 (second in command privileges only) and a current FAA first-class medical certificate.

The first officer, age 58, reported 2,337 hours total flight time, including 383 hours in the BE-1900. He held a valid FAA ATP certificate and a current FAA first-class medical certificate with a limitation that he must wear corrective lenses.

AIRCRAFT INFORMATION

N575U, manufacturer serial number UC-93, was a Beech 1900C equipped with two Pratt and Whitney PT6A-65B turbo-prop engines. The company reported that the airplane had approximately 29,841 hours total time on the airframe. Recorded data and airline records indicated no open maintenance items with the airplane. At the time of the accident the estimated landing weight was 14,991 pounds.

Cockpit controls

The flap position lever is located on the lower right hand side of the center pedestal and included four detent positions: UP, TAKEOFF, APPROACH, and LANDING. Post-accident inspection indicated the flap position lever was in the LANDING position.

The landing gear control selector handle is located on the captain's side of the cockpit on the lower right subpanel included two positions: UP and DOWN. The control handle must be pulled out of a detent before it can be selected either UP or DOWN. A post-accident inspection indicated the landing gear selector lever was in the UP position.

Landing Gear Safety Switch

A safety switch on the right main landing gear opens the control circuit when the landing gear strut is compressed to prevent the landing gear handle from being raised when the airplane is on the ground. The safety switch automatically disengages when the airplane is not on the ground, and can be manually overridden by pressing a release button adjacent to the landing gear control handle.

METEOROLOGICAL INFORMATION

Day visual meteorological conditions prevailed at the time of the accident. The Homer Airport surface observation at 1453 AKDT, the most recent observation at the time of landing, reported wind from 070 degrees at 5 knots, visibility 10 statute miles, clear skies, temperature 6 degrees Celsius, dew point temperature minus 3 degrees Celsius, and altimeter 29.79 inches mercury.

AERODROME INFORMATION

The Homer Airport (HOM) is located about 2 miles east of the city of Homer, AK. The airport has 2 runways for commercial and general aviation. Runway 22 is asphalt, 6,701 feet long, 150 feet wide with a touchdown zone elevation of 74 feet. The runway is served by a visual approach slope indicator system (VASI) with a 3 degree glide path on the left side of the runway, and a medium intensity approach light system with runway alignment indicator lights (MALSR).

FLIGHT RECORDERS

The cockpit voice recorder (CVR), an L-3/Fairchild model FA2100-1020, serial number 356941, was removed from the airplane and downloaded at the NTSB Vehicle Recorder Laboratory. The CVR contained 2 hours, 4 minutes of recording on 4 audio channels. The audio quality of each channel was characterized excellent, and the recording included events from the entire flight beginning with ground operations prior to departure from ANC. Timing on the transcript was established by adjusting CVR elapsed time to align with crew reported off time in ANC.

The FDR, a Loral/Fairchild F1000, S703-1000-00 64 wps, serial number 000386321, was removed from the aircpane and downloaded at the NTSB Vehicle Recorder Laboratory. During removal from the aircraft, the FDR was found with the total pressure line disconnected. The FDR arrived in good condition and contained approximately 90 hours of data which was extracted normally. The Pneumatic Indicated Airspeed parameter exhibited characteristics similar to static pressure. A test by the manufacturer indicated the recorder was fully functional. Correlation of the FDR data to event local time, Alaska daylight time, was established by aligning the FDR microphone clicks with the radio transmissions observed on the CVR.

TESTS AND RESEARCH

Post-accident tests included placing the aircraft on jacks, performing a normal operation of the landing gear, and an operational check of the safety switch on the right main landing gear and the ground mode override function of the safety switch. All tests indicated normal operation and no anomalies were noted.

T not information			
Certificate:	Airline transport; Flight instructor	Age:	34
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	March 21, 2013
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 5, 2013
Flight Time:	7609 hours (Total, all aircraft), 6639 hours (Pilot In Command, all aircraft), 134 hours (Last 90 days, all aircraft), 66 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Pilot Information

Co-pilot Information

Certificate:	Airline transport	Age:	58
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	April 1, 2013
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 9, 2013
Flight Time:	2337 hours (Total, all aircraft), 383 hours (Total, this make and model), 1581 hours (Pilot In Command, all aircraft), 204 hours (Last 90 days, all aircraft), 83 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N575U
Model/Series:	1900C C	Aircraft Category:	Airplane
Year of Manufacture:	1990	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	UC-93
Landing Gear Type:	Retractable - Tricycle	Seats:	
Date/Type of Last Inspection:	October 4, 2013 Continuous airworthiness	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	29841 Hrs as of last inspection	Engine Manufacturer:	P&W CANADA
ELT:	Installed, not activated	Engine Model/Series:	PT6A-65B
Registered Owner:	ICECAP LLC TRUSTEE	Rated Power:	1173 Horsepower
Operator:	ERA AVIATION INC	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:	ERA Alaska	Operator Designator Code:	ERAA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAH0,84 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	5 knots / None	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	70°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	6°C / -3°C
Precipitation and Obscuration:			
Departure Point:	Anchorage, AK (KANC)	Type of Flight Plan Filed:	IFR
Destination:	Homer, AK (KHOM)	Type of Clearance:	IFR
Departure Time:	13:00 Local	Type of Airspace:	

Airport Information

Airport:	Homer Airport HOM	Runway Surface Type:	Asphalt
Airport Elevation:	84 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	6701 ft / 150 ft	VFR Approach/Landing:	Straight-in

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	13 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	15 None	Latitude, Longitude:	59.645557,-151.476669(est)

Administrative Information

Investigator In Charge (IIC):	Helson, David
Additional Participating Persons:	
Original Publish Date:	September 2, 2015
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=88290

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.