



Aviation Investigation Final Report

Location:	Los Alamos, New Mexico	Accident Number:	CEN14FA077
Date & Time:	December 8, 2013, 08:10 Local	Registration:	N80MF
Aircraft:	AVIAT AIRCRAFT INC A-1C-200	Aircraft Damage:	Destroyed
Defining Event:	Loss of control in flight	Injuries:	2 Fatal
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot and passenger were on a cross-country flight and stopped at an en route airport. After waiting for weather to improve, they took off to the west. A witness reported seeing the airplane depart the runway and then enter a steep left turn, before descending and impacting terrain. The airport directory noted that all landings are to the west, and all takeoffs to the east. A commuter pilot reported that the accident pilot asked him if east takeoffs and west landings were mandatory. The commuter pilot responded that he believed it was but that the commuter crew had permission from the airport manager to depart to the west, if needed. The commuter pilot added that if they departed to the west, they would make a turn before the terminal building. The automated weather reporting station, located on the field recorded about 5 minutes after the accident, the wind from 270 degrees at 12 knots, gusting to 23 knots. An examination of the wreckage did not reveal any preimpact abnormality with the engine or airframe.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of airplane control while maneuvering after takeoff in gusty wind conditions.

Findings

Personnel issues	(general) - Pilot
Environmental issues	Gusts - Effect on operation
Aircraft	(general) - Not attained/maintained

Factual Information

History of Flight

Takeoff	Other weather encounter
Takeoff	Loss of control in flight (Defining event)
Uncontrolled descent	Collision with terr/obj (non-CFIT)

On December 8, 2013 about 0810 mountain standard time (MST), an Aviat Aircraft Inc., "Husky", A-1C-200 airplane, N80MF, impacted terrain near the Los Alamos County Airport (KLAM), Los Alamos, New Mexico. The private pilot rated pilot and passenger were fatally injured. The airplane was destroyed. The airplane was registered to Blackhawk Leasing LLC, Harmony, Minnesota, and operated by a private individual. Visual meteorological conditions prevailed and a flight plan was not filed for the 14 Code of Federal Regulations Part 91 cross-country flight. The flight was originating from KLAM at the time of the accident.

The flight originally departed from Harmony, Minnesota, three days earlier, with a planned stop in Iowa, to pick up the passenger, before going to Denver, and then to their final destination of Chandler, Arizona. The flight landed at KLAM due to poor weather en route.

Refueling records indicated that the airplane was filled with 32 gallons of fuel on the afternoon of December 7, 2013.

The crew of a small commuter plane reported talking to the accident pilot and passenger the morning of the accident flight. The commuter crew reported arrived on the morning of December 8, and that the runway had ½ to 1 inch of snow on it. While getting ready for their departure, the commuter pilot recalled that accident pilot asked via radio, if the east takeoff and west landings were mandatory. The commuter pilot responded that he believed it was, but that the commuter crew had permission from the airport manager to depart west, if needed. The commuter pilot added if they departed to the west, they would make a turn before the terminal building. The accident pilot responded, "that makes sense, thank you". Shortly after their departure, the commuter crew heard the accident pilot announce his taxi on runway 27.

There were no reported distress calls from the pilot.

Two witnesses reported seeing the airplane. The first witness reported seeing the airplane appear out of whirling snow and then make a 180-degree turn. The other witness reported seeing the airplane about 100 feet in the air; it then made a steep left bank turn before disappearing from sight.

Pilot Information

Certificate:	Private	Age:	51
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Unknown	Last FAA Medical Exam:	January 7, 2011
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 500 hours (Total, all aircraft), 100 hours (Total, this make and model)		

Pilot-rated passenger Information

Certificate:	Private	Age:	52
Airplane Rating(s):	Single-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	June 5, 2013
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 151 hours (Total, all aircraft)		

The pilot held a private pilot certificate with a rating for airplane single engine land. The pilot's last class 3 medical exam was conducted on January 7, 2011, and had the limitation "must have available glasses for near vision." At the time of the exam, the pilot reported his flight experience as 500 total and 100 hours in last six months.

The passenger held a private pilot certificate with a rating for airplane single engine land. The passenger's last class 3 medical exam was conducted on June 5, 2013. At the time of the exam, the passenger reported his flight experience as 151 total hours and 2.5 hours in last six months.

Aircraft and Owner/Operator Information

Aircraft Make:	AVIAT AIRCRAFT INC	Registration:	N80MF
Model/Series:	A-1C-200	Aircraft Category:	Airplane
Year of Manufacture:	2012	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3156
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	IO-360-A1D6
Registered Owner:	BLACKHAWK LEASING LLC	Rated Power:	200 Horsepower
Operator:	BLACKHAWK LEASING LLC	Operating Certificate(s) Held:	None

Aviat Husky is a tandem two-seat, high wing airplane. The structure is steel tube frame and fabric covered fuselage. The airplane was powered by 200 horsepower (hp) Lycoming IO-360-A1D6 reciprocating engine, driving an MT, 3 bladed constant speed propeller. Flight controls are installed at each seat. The accident airplane was manufactured in 2012, and received its standard airworthiness certificate on July 2, 2012. A review of Federal Aviation Administration (FAA) records revealed the pilot purchased the airplane on July 2, 2012.

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLAM	Distance from Accident Site:	
Observation Time:	08:15 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / 23 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.78 inches Hg	Temperature/Dew Point:	-3°C / -13°C
Precipitation and Obscuration:			
Departure Point:	Los Alamos, NM (KLAM)	Type of Flight Plan Filed:	Unknown
Destination:	Chandler, AZ	Type of Clearance:	None
Departure Time:	08:10 Local	Type of Airspace:	

At 0815, the automated weather observation facility located at KLAM, reported wind from 270 degrees at 12 knots, gusting to 23 knots, visibility 10 miles, a clear sky, temperature 26 Fahrenheit (F), dew point 14 F, and a barometric pressure of 29.78 inches of mercury.

Airport Information

Airport:	Los Alamos Airport KLAM	Runway Surface Type:	Asphalt
Airport Elevation:	7171 ft msl	Runway Surface Condition:	Snow
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	6000 ft / 120 ft	VFR Approach/Landing:	None

The Los Alamos (KLAM) airport is a public-use, non-towered airport. Pilots are to use the common traffic advisory frequency (CTAF), for communications. The airport has a single 6,000 feet by 120 feet runway aligned east-west (09 and 27). The facility directory notes all landings are to the west and all takeoffs to the east. The airport also has a restricted area (R-5101) on the south side that is continually active from the surface to 12,000 feet mean sea level; as a result, west go-arounds or missed approaches are to turn right, to avoid the restricted area.

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal	Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Fatal	Latitude, Longitude:	35.877498,-106.269165

The accident site was located about 900 feet south of the airport's runway, in a lightly wooded ravine. The wreckage area consisted of several impact/ground scars about 25 feet in front of the wreckage. The airplane came to rest in an upright position, turned about 180-degrees and facing the first impact point; on a westerly heading. A post-crash fire consumed much of the airplane. Control continuity was established at each control surface, except the left side flap cable was broken. The broken section was removed for further examination. Each blade from 3-bladed wood propeller was splintered and separated before the propeller hub. After initial documentation and examination of the wreckage site, the engine was removed for examination at a nearby facility.

Medical and Pathological Information

The Office of the Medical Investigator, Albuquerque, New Mexico conducted an autopsy on the pilot and pilot rated passenger. The cause of death on both occupants was determined to be, "blunt force injuries".

The FAA Bioaeronautical Sciences Research Laboratory, Oklahoma City, Oklahoma, conducted toxicologically testing on the on both occupants. The specimens were negative for carbon monoxide and ethanol. The test on the pilot was positive for diphenhydramine in the urine and blood (0.198 ug/ml, ug/g).

Diphenhydramine is a nonprescription antihistamine and is generally used to treat the symptoms of allergies and the common cold. The drug contains a warning that is may impair mental and/or physical ability required for the performance of potentially hazardous tasks (e.g. driving, operating heavy machinery). Diphenhydramine is marketed under the trade name Benadryl.

TEST and RESEARCH

The section of broken flap cable was sent the NTSB Materials Lab, in Washington, D.C. for examination. The exam found the fractured ends were frayed; some of the cable wires exhibited necking and other wires a slant fracture. The broken cable was consistent with a tensile over stress fracture, under

a high strain rate.

The engine was removed from the airframe wreckage and examined off site. The engine had sustained both impact and fire damage. Both magnetos were thermally damaged along with the fuel pump, and could not be examined. The engine was rotated by hand; a thumb compression test was done on each cylinder. Engine and valve train continuity was confirmed. Each cylinder was borescoped; no preimpact abnormalities were no found with the engine that would have prevented normal operation.

Administrative Information

Investigator In Charge (IIC):	Hatch, Craig
Additional Participating Persons:	Howard R Dunn; FAA FSDO; Albuquerque, NM Troy Helgeson; Lycoming Aircraft Engines; Denver, CO
Original Publish Date:	November 17, 2014
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=88525

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).