



# Aviation Investigation Final Report

---

<b>Location:</b>	Oglesby, Texas	<b>Accident Number:</b>	CEN14LA174
<b>Date &amp; Time:</b>	March 30, 2014, 11:30 Local	<b>Registration:</b>	N147WT
<b>Aircraft:</b>	Bell 47G 3B	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Powerplant sys/comp malf/fail	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Aerial observation		

---

## Analysis

The pilot reported that, during an en route climb in the helicopter, he increased the throttle and noticed a "slight resistance." Shortly after, the throttle freed up, but it was ineffective; there was no corresponding change in engine power when he moved the throttle control. Both the engine and rotor rpm were indicating in the green, but they began to decrease when he adjusted the collective. When he stopped moving the collective, the engine and rotor rpm increased rapidly and continued to accelerate. The pilot initiated an autorotation and cut off the fuel. The pilot then increased the collective, and the helicopter yawed left, touched down, and rolled over to the right, which resulted in the tailboom separating.

A postaccident examination of the helicopter revealed that the throttle control adapter had disconnected from the serrated shaft on the carburetor. The retention screws on the throttle control adapter were not safety wired to the carburetor idle stop lever as required in the helicopter manufacturer's maintenance manual. A review of maintenance records revealed that the carburetor was removed and replaced about 1 1/2 years before the accident and that the helicopter's last annual inspection was conducted about 4 1/4 months before the accident.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Maintenance personnel's failure to safety wire the throttle control adapter per maintenance instructions when the carburetor was replaced and to detect that the adapter was not safety wired during the annual inspection, which resulted in the throttle control disconnecting and subsequent loss of engine control.

## Findings

---

<b>Personnel issues</b>	Installation - Maintenance personnel
<b>Aircraft</b>	(general) - Incorrect service/maintenance
<b>Aircraft</b>	(general) - Incorrect service/maintenance
<b>Personnel issues</b>	Scheduled/routine inspection - Maintenance personnel

## Factual Information

### History of Flight

<b>Maneuvering-low-alt flying</b>	Powerplant sys/comp malf/fail (Defining event)
<b>Autorotation</b>	Loss of control in flight
<b>Landing-flare/touchdown</b>	Roll over

On March 30, 2014, about 1130 central daylight time, a Bell 47G-3B helicopter, N147WT, rolled over during an autorotation near Oglesby, Texas. The pilot and passenger were not injured. The helicopter was registered to and operated by Lazy 7 Agricultural Services LLC as a 14 Code of Federal Regulations Part 91 aerial observation flight. Visual meteorological conditions prevailed for the flight, which was not operated on a flight plan. The local flight originated from the Gatesville Municipal Airport (GOP), Gatesville, Texas at 1100.

The pilot reported the purpose of the flight was to spot wildlife. He stated that during the flight he initiated a climb to transit from one area to another. As he increased the throttle he noticed a "slight resistance." Shortly thereafter, the throttle freed up, but there was no response to the throttle movements. The pilot stated that both the engine and rotor rpm were indicating in the green, but the rotor and engine rpm decayed when he increased the collective. When he stopped increasing the collective, the rotor and engine rpm increased rapidly and continued to accelerate. The pilot initiated an autorotation, during which time he cutoff the fuel. During the final collective application to cushion the landing, the helicopter suddenly yawed to the left and simultaneously rolled to the right on touchdown.

A postaccident examination of the helicopter revealed the throttle control adapter had disconnected from the serrated shaft on the carburetor. The retention screws on the throttle control adapter were not safety wired to the carburetor idle stop lever as required in the Bell Helicopter maintenance manual.

Service Bulletin 131SB was issued on December 2, 1960, which addressed the reworking the adapter screw holes and safety wiring of the adapter to the carburetor idle stop lever. This Service Bulletin addressed the Bell 47G-2 and 47J-2 models. The maintenance manual for the 47G-3B was later revised to reflect the information in the Service Bulletin. Maintenance records show the carburetor was removed and replaced on September 25, 2012, and the last annual inspection was performed November 11, 2013.

## Pilot Information

<b>Certificate:</b>	Airline transport; Flight instructor	<b>Age:</b>	41
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Helicopter; Instrument helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	May 7, 2013
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	3800 hours (Total, all aircraft), 54 hours (Total, this make and model), 3000 hours (Pilot In Command, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Bell	<b>Registration:</b>	N147WT
<b>Model/Series:</b>	47G 3B	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>	1964	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	2920
<b>Landing Gear Type:</b>	N/A; Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	November 5, 2013 Annual	<b>Certified Max Gross Wt.:</b>	2950 lbs
<b>Time Since Last Inspection:</b>	30 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	3280 Hrs at time of accident	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Installed, activated	<b>Engine Model/Series:</b>	TVO-435-B1
<b>Registered Owner:</b>	LAZY 7 AGRICULTURAL SERVICES LLC	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	LAZY 7 AGRICULTURAL SERVICES LLC	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	TPL,682 ft msl	<b>Distance from Accident Site:</b>	11 Nautical Miles
<b>Observation Time:</b>	12:15 Local	<b>Direction from Accident Site:</b>	160°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	15 knots / 21 knots	<b>Turbulence Type Forecast/Actual:</b>	/ None
<b>Wind Direction:</b>	170°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.19 inches Hg	<b>Temperature/Dew Point:</b>	22°C / 8°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Gatesville, TX (GOP )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Gatesville, TX (GOP )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	11:00 Local	<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	31.311388,-97.361114(est)

## Administrative Information

**Investigator In Charge (IIC):** Sullivan, Pamela  
**Additional Participating Persons:** Chris Doherty; FAA; Irving, TX

**Original Publish Date:** June 1, 2015

**Last Revision Date:**

**Investigation Class:** [Class](#)

**Note:**

**Investigation Docket:** <https://data.ntsb.gov/Docket?ProjectID=88989>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).