



# **Aviation Investigation Final Report**

Location:	Punta Gorda, Florida	Accident Number:	ERA14CA229
Date & Time:	April 27, 2014, 15:00 Local	Registration:	N543MG
Aircraft:	GINGRAS MICHEL AVENTURA II	Aircraft Damage:	Substantial
Defining Event:	Low altitude operation/event	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

# Analysis

The pilot of the float-equipped airplane stated the purpose of the flight was to "scout for fish." While flying 30 feet above the water the airplane encountered a "huge gust of wind" and then bounced off the water surface multiple times. The pilot applied full power to reestablish flight but the right pontoon contacted the water and the airplane "ground looped." Examination of the airplane by a Federal Aviation Administration inspector revealed substantial damage to the vertical stabilizer. The pilot reported there were no mechanical malfunctions or anomalies that could have precluded normal operation.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain clearance from the water while operating at a low altitude.

#### Findings

Aircraft	Altitude - Not attained/maintained
Personnel issues	Aircraft control - Pilot
Environmental issues	Gusts - Contributed to outcome

# **Factual Information**

# History of Flight

Maneuvering-low-alt flying	Low altitude operation/event (Defining event)
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)

#### **Pilot Information**

Certificate:	Private	Age:	69
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 12, 2013
Flight Time:	1386.3 hours (Total, all aircraft), 33.7 hours (Total, this make and model), 1386.3 hours (Pilot In Command, all aircraft), 9.8 hours (Last 90 days, all aircraft), 3.7 hours (Last 30 days, all aircraft), 3.7 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	GINGRAS MICHEL	Registration:	N543MG
Model/Series:	AVENTURA II	Aircraft Category:	Airplane
Year of Manufacture:	2009	Amateur Built:	Yes
Airworthiness Certificate:	Experimental light sport (Special)	Serial Number:	AA2A0148
Landing Gear Type:	Tailwheel; Amphibian	Seats:	2
Date/Type of Last Inspection:	October 5, 2013 Condition	Certified Max Gross Wt.:	1430 lbs
Time Since Last Inspection:	35 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	441 Hrs at time of accident	Engine Manufacturer:	ROTAX
ELT:	Installed, not activated	Engine Model/Series:	912ULS
Registered Owner:	CLAUS DONNA M	Rated Power:	0 Horsepower
Operator:	John Keyworth	Operating Certificate(s) Held:	None

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PGD,26 ft msl	Distance from Accident Site:	14 Nautical Miles
Observation Time:	18:53 Local	Direction from Accident Site:	200°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.96 inches Hg	Temperature/Dew Point:	32°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	PUNTA GORDA, FL (PGD )	Type of Flight Plan Filed:	None
Destination:	PUNTA GORDA, FL (PGD )	Type of Clearance:	VFR
Departure Time:	14:00 Local	Type of Airspace:	Class E

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	26.722221,-82.07389(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Stein, Stephen
Additional Participating Persons:	Robert Donahue; FAA/FSDO; Tampa Bay, FL
Original Publish Date:	July 30, 2014
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=89186

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.