

Aviation Investigation Final Report

Location: Rigby, Idaho Accident Number: WPR14CA352

Date & Time: August 22, 2014, 11:30 Local Registration: N171CT

Aircraft: RANS AIRCRAFT S 6S Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 2 Minor

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The light sport flight instructor was providing flight instruction to the owner of the experimental, amateur-built, tailwheel-equipped light sport airplane. The airplane was equipped with side-by-side seating; the owner sat in the left seat and was the flying pilot, and the instructor sat in the right seat. They departed the home, non-towered airport and flew uneventfully to an airport with an operating air traffic control tower, where they practiced landings and takeoffs. They then returned to the home airport for additional landings and takeoffs. All portions of the flight through that point were uneventful. After returning to, and making at least one landing back at the home airport, the pilot was attempting a takeoff from runway 19. Either at or shortly after liftoff, the airplane was struck by an "unexpected wind gust," which resulted in a loss of directional control. The student pilot was unable to regain control, and the flight instructor did not physically intervene, before the airplane struck a hangar located about 270 feet from the runway centerline. The right wing sustained substantial damage when it struck the hangar. The airplane then passed between that hangar and an adjacent one. The flight instructor did not offer any explanation as to why he did not intervene. The measured wind at an airport located about 10 miles southwest of the accident airport was reported as 320 degrees at 8 knots about 37 minutes prior to the accident, and as 090 degrees at 3 knots about 23 minutes after the accident.

The pilot reported no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's loss of directional control during takeoff in gusting wind conditions. Contributing to the accident was the flight instructor's failure to intervene and apply corrective flight control inputs.

Findings

Personnel issues Aircraft control - Student/instructed pilot

Personnel issues Lack of action - Instructor/check pilot

Environmental issues Gusts - Effect on operation

Aircraft Directional control - Not attained/maintained

Environmental issues Residence/building - Contributed to outcome

Page 2 of 6 WPR14CA352

Factual Information

History of Flight

Takeoff	Loss of control in flight (Defining event)
Takeoff	Runway excursion
Takeoff	Attempted remediation/recovery
Takeoff	Collision with terr/obj (non-CFIT)

Flight instructor Information

Certificate:	Flight instructor; Private	Age:	58
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	Sport pilot	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	August 23, 2013
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 1, 2013
Flight Time:	1587 hours (Total, all aircraft), 87 hours (Total, this make and model), 1400 hours (Pilot In Command, all aircraft), 57 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft)		

Student pilot Information

·			
Certificate:	Student	Age:	66
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Sport pilot	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	21 hours (Total, all aircraft), 21 hours (Total, this make and model), 5 hours (Pilot In Command, all aircraft), 13 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR14CA352

Aircraft and Owner/Operator Information

Aircraft Make:	RANS AIRCRAFT	Registration:	N171CT
Model/Series:	S 6S SUPERSIX	Aircraft Category:	Airplane
Year of Manufacture:	2005	Amateur Built:	
Airworthiness Certificate:	Experimental light sport (Special)	Serial Number:	11021467
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 10, 2014 Annual	Certified Max Gross Wt.:	1200 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	468 Hrs as of last inspection	Engine Manufacturer:	ROTAX
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	912S
Registered Owner:	On file	Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KIDA,4744 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	10:53 Local	Direction from Accident Site:	225°
Lowest Cloud Condition:	Thin Overcast / 10000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Overcast / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/ Unknown
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	/ Unknown
Altimeter Setting:	30.07 inches Hg	Temperature/Dew Point:	14°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Idaho Falls, ID (KIDA)	Type of Flight Plan Filed:	None
Destination:	Rigby, ID (U56)	Type of Clearance:	None
Departure Time:	11:15 Local	Type of Airspace:	

Page 4 of 6 WPR14CA352

Airport Information

Airport:	Rigby U56	Runway Surface Type:	Asphalt
Airport Elevation:	4845 ft msl	Runway Surface Condition:	Dry
Runway Used:	19	IFR Approach:	None
Runway Length/Width:	3500 ft / 50 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	2 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	43.642501,-111.929443(est)

Page 5 of 6 WPR14CA352

Administrative Information

Investigator In Charge (IIC):	Huhn, Michael
Additional Participating Persons:	Gregory Pire; FAA; Salt Lake City, UT
Original Publish Date:	November 13, 2014
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=89933

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR14CA352