



# Aviation Investigation Final Report

<b>Location:</b>	Bloomington, Indiana	<b>Accident Number:</b>	CEN14LA504
<b>Date &amp; Time:</b>	September 18, 2014, 11:45 Local	<b>Registration:</b>	N516SW
<b>Aircraft:</b>	SACCIO THOMAS A SEAWIND 3000	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>	Fire/smoke (non-impact)	<b>Injuries:</b>	2 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot and one passenger were on a cross-country flight in a single-engine amphibian airplane. The pilot reported to an airport tower air traffic controller that the airplane had a low fuel pressure indication and that he planned to fly directly to the airport. However, the airplane impacted terrain about 3 miles north of the airport. One witness reported seeing the airplane on fire before it crashed. A postcrash fire consumed most of the composite-frame airplane.

An examination of the engine's accessories was not performed due to fire and thermal damage. Although the engine sustained fire damage, compression and continuity through the engine drive train was established, and no preimpact abnormalities were noted. A section of an alternator cable and a section of a fuel line that had signatures consistent with fraying and thermal damage, respectively, were examined to determine if chafing and electrical arcing had occurred between them. However, the examined sections exhibited no evidence of chafing and arcing. The accident is consistent with an in-flight fire; however, the source of the fire could not be determined because the examination did not reveal any preimpact abnormalities.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

An in-flight fire for reasons that could not be determined because the examination of the airplane did not reveal the source of the fire.

## Findings

---

**Not determined**

(general) - Unknown/Not determined

## Factual Information

### History of Flight

<b>Enroute</b>	Unknown or undetermined
<b>Enroute</b>	Fire/smoke (non-impact) (Defining event)
<b>Emergency descent</b>	Collision with terr/obj (non-CFIT)
<b>Post-impact</b>	Fire/smoke (post-impact)

On September 18, 2014, about 1145 central daylight time, a kit-built Seawind 3000 seaplane, N516SW, impacted terrain near Bloomington, Indiana. The private rated pilot and pilot rated passenger were fatally injured, and the seaplane was destroyed. The seaplane was registered to and operated by a private individual under the provisions of 14 Code of Federal Regulations Part 91 as a personal flight. Visual meteorological conditions prevailed and a flight plan was not filed.

The pilot contacted the control tower operator at Monroe Country Airport (KBMG) and reported he had a low fuel pressure indicator problem and they planned to fly directly to the airport.

Several witnesses reported seeing the seaplane flying, with one witness noting that the seaplane was on fire prior to the aircraft impacting terrain.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	72
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea	<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Unknown
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	November 21, 2012
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	765 hours (Total, all aircraft)		

## Passenger Information

<b>Certificate:</b>		<b>Age:</b>	51
<b>Airplane Rating(s):</b>		<b>Seat Occupied:</b>	Unknown
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	Unknown
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>		<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

The pilot held a private pilot certificate with ratings for airplane single-engine land and sea. He also held instrument-airplane and repairman experimental aircraft builder ratings. The pilot's last class 3 medical exam was conducted on November 21, 2012. At the time of the exam, the pilot reported his flight experience as 765 total flight hours and 20 hours in last six months.

The passenger held a private pilot certificate with ratings for airplane single-engine land and sea. The passenger's last class 3 medical exam was conducted on December 12, 2012. At the time of the exam, the passenger reported his flight experience as 3,400 total flight hours and 50 hours in last six months.

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	SACCIO THOMAS A	<b>Registration:</b>	N516SW
<b>Model/Series:</b>	SEAWIND 3000	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2007	<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	061
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	
<b>Date/Type of Last Inspection:</b>	Unknown	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>		<b>Engine Model/Series:</b>	IO-540-K1A5
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	300 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

The Seawind is a kit built, composite structure, four seat, amphibian airplane, with a single tail-mounted engine. The airplane was powered by a 300 horsepower (HP) Lycoming IO-540-K1A5 reciprocating engine, which drove a Hartzell, 3 blade, constant speed propeller. A review of Federal Aviation Administration (FAA) records revealed the accident airplane received its special airworthiness certificate in the experimental amateur-built category on September 20, 2007.

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KBMG	<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>	11:53 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	110°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.09 inches Hg	<b>Temperature/Dew Point:</b>	20°C / 10°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Madison, WI (KMSN)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Bloomington, IN (KBMG)	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>		<b>Type of Airspace:</b>	

At 1153, the automated weather observation facility located at KBMG, reported wind from 110 degrees at 4 knots, visibility 10 miles, a clear sky, temperature 68 Fahrenheit (F), dew point 50 F, and a barometric pressure of 30.09 inches of mercury.

## Airport Information

<b>Airport:</b>	Monroe County Airport KBMG	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	845 ft msl	<b>Runway Surface Condition:</b>	Unknown
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing;Precautionary landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>	1 Fatal	<b>Aircraft Fire:</b>	Both in-flight and on-ground
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	Unknown
<b>Total Injuries:</b>	2 Fatal	<b>Latitude, Longitude:</b>	39.164722,-86.618888(est)

The seaplane impacted terrain about 3 miles north of KBMG, in a lightly wooded area. A post-crash fire consumed much of the composite structure. Several pieces of composite material were located along the airplane's flight path; the material pieces had evidence of burn areas, consistent with an in-flight fire. After an initial documentation and examination of the wreckage site, the wreckage was removed for examination at a nearby facility.

## Medical and Pathological Information

The Lawrence County Coroner's Office, Bedford, Indiana, conducted an autopsy on the pilot and pilot rated passenger. The cause of death on both occupants was determined to be injuries sustained in an aircraft crash.

The FAA Bioaeronautical Sciences Research Laboratory, Oklahoma City, Oklahoma, conducted toxicologically testing on the on both occupants. The specimens were negative for tested items.

### TEST and RESEARCH

Examination of the airplane was conducted; the fire had destroyed the majority of the airplane. The engine's 3-bladed propeller remained attached to the crankshaft. All three blades exhibited signs of fire/thermal damage, with one blade missing the outboard tip. One blade exhibited slight aft bending, starting about 12 inches from the tip. The engine's fuel servo and fuel pump were destroyed by the fire, and identification part and serial numbers could not be found. The fuel flow divider was disassembled and had suffered thermal damage to the diaphragm. The fuel nozzles and lines to the flow divider were secure. Both magnetos sustained thermal damaged and could not be tested. The sparkplugs were removed and appeared to have normal wear.

On the initial attempt to rotate the engine by manually rotating the propeller, the engine would only turn about 100 degrees before binding. The accessory case was removed and a large amount of melted aluminum was found within the gear train consistent with a melted aluminum case of a magneto. The melted aluminum was removed, and the crankshaft was able to rotate. Thumb compression and valve action was confirmed at each cylinder. The rear accessory gears rotated and mechanical continuity was

established throughout the engine drive train. The fire/thermal damage limited a complete examination of the engine; however, based on the limited examination, there was no evidence of pre-impact mechanical malfunctions noted.

During the examination, an electrical wire was found within the wreckage that had signatures consistent with fraying and a piece of metal attached. A fuel line was also found in the same area of the electrical wire that had signatures consistent with thermal damage. Both pieces would have been located in the vicinity of the tail and engine nacelle, a confined area of the tail structure near the engine nacelle.

Sections of both materials were sent to the NTSB Materials Laboratory in Washington DC for further examination. The purpose of examining sections of the fuel line and electrical wire was to identify a potential source of an in-flight fire. The laboratory investigation consequently tried to find evidence of chafing and electrical arcing between the alternator cable and the fuel line. While the laboratory found some evidence of electrical arcing, the tested section was absent evidence of chafing and arcing between the two.

A source of the in-flight fire was not found.

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Hatch, Craig
<b>Additional Participating Persons:</b>	Steven A Burnham; FAA FSDO; Indianapolis , IN Judson Rupert; Lycoming engines; Williamsport, PA
<b>Original Publish Date:</b>	January 5, 2016
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=90102">https://data.ntsb.gov/Docket?ProjectID=90102</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).