



# **Aviation Investigation Final Report**

Location: Bethany Center, New York Accident Number: ERA14CA449

Date & Time: September 20, 2014, 09:15 Local Registration: N3785D

Aircraft: Cessna 182A Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

According to the pilot, he was attempting a soft field landing on runway 27. Following a stable approach and landing, a gust of wind was encountered. The airplane veered to the right and the pilot was unable to stop the airplane before the right wing struck a wind sock pole. An inspector from the Federal Aviation Administration examined the airplane and confirmed substantial damage to the right wing. The pilot reported no pre-impact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain a directional control of the airplane during gusting wind conditions.

#### **Findings**

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Effect on operation

Environmental issues Pole - Contributed to outcome

## **Factual Information**

### History of Flight

Landing-landing roll	Loss of control on ground (Defining event)
Landing-landing roll	Runway excursion
Landing-landing roll	Collision with terr/obj (non-CFIT)

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	23
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	September 4, 2014
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 27, 2014
Flight Time:	329 hours (Total, all aircraft), 18 hours (Total, this make and model), 214 hours (Pilot In Command, all aircraft), 44 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft)		

Page 2 of 5 ERA14CA449

### **Aircraft and Owner/Operator Information**

Cessna	Registration:	N3785D
182A	Aircraft Category:	Airplane
1957	Amateur Built:	
Normal	Serial Number:	34485
Tricycle	Seats:	4
August 14, 2014 Annual	Certified Max Gross Wt.:	2950 lbs
30 Hrs	Engines:	1 Reciprocating
3900 Hrs as of last inspection	Engine Manufacturer:	CONT MOTOR
Installed, not activated	Engine Model/Series:	0-470 SERIES
On file	Rated Power:	230 Horsepower
On file	Operating Certificate(s) Held:	None
	182A 1957 Normal Tricycle August 14, 2014 Annual 30 Hrs 3900 Hrs as of last inspection Installed, not activated On file	182A Aircraft Category:  1957 Amateur Built:  Normal Serial Number:  Tricycle Seats:  August 14, 2014 Annual Certified Max Gross Wt.:  30 Hrs Engines:  3900 Hrs as of last inspection Engine Manufacturer:  Installed, not activated Engine Model/Series:  On file Rated Power:  On file Operating Certificate(s)

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ROC,558 ft msl	Distance from Accident Site:	23 Nautical Miles
Observation Time:	08:54 Local	Direction from Accident Site:	30°
<b>Lowest Cloud Condition:</b>	Few / 6000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 25000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 17 knots	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	18°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Batavia, NY (GVQ )	Type of Flight Plan Filed:	None
Destination:	Bethany Center, NY (8NK4)	Type of Clearance:	None
Departure Time:	09:00 Local	Type of Airspace:	

Page 3 of 5 ERA14CA449

### **Airport Information**

Airport:	Bethany Airpark 8NK4	Runway Surface Type:	Grass/turf
Airport Elevation:	1000 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	2800 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.943332,-78.138336(est)

Page 4 of 5 ERA14CA449

#### **Administrative Information**

Investigator In Charge (IIC):	Hicks, Ralph
Additional Participating Persons:	
Original Publish Date:	October 9, 2014
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=90127

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ERA14CA449