



Aviation Investigation Final Report

Location: Rancho Murieta, California Accident Number: WPR14CA397

Date & Time: September 28, 2014, 10:05 Local Registration: N8129P

Aircraft: Piper PA 24-250 Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The pilot, who held a private pilot certificate, stated that the purpose of the flight was for him to acquire hours in the airplane with a certified flight instructor (CFI) for insurance purposes. They departed from the airplane's base to a nearby airport to practice landings. After completing about two landings, the pilot configured the airplane for a short field takeoff. During the takeoff roll, he waited for the airplane to reach rotation speed and shortly thereafter they were airborne. The airplane immediately began to veer to the left and subsequently stalled. The airplane came to rest about 50 yards off the runway surface.

As a result of the impact, the airplane sustained substantial damage to the wings. The pilot stated that there were no pre impact mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's failure to maintain adequate airspeed during takeoff and the certified flight instructors delayed remedial action, which resulted in the stall.

Findings

Personnel issues	Aircraft control - Student/instructed pilot
Personnel issues	Delayed action - Instructor/check pilot

Page 2 of 6 WPR14CA397

Factual Information

History of Flight

Takeoff	Loss of control in flight (Defining event)

Student pilot Information

Certificate:	Private	Age:	53
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	July 18, 2013
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	277 hours (Total, all aircraft), 3 hours (Total, this make and model), 202 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	69
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	June 9, 2014
Occupational Pilot:	No Last Flight Review or Equivalent:		
Flight Time:	2874 hours (Total, all aircraft), 21 hours (Total, this make and model), 2700 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR14CA397

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8129P
Model/Series:	PA 24-250 250	Aircraft Category:	Airplane
Year of Manufacture:	1963	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-3382
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:	April 19, 2014 Annual	Certified Max Gross Wt.:	2899 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2438 Hrs	Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	O-540-A1D5
Registered Owner:	On file	Rated Power:	250 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ Clear air
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	18°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Placerville, CA (KPVF)	Type of Flight Plan Filed:	None
Destination:	Rancho Murieta, CA (RIU)	Type of Clearance:	None
Departure Time:	09:00 Local	Type of Airspace:	

Page 4 of 6 WPR14CA397

Airport Information

Airport:	RANCHO MURIETA RIU	Runway Surface Type:	Asphalt
Airport Elevation:	144 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	3798 ft / 75 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	38.486667,-121.102775(est)

Page 5 of 6 WPR14CA397

Administrative Information

Investigator In Charge (IIC):	Keliher, Zoe
Additional Participating Persons:	Debbie Murray; Federal Aviation Administration; Sacramento, CA
Original Publish Date:	January 12, 2015
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=90184

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR14CA397