



Aviation Investigation Final Report

Location: Palmer, Alaska **Accident Number**: ANC15CA019

Date & Time: April 1, 2015, 14:15 Local Registration: N3885Q

Aircraft: Cessna A185F Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot was landing to the south on a gravel runway in his tailwheel-equipped Cessna 185 airplane. During the landing rollout, a wind gust from the east was encountered and the pilot was unable to maintain directional control. The airplane entered a ground loop, sustaining substantial damage to the right wing. The pilot stated there were no preaccident mechanical malfunctions or anomalies with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's loss of directional control during landing, resulting in a collision with terrain.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Factual Information

History of Flight

Landing	Loss of control on ground (Defining event)

Pilot Information

Certificate:	Private	Age:	56
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	May 23, 2014
Occupational Pilot:	No	Last Flight Review or Equivalent:	February 11, 2015
Flight Time:	(Estimated) 111 hours (Total, all aircraft), 111 hours (Total, this make and model), 49 hours (Pilot In Command, all aircraft), 28 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N3885Q
Model/Series:	A185F F	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18502207
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	October 16, 2014 100 hour	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1020.3 Hrs at time of accident	Engine Manufacturer:	Continental Motors
ELT:	C126 installed, not activated	Engine Model/Series:	IO-520D
Registered Owner:	CRUZ DAVID C	Rated Power:	300 Horsepower
Operator:	CRUZ DAVID C	Operating Certificate(s) Held:	None

Page 2 of 4 ANC15CA019

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAAQ,242 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	18 knots /	Turbulence Type Forecast/Actual:	/ Unknown
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/ Unknown
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	4°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SKWENTNA, AK (SKW)	Type of Flight Plan Filed:	VFR
Destination:	Palmer, AK (PAQ)	Type of Clearance:	VFR
Departure Time:	12:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	PALMER MUNI PAQ	Runway Surface Type:	Gravel
Airport Elevation:	242 ft msl	Runway Surface Condition:	Rough
Runway Used:	16S	IFR Approach:	None
Runway Length/Width:	1560 ft / 60 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	61.596668,-149.088058(est)

Page 3 of 4 ANC15CA019

Administrative Information

Investigator In Charge (IIC):	Williams, David
Additional Participating Persons:	
Original Publish Date:	May 13, 2015
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=90992

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC15CA019