



Aviation Investigation Final Report

Location:	Draper, Utah	Accident Number:	GAA15CA258
Date & Time:	September 9, 2015, 10:40 Local	Registration:	N253HP
Aircraft:	Airbus AS350	Aircraft Damage:	Substantial
Defining Event:	External load event (Rotorcraft)	Injuries:	2 None
Flight Conducted Under:	Public aircraft		

Analysis

The pilot reported that he and a tactical flight officer were conducting a high altitude rescue mission in "remote and nearly vertical" terrain with a public use helicopter, by doing a one-skid recovery. The purpose of this mission was to recover a fallen hiker.

A member of the three person ground recovery team had secured himself to a rescue rope that was anchored to the steep terrain above the plane-of-rotation of the main rotor system blades. Once the helicopter's right skid landed on a rock outcrop, the ground recovery team approached the helicopter to begin the loading process. During the approach to the helicopter, the rescue rope came in contact with a main rotor blade.

The pilot reported that the helicopter then, "rotated abruptly to the left and began to shake violently." The helicopter impacted terrain, the pilot regained control, and he then made an emergency landing at a lower altitude. He reported that upon applying power to land, the helicopter "began to shake violently again until touching down and reducing collective pitch." A postflight inspection revealed substantial damage to the main rotor system, the tail boom, and the empennage.

The pilot reported there were no pre-impact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The ground recovery team member's failure to secure a rescue rope during the helicopter loading process in steep terrain, resulting in the rope fouling the helicopter's main rotor system.

Findings

Personnel issues	Use of equip/system - Emergency services personnel	
Aircraft	Main rotor head system - Damaged/degraded	
Aircraft	Main rotor control - Damaged/degraded	
Environmental issues	Ground equipment - Effect on operation	

Factual Information

History of Flight	
Maneuvering-hover	External load event (Rotorcraft) (Defining event)
Emergency descent	Loss of control in flight
Emergency descent	Collision with terr/obj (non-CFIT)

Pilot Information

			/
Certificate:	Airline transport	Age:	54
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	4-point
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Helicopter; Instrument airplane; Instrument helicopter	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	March 12, 2015
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 1, 2015
Flight Time:	(Estimated) 5000 hours (Total, all aircraft), 3000 hours (Total, this make and model)		

Other flight crew Information

Certificate:	None	Age:	
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Airbus	Registration:	N253HP
Model/Series:	AS350 B3	Aircraft Category:	Helicopter
Year of Manufacture:	2013	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7533
Landing Gear Type:	High skid	Seats:	6
Date/Type of Last Inspection:	August 3, 2015 100 hour	Certified Max Gross Wt.:	5225 lbs
Time Since Last Inspection:		Engines:	1 Turbo shaft
Airframe Total Time:	834.3 Hrs at time of accident	Engine Manufacturer:	Turbomeca
ELT:	C126 installed, not activated	Engine Model/Series:	Arriel 2D
Registered Owner:	On file	Rated Power:	860 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSLC,4225 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	16:53 Local	Direction from Accident Site:	327°
Lowest Cloud Condition:	Few / 6000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.18 inches Hg	Temperature/Dew Point:	22°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SALT LAKE CITY, UT (SLC)	Type of Flight Plan Filed:	Company VFR
Destination:	SALT LAKE CITY, UT (SLC)	Type of Clearance:	VFR
Departure Time:	08:30 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	40.52639,-111.754997(est)

Administrative Information

Investigator In Charge (IIC):	Hodges, Michael
Additional Participating Persons:	Jeff Guzzetti; FAA Accident Investigation Division (AVP-100); Washington, DC
Original Publish Date:	January 15, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=91979

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.