

Aviation Investigation Final Report

Location: Pelican Lake, Wisconsin Accident Number: GAA15CA279

Date & Time: September 22, 2015, 17:00 Local Registration: N896CB

Aircraft: BRUNZLICK LARRY R SEAWIND 3000 EXPERIM Aircraft Damage: Substantial

3000 EAF EINIM

Injuries:

1 None

Flight Conducted Under: Part 91: General aviation - Personal

Abnormal runway contact

Analysis

Defining Event:

The pilot reported that he was practicing landings on a lake in his experimental amateur-built amphibious airplane. During the accident landing, he reported that the airplane "skipped slightly about 2 feet off the water, I held attitude and let it come down again but I accidentally let the left wing tip sponson settle onto the water while still going at about 55 knots." The airplane started to turn to the left, the sponson dug in more, and he reported that he did not correct the situation quickly enough. The airplane turned 180 degrees before coming to rest. Once the airplane was towed to shore, substantial damage was noticed to both wing sponsons and the rudder.

The pilot reported there were no pre-impact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Abnormal runway contact which precipitated a loss of directional control and impact with water.

Findings

| Personnel issues | Aircraft control - Pilot |
|------------------|--|
| Aircraft | Lateral/bank control - Not attained/maintained |

Page 2 of 6 GAA15CA279

Factual Information

History of Flight

| Landing-landing roll | Abnormal runway contact (Defining event) | |
|----------------------|--|--|
| Landing-landing roll | Attempted remediation/recovery | |
| Landing-landing roll | Loss of control on ground | |
| Landing-landing roll | Collision during takeoff/land | |

Pilot Information

| Certificate: | Private | Age: | 61 |
|---------------------------|---|-----------------------------------|-----------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | August 19, 2014 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | June 30, 2015 |
| Flight Time: | (Estimated) 2601 hours (Total, all aircraft), 119 hours (Total, this make and model), 2361 hours (Pilot In Command, all aircraft) | | |

Page 3 of 6 GAA15CA279

Aircraft and Owner/Operator Information

| Aircraft Make: | BRUNZLICK LARRY R | Registration: | N896CB |
|-------------------------------|-----------------------------------|-----------------------------------|---------------------------|
| Model/Series: | SEAWIND 3000 EXPERIM NO SERIES | Aircraft Category: | Airplane |
| Year of Manufacture: | 2012 | Amateur Built: | Yes |
| Airworthiness Certificate: | Normal; Experimental (Special) | Serial Number: | 093 |
| Landing Gear Type: | Amphibian | Seats: | 4 |
| Date/Type of Last Inspection: | September 17, 2015 Annual | Certified Max Gross Wt.: | 3600 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 125 Hrs at time of accident | Engine Manufacturer: | Barrett Precision Engines |
| ELT: | C126 installed, not activated | Engine Model/Series: | IO-540X |
| Registered Owner: | BRUNZLICK LARRY R. | Rated Power: | 291 Horsepower |
| Operator: | BRUNZLICK LARRY R. | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | KRHI,1624 ft msl | Distance from Accident Site: | 14 Nautical Miles |
| Observation Time: | 21:53 Local | Direction from Accident Site: | 303° |
| Lowest Cloud Condition: | | Visibility | 10 miles |
| Lowest Ceiling: | Overcast / 1800 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | / | Turbulence Type Forecast/Actual: | / None |
| Wind Direction: | | Turbulence Severity Forecast/Actual: | / N/A |
| Altimeter Setting: | 30.19 inches Hg | Temperature/Dew Point: | 18°C / 15°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | MEDFORD, WI (MDZ) | Type of Flight Plan Filed: | None |
| Destination: | Pelican Lake, WI | Type of Clearance: | None |
| Departure Time: | 16:15 Local | Type of Airspace: | Class G |

Page 4 of 6 GAA15CA279

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 45.503055,-89.196388(est) |

Page 5 of 6 GAA15CA279

Administrative Information

| Hodges, Michael |
|---|
| Timothy H Anderson; FAA Milwaukee FSDO; Milwaukee, WI |
| December 3, 2015 |
| |
| Class |
| This accident report documents the factual circumstances of this accident as described to the NTSB. |
| https://data.ntsb.gov/Docket?ProjectID=92078 |
| |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 GAA15CA279