



# **Aviation Investigation Final Report**

Location: McKinney, Texas Accident Number: CEN16LA185

Date & Time: May 13, 2016, 08:30 Local Registration: N700MJ

Aircraft: JEWETT BRANDON RV 6 Aircraft Damage: Substantial

**Defining Event:** Runway excursion **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The private-rated pilot planned a short, personal cross-country flight. The pilot reported that, as he applied engine power for the takeoff, the airplane "snapped" left. The pilot applied right rudder to correct the turn; however, the airplane continued off the left side of the runway. The pilot reduced the throttle and mixture control but could not stop the airplane before it impacted trees. The pilot reported that the direct link bar to the tailwheel and the bolts that hold the tailwheel were broken postimpact. The pilot also reported that he had 15.5 hours in the airplane make and model with 4 hours as pilot-incommand. The accident is consistent with a loss of directional control during application of engine power for takeoff.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during takeoff.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Personnel issues Total experience w/ equipment - Pilot

Page 2 of 6 CEN16LA185

#### **Factual Information**

#### **History of Flight**

Takeoff	Runway excursion (Defining event)
Takeoff	Collision with terr/obj (non-CFIT)

On May 13, 2016, about 0830 central daylight time, a kit built Vans RV-6 airplane, N700MJ, departed the runway and impacted trees during an attempted takeoff from the Aero Country Airport (T31), McKinney, Texas. The private rated pilot was not injured and the airplane was substantially damaged. The airplane was registered to and operated a private individual, under the provisions of 14 Code of Federal Regulations Part 91 as a personal flight. Day visual meteorological conditions prevailed at the time of the accident. The cross country flight was originating at the time of the accident with the intended destination of Sherman, Texas.

The pilot reported that he applied engine power for the takeoff, the airplane "snapped" left; he applied right rudder to counter the propeller torque. The airplane continued off the left side of the runway, so he reduced the throttle, and pulled the mixture control, but could not get the airplane stopped before the airplane impacted trees.

The pilot added that the direct link bar that connected to the tailwheel and the bolts that hold the tailwheel were broken post impact.

The pilot reported he had 358 total flight hours with 15.5 hours in make and model, with 4 hours as pilot-in-command.

The responding Federal Aviation Administration Inspector noted the airplane had sustained substantial damage to both wings and fuselage.

Page 3 of 6 CEN16LA185

### **Pilot Information**

Certificate:	Private	Age:	53
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	January 1, 2015
Occupational Pilot:	No Last Flight Review or Equivalent:		
Flight Time:	358 hours (Total, all aircraft), 15.5 hours (Total, this make and model), 248 hours (Pilot In Command, all aircraft), 25.7 hours (Last 90 days, all aircraft), 13.5 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	JEWETT BRANDON	Registration:	N700MJ
Model/Series:	RV 6	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	22896
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:	February 14, 2016 100 hour	Certified Max Gross Wt.:	
Time Since Last Inspection:	692 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-360
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 4 of 6 CEN16LA185

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KTKI	Distance from Accident Site:	8 Nautical Miles
Observation Time:	08:53 Local	Direction from Accident Site:	90°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.21 inches Hg	Temperature/Dew Point:	19°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	McKinney, TX (T31)	Type of Flight Plan Filed:	None
Destination:	Sherman, TX (KSWI)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

## **Airport Information**

Airport:	Aero Country Airport T31	Runway Surface Type:	Asphalt
Airport Elevation:	782 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	4352 ft / 60 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.209445,-96.743614(est)

Page 5 of 6 CEN16LA185

#### **Administrative Information**

Investigator In Charge (IIC): Hatch, Craig

Additional Participating Persons: Gregory Sheehan; FAA FSDO; Dallas, TX

Original Publish Date: December 12, 2016

Last Revision Date: Investigation Class: Class

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=93181

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN16LA185