



# Aviation Investigation Final Report

<b>Location:</b>	Fruitland, Utah	<b>Accident Number:</b>	WPR16LA114
<b>Date &amp; Time:</b>	May 20, 2016, 11:00 Local	<b>Registration:</b>	N50NE
<b>Aircraft:</b>	MICHAEL BURTON Calidus	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Turbulence encounter	<b>Injuries:</b>	2 Serious
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

After fueling the gyroplane, the private pilot and passenger embarked on a cross-country flight over rugged and mountainous terrain. The pilot reported that, as the gyroplane approached a ridge, about 200 ft above its peak, it encountered strong downdrafts and then descended into a box canyon. Unable to climb the gyroplane to clear terrain, the pilot guided it over a river at the base of the canyon until he could see a landing spot on the shore. As he approached the site and initiated the landing flare, the right wheel struck a boulder, and the gyroplane rolled over and then came to rest in the river. The canyon in which the gyroplane came to rest was at an elevation of about 7,300 ft mean sea level (msl), and the canyon walls rose about 1,000 ft above the accident site to the north and south. The gyroplane's demonstrated maximum operating altitude was 10,000 ft, and the pilot's intended flight route would have required clearing mountain peaks that were at an elevation of 8,200 ft msl.

The pilot reported that there were no mechanical malfunctions or failures with the gyroplane. Local wind conditions, along with the rugged terrain, likely resulted in mechanical turbulence and strong downdrafts along the flight route, and it is likely that the weather conditions affected the gyroplane's ability to achieve a positive climb rate. Given the weather conditions and the gyroplane's maximum operating altitude of 10,000 ft, the pilot demonstrated improper judgment by attempting such a flight. The pilot stated that he could have avoided the accident if he had approached the mountain ridge at a higher altitude.

The accident site was inaccessible to first responders, which resulted in the pilot's blood being drawn about 5 hours following the accident. Toxicological testing revealed strong evidence that he had used marijuana at some point before the accident. Although he had no significant active drug (tetrahydrocannabinol [THC]) in his blood at the time it was drawn, it could not be determined how much THC was in this blood at the time of the accident. Therefore, it could not be determined if impairment due to marijuana use contributed to the pilot's poor decision-making.

# Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper judgment in conducting a flight in a gyroplane over mountainous terrain near its demonstrated maximum operating altitude and his subsequent failure to maintain adequate clearance with terrain during cruise flight in turbulent weather conditions.

## Findings

Personnel issues	Decision making/judgment - Pilot
Aircraft	Altitude - Not attained/maintained
Aircraft	Climb capability - Attain/maintain not possible
Environmental issues	Mountainous/hilly terrain - Effect on operation
Environmental issues	Terrain induced turbulence - Effect on operation
Personnel issues	Use of medication/drugs - Pilot

# Factual Information

## History of Flight

<b>Enroute-cruise</b>	Turbulence encounter (Defining event)
<b>Enroute-cruise</b>	Loss of lift
<b>Emergency descent</b>	Off-field or emergency landing
<b>Landing-flare/touchdown</b>	Collision with terr/obj (non-CFIT)

On May 20, 2016, about 1100 mountain daylight time, an experimental amateur-built Michael Burton (AutoGyro GmbH) Calidus, N50NE, collided with mountainous terrain near Fruitland, Utah. The gyroplane was registered to the builder and operated by the pilot under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The private pilot and passenger were seriously injured, and the gyroplane sustained substantial damage. The cross-country personal flight departed Duchesne Municipal Airport, Duchesne, Utah, about 1015, with a planned destination of Spanish Fork Airport-Springville-Woodhouse Field, Spanish Fork, Utah. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot reported that they departed from Glenwood Springs Municipal Airport, Glenwood Springs, Colorado, earlier that morning and stopped at Duchesne for fuel. They then departed west towards Spanish Fork on a route over the Wasatch Mountain Range. As they approached the last ridge, about 200 ft above its peak, they encountered strong downdrafts and the gyroplane descended 500 ft and into a box canyon. Unable to out-climb the terrain, the pilot guided the gyroplane over a river at the base of the canyon until he could see a landing spot on the shore. As he approached the site and initiated the landing flare, the right wheel struck a boulder and the gyroplane rolled over, coming to rest in the river.

A witness, who was fishing in the river, called 911 after climbing to a peak where he was able to acquire cell phone reception. Due to the remoteness of the site, the pilot and passenger were not recovered until later in the afternoon.

The gyroplane came to rest within a canyon, at an elevation of about 7,300 ft mean sea level. The canyon walls rose about 1,000 ft above the accident site to the north and south. The projected route of flight would have required clearance over rugged 8,200 ft peaks, about 5 miles north of the 9,420 ft summit of Baldy Mountain.

About the time of the accident, a weather observation station located at Carbon County Regional Airport/Buck Davis Field, 37 miles south-southeast of the accident site and at an elevation of 5,957 ft, reported wind from 170 degrees at 20 knots gusting 25 knots. About the same time, at Provo Municipal Airport, 38 miles west at an elevation of 4,497 ft, wind was reported from 130 degrees at 15 knots, gusting to 22 knots.

The gyroplanes Pilot Operating Handbook specified a maximum demonstrated operating altitude of 10,000 ft. The pilot reported that the gyroplanes maximum gross weight was 1,256 pounds, and the that

the weight at the time of the accident was 1,100 pounds.

The pilot stated that the gyroplane did not experience any mechanical malfunctions or failures, and that the accident could have been avoided if he had approached the mountain ridge at a higher altitude.

The Federal Aviation Administration Bioaeronautical Research Laboratory performed toxicology tests on a sample of blood that was collected from the pilot at 1546 on the day of the accident. Results identified 0.0111 ug/ml of tetrahydrocannabinol carboxylic acid (THC-COOH) in his blood. Tetrahydrocannabinol carboxylic acid (THC-COOH) is the primary metabolite of tetrahydrocannabinol (THC), the main psychoactive compound in marijuana. The report did not document the presence of THC. The reporting cutoff for THC was 0.001 ug/ml.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	57, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Front
<b>Other Aircraft Rating(s):</b>	Gyroplane	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	January 8, 2016
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	January 25, 2016
<b>Flight Time:</b>	285 hours (Total, all aircraft), 235 hours (Total, this make and model), 215 hours (Pilot In Command, all aircraft), 120 hours (Last 90 days, all aircraft), 60 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	MICHAEL BURTON	<b>Registration:</b>	N50NE
<b>Model/Series:</b>	Calidus	<b>Aircraft Category:</b>	Gyroplane
<b>Year of Manufacture:</b>	2014	<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	C00240
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	May 20, 2016 Condition	<b>Certified Max Gross Wt.:</b>	1256 lbs
<b>Time Since Last Inspection:</b>	25 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	350 Hrs at time of accident	<b>Engine Manufacturer:</b>	Rotax
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	914
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	115 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KPUC, 5921 ft msl	<b>Distance from Accident Site:</b>	33 Nautical Miles
<b>Observation Time:</b>	16:53 Local	<b>Direction from Accident Site:</b>	160°
<b>Lowest Cloud Condition:</b>	Few / 7000 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	20 knots / 25 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	170°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.81 inches Hg	<b>Temperature/Dew Point:</b>	18°C / 1°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	DUCHESNE, UT (U69 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	SPANISH FORK, UT (U77 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	10:30 Local	<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Serious	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Serious	<b>Latitude, Longitude:</b>	40.124168,-111.001663(est)

## Administrative Information

**Investigator In Charge (IIC):** Simpson, Elliott

**Additional Participating Persons:** Lyndsay Carlson; Federal Aviation Administration FSDO; Salt Lake City, UT

**Original Publish Date:** May 1, 2017

**Last Revision Date:**

**Investigation Class:** [Class](#)

**Note:** The NTSB did not travel to the scene of this accident.

**Investigation Docket:** <https://data.nts.gov/Docket?ProjectID=93217>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).