



# **Aviation Investigation Final Report**

Location: Reno, Nevada Accident Number: GAA16CA259

Date & Time: May 24, 2016, 13:25 Local Registration: N4793D

Aircraft: Cessna 182 Aircraft Damage: Substantial

**Defining Event:** Loss of engine power (total) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

According to the Federal Aviation Administration, Aviation Safety Inspector that arrived at the scene shortly after the accident, he located the uninjured pilot in command (PIC) and a passenger rated pilot who were the only occupants of the airplane. The inspector reported that the PIC told him that he had fueled the airplane prior to the flight. The PIC told the inspector that he had flown 2.5 hours on the right tank which indicated 3.9 gallons of fuel remained per the electronic fuel quantity indicator, at which time he switched to the left tank which indicated 15 gallons of fuel remained per the electronic fuel quantity indicator. The PIC reported to the inspector thatafter switching tanks the engine ran for an additional five minutes and ceased operation. The PIC told the inspector that he contacted air traffic control (ATC) stating that he had experienced an "engine failure", and that they would not make it to the nearest airport. The pilot landed the airplane on a highway five miles from the destination airport. During the landing the nose gear collapsed and the airplane sustained substantial damage to the firewall.

During a post-accident examination of the airplane by the FAA Inspector, there wasn't any usable fuel found in the left or right fuel tanks, and the paved surface where the airplane landed did not contain any evidence of fuel spillage.

The airplane landed 5 miles from the nearest airport. The pilot's destination airport was 17.5 nautical miles southwest of the accident site. The distance between the departure airport and the destination airport was about 415 nautical miles. According to the pilot operating handbook, the range of the accident airplane is 880 nautical miles.

The NTSB Investigator contacted the fixed base operator who reportedly fueled the airplane prior to the flight in order to acquire the fuel records. The operator did not have any fuel records for the accident airplane.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate fuel planning, resulting in fuel exhaustion and substantial damage to the firewall during the forced landing.

#### **Findings**

Aircraft	Fuel - Fluid level
Personnel issues	Fuel planning - Pilot

Page 2 of 6 GAA16CA259

## **Factual Information**

### **History of Flight**

**Enroute-cruise** Loss of engine power (total) (Defining event)

**Enroute-cruise** Fuel exhaustion

Enroute-cruise Emergency descent initiated

**Landing** Collision with terr/obj (non-CFIT)

Landing-flare/touchdown Hard landing

#### **Pilot Information**

Certificate:	Commercial; Private	Age:	68,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	May 21, 2014
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 4101 hours (Total, all ai	rcraft), 2500 hours (Total, this make a	ind model)

#### **Passenger Information**

Age:	43,Male
Seat Occupied:	Unknown
Restraint Used:	
Second Pilot Present:	Yes
Toxicology Performed:	No
Last FAA Medical Exam:	
Last Flight Review or Equivalent:	
	Seat Occupied: Restraint Used: Second Pilot Present: Toxicology Performed: Last FAA Medical Exam:

Page 3 of 6 GAA16CA259

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N4793D
Model/Series:	182 A	Aircraft Category:	Airplane
Year of Manufacture:	1958	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	34893
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:		Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	IO-540-AB1A5
Registered Owner:	EXTREME SOURCE INC.	Rated Power:	230 Horsepower
Operator:	EXTREME SOURCE INC.	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
KRNO,4400 ft msl	Distance from Accident Site:	17 Nautical Miles
19:55 Local	Direction from Accident Site:	314°
Few / 4500 ft AGL	Visibility	10 miles
Broken / 6000 ft AGL	Visibility (RVR):	
9 knots / None	Turbulence Type Forecast/Actual:	/ None
260°	Turbulence Severity Forecast/Actual:	/ N/A
29.93 inches Hg	Temperature/Dew Point:	15°C / 3°C
No Obscuration; No Precipitation		
PRESTON, ID (U10)	Type of Flight Plan Filed:	Unknown
RENO, NV (RNO )	Type of Clearance:	Unknown
10:15 Local	Type of Airspace:	Class G
	19:55 Local Few / 4500 ft AGL Broken / 6000 ft AGL 9 knots / None  260°  29.93 inches Hg No Obscuration; No Precipital PRESTON, ID (U10) RENO, NV (RNO)	KRNO,4400 ft msl Distance from Accident Site:  19:55 Local Direction from Accident Site:  Few / 4500 ft AGL Visibility  Broken / 6000 ft AGL Visibility (RVR):  9 knots / None Turbulence Type Forecast/Actual:  260° Turbulence Severity Forecast/Actual:  29.93 inches Hg Temperature/Dew Point:  No Obscuration; No Precipitation  PRESTON, ID (U10) Type of Flight Plan Filed:  RENO, NV (RNO) Type of Clearance:

Page 4 of 6 GAA16CA259

## **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	39.29,-119.510002(est)

Page 5 of 6 GAA16CA259

#### **Administrative Information**

Investigator In Charge (IIC):	Hicks. Michael
investigator in onlinge (iio).	i iloko, Milotidoi
Additional Participating Persons:	Gerald W Rose; Federal Aviation Administration; Reno, NV James D Richardson; Federal Aviation Administration; Reno, NV
Original Publish Date:	September 12, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93244

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 GAA16CA259