



Aviation Investigation Final Report

Location:	Waianae, Hawaii	Accident Number:	WPR16LA119
Date & Time:	May 23, 2016, 11:37 Local	Registration:	N6697Y
Aircraft:	Beech C23	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (partial)	Injuries:	2 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The private pilot reported that, during the climb-to-cruise portion of the cross-country interisland flight over open ocean water, the engine began to run roughly. The pilot applied carburetor heat, which resolved the engine roughness. The pilot decided to continue his flight. As the flight approached his destination, the engine began running roughly again, accompanied by a significant loss of engine rpm. The pilot applied carburetor heat and adjusted the mixture, but the engine power was not restored. He then ditched the airplane into the water just offshore of the island.

The airplane wreckage was recovered from the water 3 days after the accident, and it had sustained significant damage from tidal forces. Postaccident examination of the airframe and engine revealed no evidence of mechanical malfunctions or failures that would have precluded normal operation.

Weather conditions in the area at the time of the accident were conducive to the formation of carburetor icing at glide and cruise power and serious carburetor icing at glide power. If the pilot had either kept the carburetor heat on or applied it earlier, the loss of engine power and subsequent ditching could have been avoided.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The total loss of engine power during cruise flight due to carburetor icing. Contributing to the accident was the pilot's delay in applying carburetor heat during flight while operating in an area conducive to carburetor icing.

Findings

Environmental issues	Conducive to carburetor icing - Effect on equipment
Personnel issues	Use of equip/system - Pilot
Personnel issues	Delayed action - Pilot

Factual Information

History of Flight

Enroute-cruise	Loss of engine power (partial) (Defining event)
Enroute-cruise	Fuel related
Enroute-cruise	Off-field or emergency landing
Enroute-cruise	Ditching

On May 23, 2016, about 1137 Hawaiian standard time, A Beech C23, N6697Y, sustained substantial damage following a loss of engine power and subsequent ditching within the open waters of the Pacific Ocean near Waianae, Hawaii. The airplane was registered to and operated by the pilot under the provisions of Title 14 Code of Federal Regulations Part 91. The private pilot and his passenger sustained minor injuries. Visual meteorological conditions prevailed and no flight plan was filed for the personal flight. The cross-country flight originated from the Lihue Airport, Lihue, Hawaii, about 20 minutes prior to the accident, with an intended destination of Kalaeloa Airport, Kapolei, Hawaii.

The pilot reported that during the climb to cruise portion of the flight, the engine began to run rough. The pilot applied carburetor heat, which resolved the roughness, and he continued his climb to 5,500 feet mean sea level. As the flight was approaching the shores of Oahu Island, the engine began running rough in addition to a reduction of engine rpm to about 1,700. The pilot applied carburetor heat and adjusted the mixture, however, was unsuccessful at restoring engine power. The pilot initiated a forced landing into the ocean waters just off shore of the island of Oahu.

The airplane came to rest nose low partially submerged within about 20 feet of water, about 50 to 75 feet from the shoreline. Initial examination of the wreckage revealed that the forward portion of the fuselage was damaged. The wreckage was recovered from the water three days after the accident. Following removal from the water, the engine was rinsed with fresh water and subsequently filled with diesel fuel in an attempt to preserve the engine.

Examination of the recovered airplane on June 30, 2016, revealed that it was mostly fragmented into multiple pieces from the ocean tidal action. The engine remained attached to the firewall structure. Corrosion was observed throughout the engine and firewall. The carburetor was separated from its mounts. The magnetos and fuel pump remained secured to their mounting pads. The bottom spark plugs were removed and exhibited corrosion and debris consistent with ocean water and salt. The magnetos were removed. Partial rotational continuity was obtained when the propeller was rotated about ¼ of a turn and mechanical continuity was obtained at the rear of the engine. The right magneto drive shaft rotated however did not produce spark at the lead terminals. Disassembly of the magneto was not performed due to the corrosion on the cap bolts. The left magneto drive shaft would not rotate by hand. Disassembly of the magneto was not performed due to the corrosion on the cap bolts.

The carburetor was removed and disassembled for inspection. The internal float was intact and the needle valve was intact. A significant amount of salt and other ocean vegetation debris was observed throughout the float bowl and screen.

The right side exhaust remained partially attached to cylinders one and three. No nuts were observed on the cylinder number one exhaust mount and only one nut remained attached to the cylinder number three cylinder exhaust mount. It could not be determined if the missing nuts were displaced prior to the accident or during salvage and subsequent engine preservation methods. No evidence of any preexisting anomalies that would have precluded normal operation and production of power was observed.

The Federal Aviation Administration (FAA) published Special Airworthiness Information Bulletin (SAIB) CE-09-35 on June 30, 2009, regarding carburetor ice prevention. The conditions encountered in this accident (ambient temperature 84 degrees F, dew point 63 degrees F) were in the area of icing at glide and cruise power, and in the area of serious icing at glide power.

Pilot Information

Certificate:	Private	Age:	56, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	July 24, 2015
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 15, 2016
Flight Time:	224 hours (Total, all aircraft), 92 hours (Total, this make and model), 161 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N6697Y
Model/Series:	C23 NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	1979	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	M-2224
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:	April 24, 2016 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	648.7 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O&VO-360 SER
Registered Owner:	On file	Rated Power:	0 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PHJR,33 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	20:53 Local	Direction from Accident Site:	137°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 4500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	29°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lihue, HI	Type of Flight Plan Filed:	None
Destination:	Kapolei, HI (JRF)	Type of Clearance:	None
Departure Time:	11:17 Local	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	21.463611,-158.21527(est)

Administrative Information

Investigator In Charge (IIC):	Cawthra, Joshua
Additional Participating Persons:	Joesph J Monfort; Federal Aviation Administration; Honolulu, HI
Original Publish Date:	May 25, 2017
Last Revision Date:	
Investigation Class:	Class
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93269

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).