



# Aviation Investigation Final Report

<b>Location:</b>	Laureles, Texas	<b>Accident Number:</b>	CEN16LA213
<b>Date &amp; Time:</b>	June 9, 2016, 16:30 Local	<b>Registration:</b>	N6203N
<b>Aircraft:</b>	Bell 47G 5	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Miscellaneous/other	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

## Analysis

The commercial pilot reported that, while conducting a spray pass, he pulled on the helicopter's collective, and the rotor speed dropped. He lowered the collective, applied maximum throttle, and pulled on the collective again, but the rotor speed continued to drop. He then attempted to land in a nearby yard, but the tailboom struck a tree, and the helicopter then flipped on its right side.

A witness, who was an experienced agricultural helicopter pilot, reported that he had flown with the accident pilot for about 12 hours in the accident helicopter, which was a piston engine-powered helicopter that did not have a throttle governor, to familiarize him with managing the throttle. He stated that the accident pilot's previous experience was in turbine-powered helicopters that had a throttle governor. The witness stated that he was in the field watching the accident pilot perform spraying operations. The pilot made a downwind pass in the field in a tight area. He said that, when the pilot pulled up to climb above the trees at the end of the pass, he heard the engine "bog down" and that he thought that the pilot had pulled the collective without adding throttle.

A postaccident examination of the helicopter and a test run of the engine revealed no preaccident mechanical malfunctions or failures that would have prevented normal operation. Based on this evidence, it is likely that the pilot failed to apply engine power when he applied collective input, which resulted in a loss of rotor speed and an exceedance of the helicopter's performance capability.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to apply additional engine power when he applied collective input, which led to a loss of rotor speed and the exceedance of the helicopter's performance capability.

## Findings

<b>Aircraft</b>	Prop/rotor parameters - Not attained/maintained
<b>Aircraft</b>	Powerplant parameters - Not attained/maintained
<b>Personnel issues</b>	Lack of action - Pilot
<b>Personnel issues</b>	Use of equip/system - Pilot
<b>Environmental issues</b>	Tree(s) - Contributed to outcome

## Factual Information

### History of Flight

#### Maneuvering-low-alt flying

Miscellaneous/other (Defining event)

On June 9, 2016, about 1630 central daylight time, a Bell 47G-5 helicopter, N6203N, was substantially damaged during a loss of control while performing agricultural spraying operations near Laurels, Texas. The pilot received minor injuries. The helicopter impacted a tree and the ground and sustained damage to the fuselage, landing gear, and main rotor system. The aircraft was registered to and operated by Hendrickson Flying Service, Inc. under the provisions of 14 Code of Federal Regulations Part 137 as an aerial application flight. Visual meteorological conditions prevailed for the flight, which was not on a flight plan. The local flight originated at an unconfirmed time.

The pilot reported that while conducting a spray pass, he pulled on the collective and the rotor speed dropped. He said that he lowered the collective, applied maximum throttle and pulled on the collective again but the rotor speed continued to drop. He then attempted a landing in a yard next to a house where the tail boom struck a tree and the helicopter came to rest on its right side.

A witness, who was an experienced agricultural helicopter pilot reported that he had flown with the accident pilot for about 12 hours in the accident helicopter. He stated that the accident pilot's previous experience was in turbine powered helicopters with governed throttle. He flew with him to familiarize him with managing throttle on the piston engine powered Bell 47 that did not have a throttle governor. The witness stated that he was in the field watching the accident pilot perform spraying operations. The pilot made a downwind pass in the field in a tight area where the helicopter was in and out of the field quickly. He said that when the pilot pulled up for the trees at the end of the pass he heard the engine "bog down." He said that he thought that the pilot had pulled collective without adding throttle.

A postaccident examination of the helicopter and a satisfactory test run of the engine disclosed no preaccident mechanical malfunctions or anomalies that would have prevented normal operations.

## Pilot Information

<b>Certificate:</b>	Commercial; Private	<b>Age:</b>	57, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	March 15, 2016
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Bell	<b>Registration:</b>	N6203N
<b>Model/Series:</b>	47G 5 5	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>	1969	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal; Restricted (Special)	<b>Serial Number:</b>	7875
<b>Landing Gear Type:</b>	N/A; Skid	<b>Seats:</b>	3
<b>Date/Type of Last Inspection:</b>	April 26, 2016 100 hour	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	9665 Hrs as of last inspection	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	VO-435 B1A
<b>Registered Owner:</b>	HENDRICKSON FLYING SERVICE INC	<b>Rated Power:</b>	260 Horsepower
<b>Operator:</b>	HENDRICKSON FLYING SERVICE INC	<b>Operating Certificate(s) Held:</b>	Agricultural aircraft (137)
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	HNKG

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	HRL,36 ft msl	<b>Distance from Accident Site:</b>	11 Nautical Miles
<b>Observation Time:</b>	21:52 Local	<b>Direction from Accident Site:</b>	310°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	9 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	60°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.84 inches Hg	<b>Temperature/Dew Point:</b>	33°C / 24°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Laureles, TX	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Laureles, TX	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	26.109167,-97.494163(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Brannen, John
<b>Additional Participating Persons:</b>	Brian Fricker; FAA - San Antonio FSDO; San Antonio, TX
<b>Original Publish Date:</b>	December 12, 2016
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=93354">https://data.nts.gov/Docket?ProjectID=93354</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).